

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



Superintendent Superintendent Suruvananthapuram

SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.: 182602

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi • 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.ki@cyrix.in Call Registration Date:93 03 04 Date of Visit: Asset No.: Thursday Hapman, Reals EQPT Name: Delea Courselles Ph: 9496196776 Manufacture! T..... Service Classification: Breakdown Call PMS 🗌 Calibration ___ Cust.Training Percuercing OR omeat Spare Required Completed Spare Replaced Requested PR Number **Part Number** Description Qty. 1. Nh NOO NO Non 2. 3. **End Time Start Time** Date Cyrix Engineer 04130 pm 051300 Pending Completed **Customer Remark** lanthapurant **Customer Name:** Service Engineer Name: Ploham Signature: Signature: Date: 496196776 Contact Number: QDate: Designation: Contact Number: Hospital Se

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

	PROFORMA							
SI. No 1	Particulars Name of District	Details THIRUVANANTHAPURAM						
2	Name of Hospital	GENERAL HOSPITAL Equipment: PULSE OXIMETER Make: L & T Model: COMET SN: C12P3003						
3	Name of Equipment with Make, Model and Serial Number							
4	Equipment ID & Barcode	102964 & 0110059						
5	Date of purchase / Year of manufacture /Installation Date	27.02.2018; you contains 2 3 noveld						
6	Warranty details (Yes/No)	No warranty						
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CMC						
8.	Date of breakdown(Date of registration of complaint through email/ Toll free)	23-03-2024 (Toll free)						
9	Action taken	Checked the machine and found the SMPS board, display and main board defective.						
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged						
11	Recommendations for repair (required service details)	Not recommending for repair.						
12	Cost of spares (specify parts and cost)	NA .						

13	Asset Value	Rs.45013			
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA			
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)				
16		Checked the machine and found the SMPS board, display and main board is defective. Equipment installed on 27.02.2018 and has covered up to 6 years. On enquiring for replacement of spare parts, it was identified and communicated by the manufacturer that the particular series is now obsolete and no service support is provided. Considering the circumstances and in adherence to the tender clause 5.3.14.2, which states that in case an equipment is declared as end of support by manufacturer, the equipment should be evaluated for condemnation and hence recommending the equipment for condemnation.			
17	Name & Signature of CYRIX Authority	MOHAMMAD SIYAD M			

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Machine obsolete. So RBER.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram

10.5. 2024

Signature of JC BM (NHM)

Date

Date

CENERAL HOSS

Superintendent

Signature of rhiruvananthapuran

Superintendent / Medical Officer (i/c)



Dear Customer,

Date: 24.01.2023

Subject: End of service support for Comet model

It is to inform you that the above said product is out of production and it is obsoleted. There is no service support available for it, hence it is fit for condemnation.


Thanking you,


For Skanray Technologies Limited

Avinash H M

Division

Service Operations Co-ordinator






REE NO:1800-425-7669

IAR CODE - 0110059

PROGRAMME (BENP)



atc	PULSE OXYMETER Jable top) Ŕ	エ	В	Rema
	escription.				
30.6.16	Brought from VOL II				
<u>a</u>	age No: 113 (Comet)			1	Ge
				2	Bu
27/2/18	pulse oxy meter (LXT/Comet)			1/	
327224	The Designation of the wester they are				
	Distro D. (Brill Minco (1884)	4		:	
'					-
18/2121. 7	Egudo pro: 82. Comen-1.				7
	eguda pro: 82. (one 0-1:		1	l	1
12/1/24 5	representation of Conso-1.		17.0		- 13
^	Sinch pau: 87. Com - 1		1	wil.	
	(2005 = 7)	A	•	707(.	
	· (*				
1			1		
1			-		
17 T		- 1			-
		and de-			
			-	-	-
					-
Call A			-		4
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1			7 7		
1,000					
			2		
2.3(5)(2)		-	4 X		
				#	21 44
					alt los la alto
	Chicago			, value ar	