



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 190676

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Patta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrilx.com | E-mail : bamp.kl@cyrilx.in

<p>Health Facility : <u>THQH</u></p> <p>Address : <u>Varkala</u> <u>Thiruvananthapuram</u></p> <p>Ph : <u>9895223585</u></p>	<p>Call Registration Date : <u>26.3.2024</u></p> <p>Caller ID : <u>103471</u></p> <p>Date of Visit : <u>27.3.2024</u></p> <p>Asset No. : <u>0121383</u></p> <p>EQPT Name : <u>Wegley Machine</u></p> <p>Manufacture : <u>Pragathi</u> Model : <u>NA</u></p> <p>S. No. : <u>NA</u> Dept. : <u>Labour Room</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not working

Action Taken : Checked and found that Main PCB was replaced.
Main PCB returns back after service and found that PCB not working
Need to replace Main PCB (control Board) for further
checking of the equipment.

Completed Date : 27.3.24 Time : 12:00pm Spare Required

Spare Replaced Requested

1.	Description	Qty.	Part Number	PR Number
2.				
3.				

Cyrilx Engineer	Date	Start Time	End Time
<u>Keethu Pankaj. VS</u>	<u>27.3.2024</u>	<u>11:15pm</u>	<u>12:00pm</u>



Customer Remark : Completed Pending

SUPERINTENDENT
HEADQUARTERS HOSPITAL
KERALA

<p>Service Engineer Name : <u>Keethu Pankaj. VS</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>27.3.2024</u></p> <p>Contact Number : <u>9072522096</u></p>	<p>Customer Name : <u>Amalalalalalalalalalal</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : _____</p> <p>Contact Number : <u>9895223585</u></p> <p>Designation : <u>SNM/Officer</u></p> <p>Hospital Seal : _____</p>
--	---




**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

490

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	THQH VARKALA
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : Weighing Machine Make : Pragathi Medical Systems Model: 2034 SI : NA
4	Equipment ID/ Barcode	103471 / 0121386
5	Date of purchase/ Year of manufacture/Installation Date	05/01/2016
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	26/03/2024
9	Action taken	Checked and found that the Mother board, Power supply transformer, Display board, sensor load cell complaint. Need to replace these spares for further checking.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not recommending for Repair.
12	Cost of spares (specify parts and cost)	Mother Board – 1350/- Power supply Transformer – 250/- Display Board – 200 Sensor Load cell – 1750/- Other accessories – 250/- One time service charge – 1000/- Total – 5900/-

13	Asset Value	Rs . 7700/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	76.62%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report with OEM quotation attached.
16	Reasons for recommending the equipment as BER	Checked and found mother board, power supply transformer, display Board and Load cell defective. The equipment was installed on 05/01/2016 and covered up to 8+ years. The repairing cost will be 76.62%. As per the tender clause 5.3.14.1 both criteria met. So recommending the unit for condemnation.
17	Name & Signature of CYRIX Authority	KASYEP PV 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* **Attach Photograph**


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


Mother board, Display board, load cell etc defective.
So the ~~sete~~ machine can be RBER.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram


27.5.2024
Signature of JC BM (NHM)

Date: 3.6.24




3/6/24

Signature of
Superintendent/Medical Officer (i/c)
SUPERINTENDENT
TALUK HEADQUARTERS HOSPITAL
VARKALA

(Baby)




DATE | BABY-WEIGHING MACHINE

2/1/12	Received from store	1	1
5/1/2016	Received from store Cost - 7700/- (Page No: 248, instrument Register KMSL, Supply. D AI - model: Prayathi Equipped with - 145-200. Rs. 7700/-	1	2
25/1/2023	Transfer out to injection of on 25/1/2023 instrument Register Volume 9 (Page No. 10)	1	1 Dr allure
11/02/23	1 nos transfer out to I.C.U.E Register Vol-2 Page No: <u>15</u>	1	1 Dr allure



WWD
3/6/24

SUPERINTENDENT
TALUK HEADQUARTERS HOSPITAL
VARKALA



Sun
3/6/24

**SUPERINTENDENT
TALUK HEADQUARTERS HOSPITAL
VARKALA**