



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 218527

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Patta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrilx.com | E-mail : bemp.kl@cyrilx.in

<p>Health Facility <u>General Hospital</u></p> <p>Address <u>Thiruvananthapuram</u> <u>Kerala</u></p> <p>Ph : <u>9847886501</u></p>	<p>Call Registration Date : <u>22/4/2024</u></p> <p>Caller ID : <u>107435</u></p> <p>Date of Visit : <u>22/4/24</u></p> <p>Asset No. : <u>0110192</u></p> <p>EQPT Name : <u>UPS</u></p> <p>Manufacture <u>Energialite</u> Model : <u>RESAIK3SB</u></p> <p>S. No. <u>NA</u> Dept. <u>Radiology</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust. Training

Problem Identified : Not working

Action Taken : Checked the machine and found driver PCB, Control PCB and Batteries damaged. Need to replace those spars for further checking and working condition of the machine


Completed Date : 22/4/24 Time : 11:15 AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
2.				
3.				

Cyrilx Engineer	Date	Start Time	End Time
<u>Govya Sudheep</u>	<u>23/4/24</u>	<u>10:30 AM</u>	<u>11:15 AM</u>

Customer Remark Pending



<p>Service Engineer Name : <u>Govya Sudheep</u></p> <p>Signature : <u>Govya</u></p> <p>Date : <u>23/4/24</u></p> <p>Contact Number : <u>907406244</u></p>	<p>Customer Name : <u>Dr Deepale</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>[Date]</u></p> <p>Contact Number : <u>[Number]</u></p> <p>Designation : <u>Radiologist</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
---	---




Superintendent
General Hospital
Thiruvananthapuram

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	GH THIRUVANANTHAPURAM
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : UPS Make : Energio lite Model : RESQ1K3SB Serial No : NA
4	Equipment ID/ Barcode	107435/0110192
5	Date of purchase/ Year of manufacture/Installation Date	05/10/2018
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No CAMC/AMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	22/04/2024
9	Action taken	Checked the machine and found Driver PCB, Control PCB and Batteries damaged. Need to replace those spares for further checking and working condition of the machine
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDING FOR REPAIR
12	Cost of spares (specify parts and cost)	Driver PCB - Rs. 4956/- Control PCB - Rs. 2655/- Battery 12v 7Ah (3nos) - Rs. 2765/- Total - Rs. 10367/-

13	Asset Value	Rs. 4500/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	230%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT ATTACHED
16	Reasons for recommending the equipments as BER	Checked the machine and found Driver PCB, Control PCB and Batteries damaged. This unit is installed on 05/10/2018 and covered up to 5+ years. The repairing cost is 230%. As per the tender clause 5.3.14.1, Both criteria met. Hence recommending for condemnation.
17	Name & Signature of CYRIX Authority	SOORYA SUDHEEP 

Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Batteries, PCB (Driver and Control) damaged. Repair cost is high. So this can be BER as per tender guidelines.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram



10-06-2024

Signature of JC BM (NHM)

Date:



Signature of
Superintendent/Medical Officer (i/c)


Superintendent
General Hospital
Thiruvananthapuram

21 | 02 | 2021.

GH Stock Book. S 1R | 8B | 399.

~~Dr. Suresh~~

~~Dr. Suresh~~

Mingony DC 60 W/OBA SYSTEM
with labour 30/40 50000 Rs 755920

① CONVEY PROBLE :- Rs 171200.

② HINER BRAY PRASE 1712000. ③ TVS PRASE :- BY UPS.

~~Dr. Suresh~~
Installed on 05-10-2018

Dr. Suresh
1R 8B Page No 22 in store book.



AION BACKUPS

YP/VIII/320 AYLARA, KERALA KOLLAM

Date: 31/05/2024

Contact: 8921950217

Email: aionbackups12@gmail.com

GSTIN: 32CGUPM9450L1ZN

1KVA ENERGIO LITE ONLINE UPS SERVICE PROPOSAL

TO,

CYRIX HEALTHCARE PVT. LTD, GH TRIVANDRUM

Barcode:0110192

Dear Sir/Madam,

We are pleased to submit here with our quote for the same as per below.

SL	DESCRIPTION	QTY	UNIT RATE IN INR	TOTAL	GST	TOTAL PRICE IN INR
1	ENERGIO LITE 1KVA DRIVER PCB	1	4200.00	4200.00	18	4956.00
2	CONTROL PCB	1	2250.00	2250.00	18	2655.00
3	EXIDE 12V/7AH SMF BATTERY	3	720.00	2160.00	28	2765.00
PAYABLE AMOUNT						10367.00

Commercial terms and conditions

1. Payment 80% advance along with PO balance before dispatch, 20% After installation.
2. Delivery period; 2weeks.
3. Tax :GST@18% for spares,28%@Battery
4. Installation; Our scope.

Please arrange to release the PO at our above address

Bank name :HDFC

Account no:50200082743176

IFSC Code:HDFC0004083

We hope you will find the above offer in line with our discussions and await your valuable order please free to call or mail us on above given number if any query.

Thank you, Sincerely,
BHAGATH MATHAN

