BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM UNDER NATIONAL HEAL H MISSION SERVICE PROVIDER No. : Tender No. WO-37/2021-2022/698 196467 ARE ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency Service Report 30/64 1 B, Petta Junction, Poonlthura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Call Registration Date : 16-04-2024 Health Facility PHC PAIPRA Address Ernakulan Date of Visit : 17-04-2024 Asset No. : 0740139 Ernatulars (Dt) EQPT Name : BP Apparatus Ph : Manufacture Dr. Morepen Model : BP-09 NA Dept. OP S. No. Service Classification : Breakdown Call PMS Calibration Cust.Training Problem Identified : BP Apparatus not working Action Taken : Checked the machine and found that main board motor ana faulte Date : 17-04-24 Time : 3:30PM Completed Spare Required Spare Replaced Requested Description Qty. Part Number **PR Number** MOLOY 1. INO . Main Boond 2. INO. 3. **Cyrix Engineer** Date Start Time **End Time** Jibin Thomas George 17-4-24 3:30 PM 2:00 PM **Customer Remark** Completed Pending ANTH CENT Custorier Name: Seema Balalonshin Service Engineer Name : , Signature : Signature : 496744481 Date : Contact Number **Designation**: NO 9rE **Contact Number : Hospital Seal :**

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

SI. Details Particulars No Ernakulam Name of District 1 PHC PAIPRA Name of Hospital 2 Equipment: BP APPARATUS Make : Dr Morepen Name of Equipment with Make, Model Model: BP 09 3 and Serial Number Sr.no : NA 106604 & 0740139 Equipment ID & Barcode 4 23-03-2018 Date of purchase / Year of manufacture 5 /Installation Date No warranty Warranty details (Yes/No) 6 *AMC/ CAMC Period agreed at the time No AMC/CAMC 7 of purchase Date of breakdown(Date of registration of 16-04-24 (Foll Free) complaint through email/ Toll free) 8 Checked the machine and found that motor and main board are faulty. Action taken 9 Present status of the equipment (Fully Fully damaged 10 damaged / partially damaged) Recommendations for repair Not recommending for repair. 11 (required service details) Cost of spares (specify parts and cost) NA 12

PROFORMA

13	Asset Value	Rs.2200
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
16	Reasons for recommending the equipment as BER	Checked and found motor and main board are defective. Equipment installed on 01-02-18 and the machine outlived 6+years. Quotation not submitted since the spares are not available in the market. So recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	JIBIN THOMAS GEORGE

Not mandatory

#Based on the period of life and value as per the BER quidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM: EN Nation Head Signature of JC BM (NHM) 1) 11

ignature of seals anuly Health Centre THCENT Superintendent / Medical Officer

A SHE BP monitor Digital 27 Reversed per the star 23 3 2018 RN B Received from spor 23/3/2018 2N. 2002 3 /2022 . IN. 3N

2



