

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

No.: 193151

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Call Registration Date: 13.03. w24 Health Facility Janly Health Con Caller ID : 100988. Date of Visit: 13.03.1024 Asset No.: 0142259 EQPT Name: Mich pipelte Ph : 98 48 #95030 Manufacture _______ Model : S. No. 4618 AAL014684Dept. **Cust.Training** Service Classification : Breakdown Call \square PMS Calibration Problem Identified : Volume Variabin **Spare Required** . 13.03 1024 Completed Requested Spare Replaced Qty. **Part Number PR Number** Description 1. NA NI NA 2. 3. **End Time Start Time Date** Cyrix Engineer 13.03. 2024 1.0000 2.00pm tookennes Pending Completed **Customer Remark Customer Name:** Service Engineer Name : Mohenneel Signature: Signature: Date: **Contact Number:** Date: **Designation:**

Hospital Seal:

7994042445

Contact Number:

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

| 2 이 년 | Particulars | Details | |
|----------|---|--|--|
| 1 | Name of District | THIRUVANANTHAPURAM | |
| 2 | Name of Hospital | PHC VEMBAYAM | |
| 3 | Name of Equipment with Make, Model and Serial Number | Equipment : Micro Pipette Make : Dragon Model : Na SL: YE18AAL0146844 | |
| 4 | Equipment ID/ Barcode | 100988 / 0142259 | |
| 5 | Date of purchase/ Year of manufacture/Installation Date | 01/01/2016 | |
| 6 | Warranty details (Yes/No) | No Warranty | |
| 7 | *AMC/ CAMC Period agreed at the time of purchase | No AMC/CMC | |
| 8 | Date of breakdown (Date of registrationof complaint through email/ Toll free) | 13/03/2024 | |
| 9 | Action taken | Checked and found that the number barrel is over rotating and damaged the rotating key, rotating number ring and rotating gears. | |
| 10 | Present status of the equipment (Fully damaged / partially damaged) | Fully Damaged | |
| 11 | Recommendations for repair (required service details) | Not recommending for condemination. | |
| 12 | Cost of spares (specify parts and cost) | Na | |

| 42 | Accet Value | Rs.1850 |
|----------|---|--|
| 13 14 | #Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value | Na |
| 15 | Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX | Cyrix service report and calibration reporattached. |
| 16 | (Attached or Not) Reasons for recommending the equipment as BER | Checked and identified the unit is showing volume variations. Despite adjusting the spring tension, the issue continued due to the damage in the rotating key, number ring and the gears. The pipette was installed on 1/1/2016 and outlived up to 8+ years. The spares are not available in the market. As per the tender clause 5.3.14.2 recommending the equipment for condemination. |
| 17 | Name & Signature of CYRIX Authority | Kasyep PV |

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Pipette was brought to shock on 1-1-2016.

The shows valume variation. and can't be reparable and calibrated. So can be RBCR. Remarks and Recommendations of Junior Consultant (Biomedical) NHM: MANEESHA MOHAN M.R. Junior Consultant (Biomedical) National Health Mission Thiruvananthapuram Signature of JC BM (NHM)

Signature of Superintendent/Medical Officerely, and Longhia P.O. Superintendent/Medical Officerely, and the superintendent of the Date:

| le . | EINN PIPETTE 100 | Receipt | Balance |
|--------------------------|--|---------|-------------------|
| 116 | Received from the Store | 1 | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | 10 10 |
| | | | |
| | | | |
| | | | |
| | | | 7. |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | A STATE OF THE STA | | |
| | | | |
| | | | - |
| | | | |
| | | | |
| | | | |
| Programme and the second | | | |
| | | | |
| | | - | |
| | CENT | | |
| | S.P.H. CENT | | edical Officering |
| | O Konchira P.O. | | |



An ISO/IEC- 17025:2017 / ACCREDITED BY NABL/ AERB CERTIFIED QA AGENCY/TUV-SUD ISO 9001:2015 Intertek ISO 13485:2016



CERTIFICATE OF CALIBRATION

| CUSTOMER NAME | FAMILY HEALTH CENTRE VEMBAYAM | | | |
|-----------------|--|---------------------|------------|--|
| ADDRESS | VEMBAYAM, THIRUVANANTHAPURAM, KERALA 695615 | DATE OF CALIBRATION | 15-02-2024 | |
| | | VALID UP TO | NA | |
| CERTIFICATE NO: | NA - | DATE OF ISSUE | 17-02-2024 | |

| | · · · · · · · · · · · · · · · · · · · | STRUMENT DETAILS | al and the second |
|-----------------|---------------------------------------|-------------------|-------------------|
| Instrument Name | MICRO PIPETTE | S No. | YE18AAL0146844 |
| Make/Model No. | DRAGON LAB | Visual Inspection | OK |
| LOCATION: | LAB | RANGE | 100 - 1000 μL |

PROBLEM IDENTIFIED: VOLUME VARIATION

ACTION TAKEN:

The pipette is gone recalibration and it is found that the volume is not achieving properly. Even after adjusting the spring tension the volume not achieving correctly. It was found that the numbered barrel is over rotating. Because of this rotating key, rotating number ring, rotating gears are damaged. This part is not available in the market. So the above mentioned pipette is non-serviceable. Therefore, we recommend to decommission this Pipette.

| Γ | CALIBRATION STATUS | PASS | FAIL | J |
|---|--------------------|------|------|---|
| 1 | | | | |

REMARKS:-

- This result of calibration refers to only to the particular items submitted for calibration.
- The above result is valid at the time of and under the stated conditions measurement.
- Calibration certificate issued for weight & measure parameters like mass, weighting balance, volumetric equipment, measuring scales/tapes etc. Are scientific purpose only and should not used for commercial.

Calibrated By (CALIBRATION ENGINEER)

9


Approved By (TECHNICAL MANAGER) PREJITH T B

Cyrix Healthcare Pvt Ltd, 30/641B, Petta Junction, Poonithura, Ernakulam-682038

prajith@cyrix.in

www.cyrixhealthcare.com

Medical Officer-in-charge Covt. P.H. Centre, Verabayain Vertuad Konchira P.O.



TOLL FREE NO:1800 - 425-7669 BAR CODE - (8004-890615225)

0142259

O Koncha P.O.

Date:

MENGRAVAM VETILINA

Office in the least of the leas

