



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 218860

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>PHC, Bhozanikkav</u></p> <p>Address : <u>Alappuzha</u> <u>Kerala</u></p> <p>Ph : <u>9947087871</u></p>	<p>Call Registration Date : <u>25/05/2024</u></p> <p>Caller ID : <u>113258</u></p> <p>Date of Visit : <u>25/05/2024</u></p> <p>Asset No. : <u>0441055</u></p> <p>EQPT Name : <u>BP apparatus</u></p> <p>Manufacture : <u>EIKO</u> Model : <u>EL-520</u></p> <p>S. No. <u>19030900269</u> Dept. <u>OP</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust. Training

Problem Identified : Not working

Action Taken : checked the Machine and Found that main board and battery holder are defective. Battery holder socket was rusted. Need to replace these spares for further checking and existing condition of the equipment

Completed Date : 25/05/24 Time : 4:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Mridula-G</u>	<u>25/05/24</u>	<u>3:00pm</u>	<u>4:00pm</u>

Customer Remark Completed Pending

Service Engineer Name : Mridula-G
Signature : [Signature]
Date : 25/05/2024
Contact Number : 906199471

Customer Name : _____
Signature : _____
Date : _____
Contact Number : _____
Designation : _____
Hospital Seal : _____





BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 218897

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>PHC, Bharanikkavu</u></p> <p>Address <u>Alappuzha</u> <u>Kerala</u></p> <p>Ph : <u>9947087871</u></p>	<p>Call Registration Date : <u>25/05/2024</u></p> <p>Caller ID : <u>113258</u></p> <p>Date of Visit : <u>25/05/2024</u></p> <p>Asset No. : <u>0441055</u></p> <p>EQPT Name : <u>BP apparatus</u></p> <p>Manufacture <u>ELKO</u> Model : <u>EL-520</u></p> <p>S. No. <u>PA30900057</u> Dept. <u>OP</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : not working

Action Taken : checked the machine and found that mainboard and battery holder are defective. Battery holder socket is in rusted condition. Need to replace these spares for further checking and working condition of the equipment.

Completed Date 24/06/24 Time : 1:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>N. Tridula G</u>	<u>24/06/24</u>	<u>12:30pm</u>	<u>1:00pm</u>

Customer Remark Completed Pending

Service Engineer Name : N. Tridula G
Signature : [Signature]
Date : 24/06/2024
Contact Number : 9061199471

Customer Name :
Signature :
Date :
Contact Number :
Designation :
Hospital Seal :




**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	PHC BHARANIKKAVU
3	Name of Equipment with Make, Model and Serial Number	BP APPARATUS MERCURY FREE MAKE :- ELKO MODEL :- EL 520 SN :- 19030900269
4	Equipment ID & Barcode	113258 & 0441055
5	Date of purchase / Year of manufacture /Installation Date	05/11/2019
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	25/05/2024
9	Action taken	Check the machine and found that main board and battery holder are defective. Battery holder socket was rusted.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not Recommended For Repair
12	Cost of spares (specify parts and cost)	NA


13	Asset Value	RS:- 2200/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service Report Attached
16	Reasons for recommending the equipment as BER	Check the machine and found that main board and battery holder are defective. Battery holder socket was rusted condition. Equipment was installed on 05/11/2019 and aged up to 4.5 years. Quotation is not submitted since spares are not available in the market. So we are recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	MRIDULA G 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for BER


 29/06/2024
 Signature of Jyothish Thirupathi
 Consultant (Biomedical Engineering)
 NHM - BM (NHM)

Date _____




 Signature of Superintendent / Medical Officer (i/c)
 27/7/24

BP Apparatus (mercury free)
(LED)

Date.	Name of Item	Qunt.	In.	Balance.	Pp.
5/11/19	BP Apparatus mercury free LED type				
	Bal. Rs. 19409.62p				
	Invoice no: 7964 Copying 1/28.	2		2	Pp
	Bal from Androm Man Stock Book				
	Page No. 41				


Subash



Ms
24/6/24

മെഡിക്കൽ ഓഫീസർ ഇൻചാർജ്ജ്
കുടുംബാരോഗ്യ കേന്ദ്രം
മേനിക്കാവ്

CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)
 TOLL FREE NO: 1800 - 425-7000
 BAR CODE - (8004-800615225)
 0441055



24/6/24
 മെഡിക്കൽ ഓഫീസർ ഇൻചാർജ്
 കൂടുംബാരാഗ് കേന്ദ്രം
 മേരിക്കാവ്