REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details	
1	Name of District	THRISSUR	
2	Name of Hospital	THQH CHAVAKAD	
3	Name of Equipment with Make, Model and Serial Number	Nebuliser MAKE: Easy Breath MODEL: JLN-2308AS SN: JLN2308AS	
4	Equipment ID/ Barcode	0820845 # 69539	
5	Date of purchase/ Year of manufacture/Installation Date	12-11-2013 (stock book attached for reference)	
6	Warranty details	No Warranty	
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC	
8	Date of breakdown/ Date of registration of complaint	15-09-2023	
9	Action taken	Checked the machine and found the Machine is not switching on, Found motor and piston are defective. need to replace the piston and motor for further checking.	
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged	
11	Details of service required (Recommendations for repair)	Not recommending	
12	Cost of spares (specify parts and cost)	NA	

13	Asset Value	1,353/-	
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA	
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX.	Cyrix Service report attached	
16	Reasons for recommending the equipment as BER	Checked the machine and found that Machine is not switching on, Found motor and piston are defective. Equipment installed on 12-11-2013 aged up to 9 years 10 month. Quotation not submitted since spare are not available from the market. So we recommend the equipment for condemnation	
17	Signature of CYRIX Authority	BIJO T JOY	

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

motor and piston are defeative.

Signature of JC BM (NHM)

Superintendent/Medical Officer (i/c)

Signature of seal

Date
SUPERINTENDENT
SUPERINTERS HOSPITAL
CHAVAKKAD
CHAVAKKAD



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION




SERVICE PROVIDER

No. :

HEALTH	CAREPV	TLTD		2990
ISO 13485 : 2012 & ISO 9001-2008 CER Service Report 30/64 1 B, Petta Junction, Ph : 98472 99500 Website : wv	Poonithura, Ko	chi - 682 038, K	erala	
Health Facility THOH CHAVALAD. THRISSUR,	Caller ID: Date of Vis Asset No.: EQPT Name	ration Date : 69539 it : 16 06 08268 e : Nebw	9 1 2023 45 4327	
Ph: ดูรูนาดให้หน	S. No	Wa 30845	Dept	JLV-230828
roblem Identified: Machine h				
roblem identified :/.//./.	0.1			
		·/····································		
machine i's not switching. Are difective need to r	eplane	and m	notog a	nd preton
machine i's hot switching are difficient. need to recting the ching. Tor further checking. ompleted Date: 16/09/23. Time:	on to eplace	und me pil	notog a ston ov	nd preton
machine i's hot switching. Are difficient need to report for further checking. completed Date: 16/09/23. Time:	on to eplace	und me pil	noto I a Stan evr Spare	nd preton
machine i's hot switching are difference. need to recting the ching. Tor further checking. ompleted Date: 16/09/23. Time:	eplane	und me pis	noto I a Stan evr Spare	nd fiktor d motos Required
machine i's not switching. Are different need to represent the surface of the su	eplane	und me pis	noto I a Stan evr Spare	nd fiktor d motos Required
machine i's hot switching. Are differed need to recommend the further. Checking. ompleted Date: 16/09/23. Time: pare Replaced Requested Description	eplane	und m mu pik	Spare	Required
Cyrix Engineer	eplane	Part Nur	Spare Start Time	Required PR Number End Time







			19	Balane
	Neubilisor.	RO	Balan	balani
12/11/				
2013	Rd from store.	0	0	
	RS. 1890.			
	Readynist Model)			
	OUARTERS			
	AND QUARTERS HO			
	CHAVAKKAD			
	TOTAL CONTRACTOR OF THE PARTY O			