


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	GENERAL HOSPITAL THIRUVANANTHAPURAM
3	Name of Equipment with Make, Model and Serial Number	Equipment :Electrical Suction unit Make : Monarch Model : MSI-RG02 SI : 2020392
4	Equipment ID/ Barcode	107256 / 0110770
5	Date of purchase/ Year of manufacture/Installation Date	07/03/2019
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	20/04/2024
9	Action taken	Checked and found the suction motor and the suction jars defective. Need to replace the spares for further checking and working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not recommending for repair
12	Cost of spares (specify parts and cost)	Suction Motor – Rs.4650/- Suction Jars – Rs.3600/- Total – Rs.8250/-

13	Asset Value	Rs.9900/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	83%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report and vendor quotation attached.
16	Reasons for recommending the equipment as BER	Checked and found suction motor and the jars defective. The equipment was installed on 07/03/2019 and aged up to 5+ years. Repairing cost of the equipment is 83%. As per the tender clause 5.3.14.1 both criteria met, So recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	KASYEP PV 

*Not mandatory


#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Suction motor and jars are defective. Repairing charge is 83%. So as per conditions this can be BER.


MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram

10.6.2024 

Signature of JC BM (NHM)



Date:


Signature of Superintendent
Superintendent Medical Officer (i/c)
Thiruvananthapuram



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 218530

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrilx.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>General Hospital</u></p> <p>Address <u>Thiruvananthapuram</u></p> <p style="padding-left: 40px;"><u>Kerala</u></p> <p>Ph : <u>8301939092</u></p>	<p>Call Registration Date : <u>20/4/24</u></p> <p>Caller ID : <u>107256</u></p> <p>Date of Visit : <u>21/4/24</u></p> <p>Asset No. : <u>0110770</u></p> <p>EQPT Name : <u>Electric Suction Unit</u></p> <p>Manufacture <u>Monarch</u> Model : <u>MSI-R602</u></p> <p>S. No. <u>2020392</u> Dept. <u>SICU</u></p>
--	--

Service Classification : Breakdown Call **PMS** **Calibration** **Cust.Training**

Problem Identified : Not working - suction motor not working.

Action Taken : Checked the machine and found motor and suction bottles are defective. Need to replace it for further checking. Enquired spare with vendor.

Completed Date : 21/4/24 Time : 11:15 AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
2.				
3.				

Cyrilx Engineer	Date	Start Time	End Time
<u>Soorya Sudheep</u>	<u>21/4/24</u>	<u>10:30 AM</u>	<u>11:15 AM</u>

Customer Remark **Pending**




<p>Service Engineer Name : <u>Soorya Sudheep</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>21/4/24</u></p> <p>Contact Number : <u>7907406244</u></p>	<p>Customer Name : <u>Suja - T</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>21/4/24</u></p> <p>Contact Number : <u>8301939092</u></p> <p>Designation : <u>Senior Nursing officer</u></p> <p>Hospital Seal :</p>
---	---

Superintendent
General Hospital
Thiruvananthapuram

SUCTION APPARATUS

Next page continues on 271
 IR Register SC Vol
 Page No: 69

11.05.17	B/F From PNo: 88 ¹²⁸ dt: 11.05.17 LPR GAT IN No: 03A Target Surgicals Rs: 10710/- Issued to ward I [SSR 28]	01	-	01	
24.10.17	B/F P.No. 225 dt 24.10.17 LPR GAT IN No. 40 Target Surgicals Rs. 11525/- Issued to FSW [SSR. 99]	01		01	Issued to FSW
7.3.19	KM SCL as per ord. no. 50/1117/2018-19/119, purchased from Monarch Surgical Industries, 62, DSIDC, Scheme -1, Phase II, Okhla Industrial area, New Delhi. Tel. 26389237, as per inv. no. MSI-0064 dt. 06.2.2019. Installed on 13.6.2019. Warranty from 13.6.2019 to 12/6/2028. Amount ₹. 9900 + tax/one.				
1.	Suction Apparatus Model RG-02 ISI marked	4		4	
28.3.19	Issued to OT	2		2	
25.10.19	Issued to Ward 8 down [SSR 75]	1		1	Singh
25.10.19	Issued to Ward I [SSR 205]	1		NIL	Arif Jaleel
10.02.2020	Invoice No: MSI-00169 Supplied by Monarch surgical industries. Scheme -1, Phase II, Okhla Industrial Area, Newdelhi - Purchase Order No: SO/1160/2019-2020/119 Model: RG-02 ISI Marked. Warranty start date: 4/3/2020 End date: 8/3/2021 Engineer: Komal Singh: 9717374579. Serial No: 2020029, 2020032				
24/3/2020	Issued to Operator theatre General	2		2	
1/3/2020	Scheme: DHS 2019-20 strengthening of emergency medical care Min hand is sub stock Part II				



Signature: _____
 No. Page 2 of 6
 Shree Superintendent
 General Hospital
 Tiruvananthapuram



9744473043, 9744473243

cloud99biotech@gmail.com

1-KMC/XIII-1333
Room No: 22
CSI Golden Jubilee Complex
Baker Hill
Shastri Road
Kottayam

CLOUD99 BIOTECH

GSTIN: 32AMWPT5633Q1Z0
State: 32 - Kerala

MSME NO.: UDYAM-KL-07--0030714

Estimate

Estimate For:

KASHYAP

1ST FLOOR 30/641B CYRIX HEALTHCARE PVT
LTD KOCHI DHANUSHKODI ROAD POONITHURA

Contact No.: 7593847134

GSTIN Number: 32AAFCC2499H2ZM

State: 32-Kerala

Estimate No.: C99B-QTN-16

Date: 27/05/2024

Place of Supply: 32-Kerala

#	Item name	HSN/ SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	SUCTION MOTOR (MOTOR FOR HOSPITAL SUCTION)	9018	1	-	₹ 3,940.68	₹ 709.32 (18%)	₹ 4,650.00
2	SUCTION JAR	90189099	1	Nos	₹ 3,214.29	₹ 385.71 (12%)	₹ 3,600.00
Total			2			₹ 1,095.03	₹ 8,250.00



Pay To:

Bank Name : UNION BANK OF INDIA, KOTTAYAM

Bank Account No. : 361201010035646

Bank IFSC code : UBIN0536121



Account holder's name : CLOUD99 BIOTECH

Sub Total	₹ 7,154.97
SGST@6%	₹ 192.86
CGST@6%	₹ 192.86
SGST@9%	₹ 354.66
CGST@9%	₹ 354.66
Total	₹ 8,250.00
You Saved	₹ 0.01

Description

EQUIPMENT: ELECTRIC SUCTION UNIT
MAKE: MONARCH
MODEL: MSI-RG02
TICKET ID: 107256
BAR CODE: 0110770
HOSPITAL: GH TRIVANDRUM

Estimate Amount In Words

Eight Thousand Two Hundred Fifty Rupees only


Terms And Conditions

Thanks for doing business with us!

For : CLOUD99 BIOTECH



Authorized Signatory



Superintendent
General Hospital
Thiruvananthapuram





Repairing Quotation for Electrical Suction ID 107256

1 message

CLOUD 99 <cloud99biotech@gmail.com>
To: kasyepcyrix@gmail.com <kasyepcyrix@gmail.com>

Tue, 28 May 2024 at 11:25 am

SUSAN JOHN
Cloud99 Biotech
Medical Engineering Works
Room No: 22, CSI Golden Jubilee Complex
Kottayam 686 001
Kerala, India
Ph: 9744473043
email: cloud99biotech@gmail.com



[Handwritten Signature]
Superintendent
General Hospital
Thiruvananthapuram