


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)


PROFORMA


Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	THQH IRITTY
3	Name of Equipment with Make, Model and Serial Number	OXYGEN CONCENTRATOR Make: OXY MED Model: OM-501 SN: NA
4	Equipment ID/ Barcode	1321039 #116878
5	Date of purchase/ Year of manufacture/Installation Date	21-08-2018 (Actual installation date is 10.10.2019 , book attached for reference)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 13-06-2024
9	Action taken	Checked the machine and found that Machine is not switching ON, found problem with Main Board, sieve bed and compressor. Need to replace these spares for further checking.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	N/A

13	Asset Value	33400/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	N/A
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM End of life letter attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that Machine is not switching ON, found problem with Main Board, sieve bed and compressor. In software equipment installed on 21.08.2018. As per the stock book installation date is 10.10.2019 aged up to 3years and 8 months. OEM informed that this machine is obsolete model, end of life letter issued. As per tender clause 5.3.14.2 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 



*Not mandatory **#Based on the period of life and value as per the BER guidelines**

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:
 checked & identified that the machine not switching ON due to main board issue aged up to 3 years above. OEM also reported the machine is an obsolete model & end of life issued. So recommended for BER as per BER Protocol.
 Signature of JC BM (NHM) 
 24/07/2024

Beenamma .pc 
 Senior Nursing Officer

Date: 4.7.24

 
 Signature of
 SUPERINTENDENT
 Taluk Hospital Iritty
 KANNUR DT. - 670703

Signature of
 Medical Officer (I/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 221929

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>THQH IRITTY</u></p> <p>Address : <u>Iratty</u> <u>KANNUR.</u></p> <p>Ph : <u>9496162881</u></p>	<p>Call Registration Date : <u>13.06.2024</u></p> <p>Caller ID : <u>116878</u></p> <p>Date of Visit : <u>14.06.2024</u></p> <p>Asset No. : <u>1321039</u></p> <p>EQPT Name : <u>OXYGEN CONCENTRATOR</u></p> <p>Manufacture : <u>OXY MED</u> Model : <u>OM 501</u></p> <p>S. No. : <u>NA</u> Dept. : <u>Ward.</u></p>
---	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Mainboard, Sieve bed, Compressor are defective

Action Taken : checked the machine and found that machine is not switching ON. Found problem with mainboard, Sieve bed and compressor, Need to replace these spares for further checking.

Completed Date : 14.06.2024 Time : 10:30 AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Sayanth</u>	<u>14/06/2024</u>	<u>9:00 am</u>	<u>10:30 am</u>

Customer Remark Completed Pending

Service Engineer Name : Sayanth
Signature : [Signature]
Date : 14/06/2024
Contact Number : 8606345195



Customer Name : Beenamma P.C
Signature : [Signature]
Date : 14/6/24
Contact Number : 9496162887
*Designation : SNO
Hospital Seal :

SUPERINTENDENT
TALUK HOSPITAL IRITTY
KANNUR DT. - 670703

Obsolete Letter for Oxy-med Owgels Model (3 Lpm / 5 Lpm)

Dear valued customers,

Medequip has discontinued support for the OXY-MED OWGELS 3Lpm and 5Lpm models, repair parts are no longer available for these models.



Please contact our OXY-MED Support staff or our Service team.

If you wish to exchange your old product with new updated Oxymed -Mini Product, Please contact our OXY-MED support staff or our service team. Should you have any commercial or product related questions please contact Mr. Jayakumar for Further Information

Thanks & Regards

Jayakumar
Service Manager- India
Mobile- +918795660006
Email-jayakumar@medequip.co.in



Fwd: REQUIRED ONE TIME SERVICE SUPPORT FOR OXYGEN CONCENTRATOR #1321039,1321050. 116878, 116877

1 message

avinash t <avinashtcyrix@gmail.com>
To: Sarang KM <sarangcyrix@gmail.com>

Wed, Jul 24, 2024 at 3:24 PM

----- Forwarded message -----

From: **avinash t** <avinashtcyrix@gmail.com>
Date: Wed, 24 Jul, 2024, 3:10 pm
Subject: Fwd: REQUIRED ONE TIME SERVICE SUPPORT FOR OXYGEN CONCENTRATOR #1321039,1321050. 116878, 116877
To: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

----- Forwarded message -----

From: **Medequip Service Kerala** <service.kerala@medequip.co.in>
Date: Wed, 24 Jul, 2024, 3:08 pm
Subject: Re: REQUIRED ONE TIME SERVICE SUPPORT FOR OXYGEN CONCENTRATOR #1321039,1321050. 116878, 116877
To: avinash t <avinashtcyrix@gmail.com>

On Wed, Jul 24, 2024, 2:39 PM avinash t <avinashtcyrix@gmail.com> wrote:

Dear sir,
Reminder

On Fri, 28 Jun, 2024, 6:45 pm avinash t, <avinashtcyrix@gmail.com> wrote:

Dear Sir,
There is a complaint reported from THQH IRITTY,KANNUR Regarding the complaint with OXYGEN CONCENTRATOR. We required your one time service support for rectifying the problem.

EQPT NAME- O2 CONCENTRATOR
MAKE- OXYMED OWGELS
MODEL- 5 L, OM 501
COMPLAINT- NOT WORKING

Thanks & Regards

Avinash T
District charge, kannur
bemp kerala
mobile: +91 6364064948
E mail: avinashtcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B | Petta | Punithura | Kochi | Kerala- 682038
www.cyrixhealthcare.com



Screenshot_2024-07-24-15-04-12-39_6012fa4d4ddec268fc5c7112cbb265e7.jpg
227K



OUGELS[®]
Oxy-med[™]
O₂ for healthy living


TREND[®]
SURGICALS PVT.LTD.
 KAKKAD ROAD, SOUTH BAZAR, KANNUR-2
 Ph: 04972 764740, Customer care: 2120 444 040
 Email: trendburg@gmail.com, Web: www.trendburg.com
 Branches: Wayand, Kothikode & Ernakulam

kpl
 KERALA PUBLIC HEALTH SOCIETY
 Kollam Group
 MEDICAL EQUIPMENT MAINTENANCE PROGRAMME (MEMPP)
 Toll FREE 1800-2700-630 85131418 QR/2D MATRIX
 ATPL BARCODE - (P005776)

CYRIX
 TOLL FREE NO. 1800-435-7060
 BAR CODE: (8004-800415223) 1321639

5L Oxygen Concentrator for Medical Use

A GERMAN RESPIRATORY THERAPIST SINCE 1963



OUGELS[®]
Oxy-med[™]
O₂ for healthy living
Oxygen Concentrator
 Model: OM-501 Input Voltage: 220V/50Hz
 Input Power: below 340W Oxygen Pressure: 40-60 KPa
 Oxygen Conc.: 93%±3% Flow Rate: 1-5 LPM
 Dim.(mm): 390*400*705 Net Weight: 19KG
Supervised by Germany Ougels Group Share GmbH

Oxygen Concentrator - 5 ltrs
 Item code - MOOXY05
 MRP: 57,980/-
 (Inclusive of all GST)
 8707031846



P. ulom
D. R. Jayaraj

SUPERINTENDENT
TALUK HOSPITAL IRITTY
KANNUR DT. - 670703

	O ₂ Concentrator	Recd	Issd	Balance
10/10/19	7m in form purchase unit. (Page-33)	2	2	2
5/5/21	Rtd from store	1		3
19/5/21	Rtd from store (Covid 19 donation)	2		5
4/6/21	Rtd from store & 2 UPS (Proactive medical product Washington)	3		8
12/6/21	Rtd from store (model no: CRP ₃ W)	3		11



Dr. Ramesh M

**SUPERINTENDENT
TALUK HOSPITAL IRITTY
KANNUR DT. - 670703**