


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	GH THALASSERY
3	Name of Equipment with Make, Model and Serial Number	MULTI PARA MONITOR Make: PHILIPS Model: UT6000 SN: CN12802961
4	Equipment ID/ Barcode	1312001 #108481
5	Date of purchase/ Year of manufacture/Installation Date	11-02-2009 (Actual installation date is 27.11.2012)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 27-04-2024
9	Action taken	Checked the machine and found that machine not working, found Display, Display Back light board, Main Board, Parameter board Defective. Requested OEM for Quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	N/A

13	Asset Value	70000/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	N/A
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM End of life letter attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that machine not working, found Display, Display Back light board, Main Board, Parameter board Defective. Requested OEM for Quotation. In Ticket master Equipment installed on 11.02.2009 .As per stock book installation date is 27.11.2012 aged up to 11 years 7 Months, oem informed that this machine is obsolete model, end of life letter issued. As per tender clause 5.3.14.2 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that main board, Parameter board defective - Aged upto 11 years & above. And also reported as obsolete model. So recommended for BER as per BER protocol


25/06/2024

Signature of JC BM(NHM)

JUNIOR CONSULTANT BIOMEDICAL
KANNUR - 670002



JYDTHISH.I.C


27/06/2024


SUPERINTENDENT
Govt General Hospital
Thalassery

Signature of
Superintendent/Medical Officer (i/c)

Date:



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. :
224882

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>G.H. THALASSERY</u></p> <p>Address <u>THALASSERY</u> <u>KANNUR</u></p> <p>Ph : <u>09846250492</u></p>	<p>Call Registration Date : <u>27/04/2024</u></p> <p>Caller ID : <u>108481</u></p> <p>Date of Visit : <u>29/04/2024</u></p> <p>Asset No. : <u>1312001</u></p> <p>EQPT Name : <u>Multipara Monitor</u></p> <p>Manufacture <u>Philips</u> Model : <u>UTE000A</u></p> <p>S. No. <u>CNI2802961</u> Dept. <u>Labour OT</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Machine not working

Action Taken : Checked the machine and found that machine not working. Found Display, Display Back light board, Main board, Parameter board defective. Requested OEM for quotation.

Completed Date : 29/04/2024 Time : 4:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Prathyush T. Bhaskar</u>	<u>29/04/2024</u>	<u>3:00pm</u>	<u>4:00pm</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Prathyush T. Bhaskar</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>29/04/2024</u></p> <p>Contact Number : <u>9947025643</u></p>	<p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>29/04/2024</u></p> <p>Contact Number : <u>984750121</u></p> <p>Designation : <u>Superintendent</u></p> <p>Hospital Seal : <u>General Hospital Thalassery</u></p>
--	---



SUPERINTENDENT
General Hospital
Thalassery

Date: 3rd July 2024

To Whomsoever it may concern

This is to inform that Philips India Ltd have declared patient monitor model Goldway UT6000 as an end-of-life device. Hence spare parts of this model may/may not be available.

Thanking you,

Yours Faithfully


Davis George
Manager
Anamdev Engineers





REQUIRED SPARE QUOTATION PATIENT MONITOR 1312001 #108481

8 messages

Sarang KM <sarangcyrix@gmail.com>

Thu, 27 Jun, 2024 at 4:45 pm

To: anamdev engineers <anamdev.medical@gmail.com>

Cc: davis george <davis.anamdev@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear Sir/Madam,

There is a complaint reported from Government General Hospital Thalassery , Kannur district, Kerala, Regarding the complaint with PATIENT MONITOR . Please share the quotation for below mentioned parts.

1. Display
2. Display back light board
3. main board
4. parameter board

Make: GOLDWAY

Model: UT6000A

Serial Number : CN12802961

--

Thanks & Regards

Sarang.k.m

Divisional Incharge|North Zone

Bemp-Kerala

Mobile : +91 7593847150

Email : sarangcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD

30/641B | Petta | Punithura | Kochi | Kerala- 682038

www.cyrixhealthcare.com

P Save Environment, Please do not print this e-mail unless it's essential

Sarang KM <sarangcyrix@gmail.com>

Fri, 28 Jun, 2024 at 5:34 pm

To: anamdev engineers <anamdev.medical@gmail.com>

Cc: davis george <davis.anamdev@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear sir,

Reminder, kindly share the quotation asp

[Quoted text hidden]

Davis George <davis.anamdev@gmail.com>

Mon, 1 Jul, 2024 at 8:47 am

To: Sarang KM <sarangcyrix@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear Cyrix Team,

Patient monitor model UT6000 is end of life as of 31st Dec 2023.

Thanks and Regards,

Davis George

Anamdev Engineers

Mob:9995721150

[Quoted text hidden]

Sarang KM <sarangcyrix@gmail.com>

Mon, 1 Jul, 2024 at 11:02 am

To: Davis George <davis.anamdev@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear sir,

Kindly share the EOL Letter

[Quoted text hidden]

Sarang KM <sarangcyrix@gmail.com>

Wed, 3 Jul, 2024 at 10:44 am

To: Davis George <davis.anamdev@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear sir,

REMINDER

Kindly share the EOL Letter

[Quoted text hidden]

Davis George <davis.anamdev@gmail.com>

Wed, 3 Jul, 2024 at 11:13 am

To: Sarang KM <sarangcyrix@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

PFA

Thanks and Regards,

Davis George

Anamdev Engineers

Mob:9995721150

[Quoted text hidden]

Sarang KM <sarangcyrix@gmail.com>

Wed, 24 Jul, 2024 at 4:45 pm

To: Davis George <davis.anamdev@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear sir,

Is that Philips GOLDWAY UT6000 AND UT6000A Models are the same .Please Let me know

[Quoted text hidden]

Davis George <davis.anamdev@gmail.com>

Wed, 24 Jul, 2024 at 6:54 pm

To: Sarang KM <sarangcyrix@gmail.com>

Cc: anamdev engineers <anamdev.medical@gmail.com>, BLESSEN JOSE <zm2.klbemp@cyrix.in>, avinash t <avinashtcyrix@gmail.com>

Dear Cyrix Team,

UT6000 and UT6000a are the same.

Thanks and Regards,

Davis George

Anamdev Engineers

Mob:9995721150

[Quoted text hidden]

MULTI PARAMETER PATIENT MONITOR

MFC-1000


93

		R	U	B	SN
1/11/2015	BF from Stock Register Vol I page no: 256 Put in use Stock verified and found correct (MFC, 1000)			2	2
Rd	22/3/11 Page no: 61 3SR Vol II Rs 82,660/- KMSCL Supply Model: Sanyo mindsey ko. Warranty = 3 years Medicals				
Rd	27/11/12 Page no: 51 book 25 donated SBI Rs 60,000/- Kerala Surgicals (CF 6000H patient monitor) warranty not available				
6/3/18	Stock verified and found correct				Physically below
1/10/2001	Multiparameter monitor 3 numbers from urology OT page NO 9 Issued to use in 6/4/01			3	5
3/15/22	Rd from store 6/1 24/01 22-23 Multiparameter Monitor (Model - Star 8000 / SHENZHEN COMEN MEDICAL Instruments) issued to use	3		NIL	5
	(Rs. 66,640.00 Exp. Date 31/12/2029 3 No: 1, 99, 920) Supply order no. 50/747/2017-18/75 Serial no. FT1803091128, (2) FT1803091144B (3) FT180309118B, Warranty 3 years 25/5/22 - 24/5/25 Accessories (1) Adult 5 lead ECG cable (2) (2) Reusable Adult & Paed. SpO ₂ probe 1 each (3) Adult & Paediatric NIBP cuffs 1 each			3	NIL 8
	Amun. v 9961476551 Pothan John 8138021100				
16/1/2022	Tr. in from OTH stock book Vol 1 Rd date - 29/6/2021 Exp. 31/5/2028 RS. 5,29,619 = 4120 52489				



SUPERINTENDENT
Govt General Hospital
Thalassery

Cancelled
Tr. out to page NO: 176



[Handwritten Signature]
SUPERINTENDENT
Govt. General Hospital
Thalassery

