


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	24*7 PHC CHERUTHAZHAM
3	Name of Equipment with Make, Model and Serial Number	REFRIGERATOR Make: KELVINATOR Model: NA SN: NA
4	Equipment ID/ Barcode	1340709 #115301
5	Date of purchase/ Year of manufacture/Installation Date	19-12-2008
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 05-06-2024
9	Action taken	Checked the Equipment found Equipment is not switching ON, found that Compressor, Condensor, cooling coil, defrost Heater, Fan Motor, Relay & OLP, Timer and Bimetal defective. Enquired for quotation
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	Condensor-1,750/- Gas Charging-2,600/- Cooling Coil-2,000/- Tinkering & Painting work-1800/- Defrost Heater-1100/- Timer & Bimetal-1200/- Relay & OLP-1200/- Compressor-3800/- Fan motor-950/- Total-16,400/-

13	Asset Value	26494/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	61.900%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & quotation attached
16	Reasons for recommending the equipment as BER	Checked the Equipment found Equipment is not switching ON, found that Compressor, Condensor, cooling coil, defrost Heater, Fan Motor, Relay & OLP, Timer and Bimetal defective. Equipment installed on 19-12-2008 aged up to 15 years 6 months. Repairing cost is 61.900% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Checked & identified that not switching on due to found that compressor, condensor, cooling coil, defrost heater, motor, relay, OLP are defective. Aged up to 15 years & above. So recommended for BER as per BER Protocol.


02/07/2024

Signature of JC BM (NHM)

CONSULTANT BIOMEDICAL
NATIONAL HEALTH MISSION
KANNUR - 670002


Akshita A.V



17/7/24

Pharmacist (Gro II)

Date: 17/7/24



Condemned as per G.O (MS) No. 63/2013
17 & 18 Feb - Pt - 23/2/2013


Signature of
Superintendent/

MEDICAL OFFICER
FHC CHERUTHAZHAM
(PO) PILATHARA - 670504



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 227468

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>PHC Cheruthazham</u>.....</p> <p>Address <u>Kannur</u>..... <u>Kerala</u>.....</p> <p>Ph : <u>9961915722</u>.....</p>	<p>Call Registration Date : <u>05-06-2024</u>.....</p> <p>Caller ID : <u>115301</u>.....</p> <p>Date of Visit : <u>06-06-2024</u>.....</p> <p>Asset No. : <u>1340709</u>.....</p> <p>EQPT Name : <u>Refrigerator</u>.....</p> <p>Manufacture <u>Kelvinator</u> Model : <u>NA</u>.....</p> <p>S. No. <u>NA</u>..... Dept. <u>OP</u>.....</p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : found equipment is not switching ON.....

Action Taken : Checked the Equipment found Equipment is not switching ON, found that compressor, condenser, cooling coil, defrost heater, fan motor, relay and OLP, timer and bimetal defective. Inquired for quotation......

Completed Date : 06-06-2024 Time : 11:00AM..... Spare Required


Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.	NA	NA	NA	NA
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Nitheesh P</u>	<u>06-06-24</u>	<u>10:00AM</u>	<u>11:00AM</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Nitheesh P</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>06-06-24</u></p> <p>Contact Number : <u>8301871531</u></p>	<p>Customer Name : <u>Akhila A.V</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>6/6/24</u></p> <p>Contact Number : <u>9961915722</u></p> <p>Designation : <u>Pharmacist</u></p> <p>Hospital Seal :</p>
--	--



MEDICAL OFFICER
PHC CHERUTHAZHAM
(P.O.) PILATHARA - 670504
17/7/24

SAJITH K

KUNNUMCHALIL HOUSE
PALAYAD POST
PHONE NO: 8943706200
AC REFRIGERATION SERVICE& REPAIRING

Date: 02.07.2024

ESTIMATE

NAME: PHC CHERUTHAZHAM

MAKE: KELVINATOR

ASSET No: 1340709

SL.NO	ITEM	AMOUNT
1.	CONDENSOR	1750/-
2.	GAS CHARGING	2600/-
3.	COOLING COIL	2000/-
4.	TINKERING AND PAINTING WORK	1800/-
5.	DEFROST HEATER	1100/-
6.	TIMER AND BIMETAL	1200/-
7.	RELAY AND OLP	1200/-
8.	COMPRESSOR	3800/-
9.	FAN MOTOR	950/-
	TOTAL -Sixteen Thousand Four Hundred only	16400/-


Sajith k

SAJITH. K
AC Refrigeration Service & Electrical Repairing
Kunnumchalil House
Palayad (P.O), Thalassery
Mob: 8943706200