


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THRISSUR
2	Name of Hospital	PHC ENGANDIYUR
3	Name of Equipment with Make, Model and Serial Number	OXYGEN CONCENTRATOR Make: NA Model: ZY-10ZW SN: 2106263411079
4	Equipment ID/ Barcode	0842641 - #84314
5	Date of purchase Year of manufacture/Installation Date	Ticket master installation date -12-05-2017 (As per hospital stock ledger equipment received on 27-07-2021- donated item)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 06-12-2023
9	Action taken	Checked the machine and found that compressor motor, sieve bed and main board are defective, need to replace these spares for further checking
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA


13	Asset Value	26500/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report Attached
16	Reasons for recommending the equipment as BER	Upon inspecting the machine, it was discovered that the compressor motor, sieve bed, and main board are faulty. These spare parts need replacement to assess the equipment's operational status. As per hospital stock ledger equipment received on 27-07-2021. Unfortunately, the supplier information is unavailable from end user as the equipment was donated without manufacturing details. Due to the lack of spare part information, we advise condemning the equipment as a special case (5.3.14.2).
17	Name & Signature of CYRIX Authority	BIJO T JOY 


*Not mandatory **#Based on the period of life and value as per the BER guidelines**

* **Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Supplier information not available



Jr. Consultant (Biomedical)
NHM, Thrissur


Signature of JC BM (NHM)



Date:


Signature of
Superintendent/Medical Officer (i/c)


MEDICAL OFFICER IN CHARGE
FAMILY HEALTH CENTRE
ENGANDIYUR, P.O. KUNDALIYUR
THRISSUR 880 616



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 128946

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>PHC</u></p> <p>Address : <u>ENGANDIYUR</u> <u>TRISSUR</u></p> <p>Ph :</p>	<p>Call Registration Date : <u>06-12-2023</u></p> <p>Caller ID : <u>84314</u></p> <p>Date of Visit : <u>07-12-2023</u></p> <p>Asset No. : <u>0842641</u></p> <p>EQPT Name : <u>Oxygen concentrator</u></p> <p>Manufacture : <u>N/A</u> Model : <u>N7 102W</u></p> <p>S. No. <u>2106263411079</u> Dept.</p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not Switching On

Action Taken : Machine checked and found that main board, sieve bed and compressed air defective need to replace this spare for further checking

Completed Date : 07/12/23 Time : 11:00am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Biyo</u>	<u>7/12/23</u>	<u>10:00am</u>	<u>11:00am</u>

Customer Remark Completed Pending

Service Engineer Name : Biyo
Signature :
Date : 07/12/2023
Contact Number : 892187040

Customer Name : Rakhi
Signature :
Date :
Contact Number :
Designation : Pharmacist
Hospital Seal :



MEDICAL OFFICER IN CHARGE
FAMILY HEALTH CENTRE
ENGANDIYUR, P.O. KUNDALIYUR
TRISSUR-680 618

OXYGEN CONCENTRATOR 10L

27/7/21 Bal IN NO. K1008/FD/00405/21-22 dtd 27/7/21.

Donated from DDWH-TSR.

1-Oxygen concentrator 10L - Qty-2 NOS

Mfr: Gata Autocomp

(1) 1. Issued to palliative @:

1- Kalyani, Aaruketty, ward 13.

1/9/21 2. Issued to Gopalan, Kizhakkemakkal ward 13.

ngp



Non sealed

CYRIX MEDICAL EQUIPMENT MAINTENANCE
PROFESSIONAL SERVICE
TOLL FREE NO-1800 - 425-7968
NAG CODE - (8004-280015225)
0042541

CYRIX
Call for details
Please don't hesitate
to call us for
any of our
and more services

Manoj
Jr. Consultant (Biomedical)
NHM, Thrissur



Dr. [Signature]
Jr Consultant (Biomedical)



Oxygen Concentrator

Model No: 102W
Capacity: 3L/min
Flow: 1-10 L/min
Oxygen Purity: 93% ± 3%
Other details can be found in the instructions
Date of production: fuselage bar code

☐ ⤴

Model No : 102W
Date Of Manufacture : 26th. 06. 2021



Serial No: 2106263411079 2106/106



[Signature]
Jr Consultant (Biomedical)
NHM, Thrissur



PHC ENGANDIYUR-0842641- FOR SUPPLY DETAILS

3 messages

Bijo T Joy <bijocyrix@gmail.com>

Tue, 9 Jul, 2024 at 8:00 am

To: KMSCL <kmsclbmecentral1@gmail.com>, bmetsr2020@gmail.com

dear mam,
kindly provide the supply detail of below mentioned oxygen concentrator
equipment - oxygen concentrator(donation)
hospital - PHC ENGANDIYUR
barcode - 0842641
caller id - 84314
make - nil
model - ZY-10ZW
With Regards,

BIJO T JOY
DISTRICT INCHARGE THRISSUR,
CYRIX HEATHCARE PRIVATE LIMITED

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia
M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

KMSCL <kmsclbmecentral1@gmail.com>

Fri, 12 Jul, 2024 at 4:46 pm

To: Bijo T Joy <bijocyrix@gmail.com>

The supply details for the above mentioned equipment were not available with us. Please refer to the hospital stock data for additional details.

[Quoted text hidden]

--

Regards,
SALU U S
DISTRICT BIOMEDICAL ENGINEER
KMSCL
Contact No: +91 91889 10013

Bijo T Joy <bijocyrix@gmail.com>

Wed, 31 Jul, 2024 at 10:28 am

To: KMSCL <kmsclbmecentral1@gmail.com>

dear mam,
We checked the stock details at the hospital. As this machine has a donated item, we could not find the supply details at the hospital.

With Regards,
BIJO T JOY
DISTRICT INCHARGE THRISSUR,
CYRIX HEATHCARE PRIVATE LIMITED

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia
M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

[Quoted text hidden]