


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	PALAKKAD
2	Name of Hospital	THQII MANNARKKAD
3	Name of Equipment with Make, Model and Serial Number	SPOT LIGHT Make :HARDIK MEDI TEK Model:SPARX LED 7004 SN:SL/18-19/066
4	Equipment ID/ Barcode	0920395 #104291
5	Date of purchase/ Year of manufacture/Installation Date	25-06-2018
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	02-04-2024 toll free
9	Action taken	Checked the machine and found that SMPS, lamp assembly, arm assembly, spot light head defective. Enquire for quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	Lamp assembly = 2124.00 Arm assembly = 3658.00 SMPS = 2950.00 Spot light head = 4012.00 TOTAL = 12744.00

13	Asset Value	RS. 16630/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	76.6%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Service report attached Quotation attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that SMPS, lamp assembly, arm assembly, spot light head defective. Enquire for quotation. Equipment installed on 25-06-2018 aged up to 5 years and 9 months. Repairing cost is 76.6% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation
17	Name & Signature of CYRIX Authority	AKHILESH P 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Machine aged up to 5 years and third party provided quotation about Rs: 12744. Repairing cost is 76.6% both criteria for RBER met.


Signature of Junior Consultant (Biomedical Engg)
Consultant (Biomedical Engg), Palakkad
NHM (Arogya Keralam)

Date:




Signature of Superintendent
Superintendent (Medical Officer) (I/c)

താലൂക്ക് ആനുകൂല്യ ഔദ്യോഗിക
മുദ്രാൻവയം



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 180180

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrrix.com | E-mail : bemp.kl@cyrrix.in

Health Facility <u>THQH MANNARKAD</u>	Call Registration Date : <u>2/4/2024</u>
Address <u>MANNARKAD</u>	Caller ID : <u>104291</u>
..... <u>PALAKKAD</u>	Date of Visit : <u>3/4/2024</u>
Ph : <u>9747472307</u>	Asset No. : <u>0920395</u>
	EQPT Name : <u>Spot light</u>
	Manufacture <u>HARDIK MEDICAL</u> Model : <u>Sprax led 7004</u>
	S. No <u>SI/18-19/066</u> Dept. <u>CASUALTY</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Machine NOT working

Action Taken : checked the machine and found that smps, Lamp assembly, arm assembly, spot light head defective. Need to replace these spare for further checking the complaint of equipment.

Completed Date : 3/4/2024 Time : 11:40 AM Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrlix Engineer	Date	Start Time	End Time
<u>SREETHA C</u>	<u>3/4/2024</u>	<u>10:00 AM</u>	<u>11:40 AM</u>

Customer Remark Completed Pending

Service Engineer Name : <u>SREETHA C</u>	Customer Name : <u>BINDUMOL</u>
Signature : <u>[Signature]</u>	Signature : <u>[Signature]</u>
Date : <u>3/4/2024</u>	Date : <u>3/4/2024</u>
Contact Number : <u>9072522058</u>	Contact Number : <u>9447759477</u>
	Designation : <u>Senior Nursing Officer</u>
	Hospital Seal : <u>[Seal]</u>



Handwritten notes in Malayalam



CYRIZ MEDICAL EQUIPMENT MAINTENANCE PROGRAMME (EMMP)

TOLL FREE NO: 1800 - 425-7669

BAR CODE - (0004-890615225)
0920395




Handwritten signature and text in Sinhala:
සුදාන
ആശുപത്രി
എന്നാൽ

MOBILE SPOT LIGHT (30K)

37

Date	To	By	Qty	Rate	Total
21/6/18	MVA 59 cell- 23/5/18				
	Haridk Meditech				
	(From 1 April 2016)				
	Plot no. 52 First Floor				
	Sec. 57 Phase - IV P.S. 1106				
	Kunche, Sanjpet, Harigere				
	Pincode KMSCL		1 Pcs	1 Pcs Rs 18626	


22/6/18 Issued to OP/CLT

Received 

Furniture for desk registration at measurement

Page Number 247





സൂപണ്ട്
അദ്ധ്യക്ഷൻ ആസ്ഥാന ആരോഗ്യപ്രതി
ബന്ധാർക്കാര്യം

sR MEDICAL SYSTEMS

ROOM NO P P VI 644(new IV 1041)
AMBIKA COMPLEX
PALLIKUNNU, KANNUR
670004 MOB; 9447746567



OUR REF: SR/MED/QTN 02/24-2025
DATE :24 APRIL 2024

TO

Cyrix healthcare pvt It
Poonithura, Ernakulam

Respected Sir,

SUB: QUOTATION FOR SPOTLIGHT SERVICE

Kindly note with reference to the discussions had with yourself regarding the above mentioned subject, we are pleased to submit our very special competitive offer for your reference and further perusal.

In case of any further clarifications kindly feel free to contact us.

SL NO	ITEM	PRICE	QTY	TOTAL	TAX18%	TOTAL PRICE
01	Lamp assembly	1800.00	1 NOS	1800.00	324.00	2124.00
	Arm assembly	3100.00	1NOS	3100.00	558.00	3658.00
	SMPS	2500.00	1NOS	2500.00	450.00	2950.00
	Spot light head	3400.00	1NOS	3400.00	612.00	4012.00

TOTAL AMOUNT = 12744 /-

Thanking you and assuring you of our best attention and engineering services at all times.

Waiting for your earliest reply.

TERMS & CONDITIONS OF SALE

- 100% ADVANCE

Yours truly,

For **SR MEDICAL SYSTEMS,**
KANNUR.

