



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 170278

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility <u>GMH ALAPPUZHA</u>	Call Registration Date : <u>5/7/24</u>
Address	Caller ID : <u>121319</u>
<u>DISC: ALAPPUZHA</u>	Date of Visit : <u>6/7/24</u>
Ph : <u>9605044886</u>	Asset No. : <u>0410537</u>
	EQPT Name : <u>OT Table</u>
	Manufacture <u>NA</u> Model : <u>NA</u>
	S. No. <u>NA</u> Dept. <u>Eye OT</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not functioning. no table movement

Action Taken : On checking found that internal parts are rusted condition

Completed Date : 6/7/24 Time : 12:00 PM Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>M Mathanraj R</u>	<u>6/7/24</u>	<u>11:00 AM</u>	<u>12:00 PM</u>

Customer Remark _____ Completed Pending

Service Engineer Name : M Mathanraj R
Signature : [Signature]
Date : 6/7/24
Contact Number : 9072522056



Customer Name : [Signature]
Signature : _____
Date : 6/7/24
Contact Number : 9447932289
Designation : _____
Hospital Seal : _____
DR. SUNITHA. V.S.
MS, Ophthalmology
Consultant
GH, Alappuzha
Reg.No. 21949



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 170300

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility <u>GH ALAPPUZHA</u>	Call Registration Date : <u>5/7/24</u>
Address <u>DIST. ALAPPUZHA</u>	Caller ID : <u>121319</u>
Ph : <u>9605044886</u>	Date of Visit : <u>5/7/24</u>
	Asset No. : <u>0410537</u>
	EQPT Name : <u>OT Table</u>
	Manufacture <u>NA</u> Model : <u>NA</u>
	S. No. <u>NA</u> Dept. <u>Eye OT</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Noo working, Table movements are not functioning

Action Taken : Checked the machine and found that hydraulic pump, all wheel assembly, Tilt assembly, gear assembly and head rest assembly are defective and rusted condition. Wear and tear ax happened.

Completed Date : 15/7/24 Time : 1:00PM Spare Required


Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Midhunraj R</u>	<u>15/7/24</u>	<u>12:00PM</u>	<u>1:00PM</u>

Customer Remark OT table - not functioning Completed Pending

Service Engineer Name : <u>Midhunraj R</u>	Customer Name : <u>Sunitha</u> <u>9447932288</u>
Signature : <u>[Signature]</u>	DR. SUNITHA. V.S.
Date : <u>15/7/24</u>	MS, Ophthalmology
Contact Number : <u>9072522088</u>	Consultant
	GH, Alappuzha
	Reg.No. 21949




SUNITHA HOSPITAL
ALAPPUZHA

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	GH ALAPPUZHA
3	Name of Equipment with Make, Model and Serial Number	OT TABLE HYDRAULIC MAKE :- NA MODEL :- NA SN :- NA
4	Equipment ID & Barcode	121319 & 0410537
5	Date of purchase / Year of manufacture /Installation Date	24/06/2010
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	05/07/2024
9	Action taken	Checked the machine and found that Hydraulic pump, all wheel assembly, tilt assembly, gear assembly and head rest assembly are defective and rusted condition. Wear and Tear happened.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not Recommended For Repair
12	Cost of spares (specify parts and cost)	NA


13	Asset Value	NA
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report attached.
16	Reasons for recommending the equipment as BER	Checked the machine and found that Hydraulic pump, all wheel assembly, tilt assembly, gear assembly and head rest assembly are defective and rusted condition. Wear and Tear happened and not safe for use. The Equipment was installed on 24/06/2010 and aged up to 14+ years. The machine is irreparable condition. So we are recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	MIDHUN RAJ R 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for BER

 15/07/24

JYOTHISH THOMAS
 Consultant (Biomedical Engineering)
 NHM ALAPPUZZHA
 Signature of J/C BM (NHM)

Date _____



Seal


 Signature of
 Superintendent / Medical Officer (MC)
 SUPERINTENDENT
 GENERAL HOSPITAL
 ALAPPUZZHA

From

Dr. Sunitha V.S
Consultant - Ophthalmology
GH. Alappuzha

To Cyrix Health Care PVT LTD

Through proper channel

Eye OT table room equipment esalilathal
24-6-2016 - th main OT table niyama. (Sambath
chayal) kizhichithal nalam. (Iru room esalilathal chalayal)

make, model, serial No, and installation date

chayal chalayal. Iru chalayal chalayal chalayal chalayal
chayal chalayal chalayal chalayal chalayal chalayal

chayal chalayal chalayal chalayal chalayal chalayal
chayal chalayal chalayal chalayal chalayal chalayal

chayal chalayal chalayal chalayal chalayal chalayal



15/07/24.

Equipment - OT Table hydraulic
cyrix Barcode - 0410537.

DR. SUNITHA V.S.
MS, Ophthalmology
Consultant
GH, Alappuzha
Reg. No. 21949

OPERATION TABLE

	Receipt	Issued	Balance	Remarks
29/1/19	Received from Major OT	2	2	
29/1/19	Received from Ikon Major equipment Register Vol 6 page no. 203 Invoice no. 44-512/10934 Apparony Associate No. 20 Site office colony, Chennai Bill total - 1,00,000/- D.O. No. 26/2129/2018-2119 Model 4A01 Warranty 3 years 29/1/19 to 28/1/22	1	3	
6/9/2019	Received from Ikon (KASCO) Major equipment Register Vol 10 page no. 214 (Model Register 51) ophthalmic chair Model 9 table NAOI/Apparony Associate. Warranty 3 years from 6/1/2019 to 5/1/22 Cost 1,00,000/-	1	4	
21/1/20	06 table (Model Register 51) Model 9 table NAOI/Apparony Associate Warranty 3 years 21/1/20 to 20/1/23 Cost 25,200/- Total cost 1,25,200/- Major equipment Register Vol 10 page no. 215	1	5	



Handwritten signature
SUPERINTENDENT
GENERAL HOSPITAL
ALAPPUZHA

Trischarge
Sufi...
1/10/2020



Sanitary
SUPERINTENDENT
GENERAL HOSPITAL
ALBUQUERQUE, N.M.

01 in charge
Saja A. J.
1/10/2012