

### **BIOMEDICAL EQUIPMENT TENANCE PROGRA** UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

No. : 196474

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency **Service Report** 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph: 98472 99500 Website: www.cyrix.com | E-mail: bemp.kl@cyrix.in Call Registration Date: 16-04-2024 Health Facility PHC Chellanam Caller ID : Proakulan Date of Visit: Asset No. : ... EQPT Name : ..... 9497120805 Manufacture Local Model: BP 1304 S. No. ..... ..... Dept. ..... OP Service Classification : Breakdown Call V PMS Calibration **Cust.Training** BP Apparatus not working **Problem Identified:** Date: 18-04-24 Time: 12:30PM Completed Spare Required Spare Replaced Requested Description Qty. **Part Number** PR Number 1. mokor INO 2. 1100 3. Cyrix Engineer **Date** Start Time **End Time** Thomas 11:00 AM 7:30PM 18-04-29 **Customer Remark** MBBS, MD(PHARICOMpleted Pending

REG.No. 38160

Service Engineer Name: bin Thomas Signature :

Contact Number : 904795805 Customer Name : NHMS . A-15

Signature: Date:

Contact Number: Alusing often an Designation: **Hospital Seal:** 

Daisus mo 68

# REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

## Recommendations for Beyond Economic Repair (BER)

### **PROFORMA**

SI.	Particulars	Details *			
1	Name of District	Ernakulam			
2	Name of Hospital	PHC CHELLANAM			
3	Name of Equipment with Make, Model and Serial Number	Equipment: BP APPARATUS Make: LOCAL Model: BP 1304 Sr.no: NA			
4	4 Equipment ID & Barcode 106520 & 0744085				
5	Date of purchase / Year of manufacture /Installation Date	10-03-2018			
6	Warranty details (Yes/No)	No warranty			
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC			
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	16-04-24 (Toll Free)			
9	Action taken	Checked the machine and found that motor and main board are faulty.			
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged			
111	Recommendations for repair (required service details)	Not recommending for repair.			
1	Cost of spares (specify parts and cost)	NA .			

13	Asset Value	Rs.2200
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
16	Reasons for recommending the equipment as BER	Checked and found motor and main board are defective. Equipment installed on 10-03-2018 and the machine outlived 5+years. Quotation not submitted since the spares are not available in the market. So recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	JIBIN THOMAS GEORGE

<sup>\*</sup>Not mandatory

#Based on the period of life and value as per the BER quidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Signature of JC BM (NHM)

Signature of JC BM (NHM)

REG.No. 38180

Superintendent / Medical Officer (i/c)

Signature of seal



Dr.JINI.K.THOMAS MBBS, MD(PHARMACOLOGY) ASSISTANT SURGEON REG.No. 38160



Date	No. and date of voucher or invoice	From whom received or to whom issued	Receipt	Issued	Balance after each transaction	Initials of Receiver	Rem <sub>ej</sub> Date
		Brought forward					
10/0	3 8 CHX(80 (6)3	188 KSTE Plu 18 (Fanch	1875). ayath 3	(unol)	Bir		
27	she chue	c occopy kar R	10 197	51-		1 No	F
	13/49	Rd from store	1 Po	Rd 30)	3 4		
011	2024	Red from 3tose Commo 140 FS 2323 21/cup issned (1) to Main	+ ]		8	~1/0	
		Isomed (n to Bable	Nie ma	Musp (	7) Reen	One of	-

Tuche

Dr.JINI.K.THOMAS MBBS, MD(PHARMACOLOGY) ASSISTANT SURGEON REG.No. 38160

