

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

HEALTHCARE PVT LTD

No. :

231201

ISO 13485 : 2012 & ISO 9001-2008 CERT	TIFIED COMPANY	AERB Approved	Service Agency	
Service Report 30/64 1 B, Petta Junction, Ph: 98472 99500 Website: wv	Poonithura, Koc vw.cvrix.com	hi - 682 038, Ki E-mail : bemp.k	eraia il@cyrix.in	
Health Facility CHC	Call Registr	ration Date :	25 [06]	
Address CHC Mynagoyppully kown	1	t: 26/	06/24	
Ph: 9744972577	E-61 1 1101111	e Apc	Model :	
		D71400008	DeptLab	ratory
Service Classification : Breakdown Call	PMS	Calibratio	on Cust	.Training
Problem Identified: Ups he	zt gette	ng 00.		
- (Looked, the	UK a	nd I	ound th	e
Action Taken: Checked the boards were defective.	E1.2.1	rised	Spuus	with
Completed Date: 26[06]24 Time:	11.30 az		Spare	Required
Spare Replaced Requested				
Description	Qty.	Part Nu	ımber	PR Number
l.				
2.				
3.				
Cyrix Engineer	1	Date	Start Time	End Time
Biswarya Ry KN				
0				
Customer Remark	Completed		Pendi	ng L
O COLOR MANAGEMENT		ALTIYY Y	REALT A CO	
Service Engineer Name: Aswarya Roj k	Custome		washy 3	
Signature: Date: 26 690519				
Date: 26.06.2024.	Contact I Designat	Number	HAGINEST F	tell

Hospital Seal:

9645384968°.

Contact Number:

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details	
1	Name of District	Kollam	
2	Name of Hospital	CHC MYNAGAPPALLI	
3	Name of Equipment with Make, Model and Serial Number	UPS Make : APC Model : AP1050+ SI no: UV060714A000682	
4	Equipment ID & Barcode	Barcode: 0230096 / Ticket id: 119259	
5	Date of purchase / Year of manufacture /Installation Date	29-08-2014	
6	Warranty details (Yes/No)	No Warranty	
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC	
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	25-06-2024	
9	Action taken	Checked the machine found that the Driver & control PCB were defective, Enquired spares with OEM	
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged	
11	Recommendations for repair (required service details)	Not Recommended for Repair	
12	Cost of spares (specify parts and cost)	1KVA 36VDC DRIVER CUM CHARGER PCB = 6490 CONTROL PCB = 2950 Total = 9440 /-	

13	Asset Value	Rs. 4500/-		
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	209.77%		
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM Quotation attached		
16	Reasons for recommending the equipment as BER	Checked the ups found that the Driver cum charger PCB & Control PCB were defective. UPS is installed on 29-08-2014 and aged up to 9 year 9 month. Repairing cost of equipment is 209.77%. as per tender clause 5.3.14.1 both criteria met So we are recommending the equipment for condemnation.		
17	Name & Signature of CYRIX Authority	AISWARYA RAJ		

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Repair cont is high. 80 sucumended

Repair secure mir sepair

Signature of JC BM (NHM)

ABMO

MHM

Seal MYNAGARRA

Superintendent / Medical Officer (i/c)

Date

AION BACKUPS

Contact: 8921950217

YP/VIII/320 AYLARA, KERALA KOLLAM

Email: alonbackups12@gmail.com

GSTIN: 32CGUPM9450L1ZN

1KVA APC ONLINE UPS SERVICE PROPOSAL

TO.

CYRIX HEALTH CARE PVT .LTD

Barcode: 0230096

Ticket ID: 119259

Dear Sir/Madam,

We are pleased to submit here with our quote for the same as per below.

SL	DESCRIPTION	QTY	UNIT RATE IN INR	TOTAL	GST	TOTAL PRICE IN INR
1	1KVA 36VDC DRIVER CUM CHARGER PCB	1	5500.00	5500.00	18	6490.00
2	CONTROL PCB	1	2500.00	2500.00	18	2950.00
	PAYABLE AMOUNT					9440.00

Commercial terms and conditions

- 1. Payment 80% advance along with PO balance before dispatch, 20% after installation.
- 2. Delivery period; 2weeks.
- 3. Tax:GST@18% for spares,28%@Battery
- 4. Installation; Our scope.

Please arrange to release the PO at our above address					
Bank name :HDFC	Account no:50200082743176	IFSC Code:HDFC0004083			
We hope you will find the	above offer in line with our discussions and	await your valuable order please free to call			

or mail us on above given number if any query.

Thank you, Sincerely,







Date: 22/07/2024

and the second of the second SEMI - AUTO Senatro / Unique IDNO SP.NO Date model No M3620614RBK 1. 29/8/14 Robonik Issued Beleau Recupit NIL OIND DINO Analysee NIL DINO DINO. Dust co ver ups. NIL DINO OINO. OIND OINO Wasti Bottle DINO. Paper ROll 02 NOS . 04 NO NH DINO OINO. Paper Rod. ast DINO orna. Wire he bong Ban code (414) 69 (254) 02 (21) 0726 = 6A,760 -









MEDICATION TO HEALT ALLAY IN COMMUNITY WAS PALLY