


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	PALAKKAD
2	Name of Hospital	DH PALAKKAD
3	Name of Equipment with Make, Model and Serial Number	MULTIPARA MONITOR MAKE: PHILIPS MODEL: GOLDWAY UT6000A SN: CN12805622
4	Equipment ID/ Barcode	0911339 #123128
5	Date of purchase/ Year of manufacture/Installation Date	Ticket master installation date = NIL (As per stock book machine installed on 20/09/2014)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	15/07/2024 (toll free)
9	Action taken	Checked the machine found ecg and spo2 not getting. Problem with ecg module and spo2 module. Requested oem for quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	RS.70000/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached OEM EOL letter attached
16	Reasons for recommending the equipment as BER	Checked the machine found ecg and spo2 not getting. Problem with ecg module and spo2 module . Requested oem for quotation . As per stock book Equipment installed on 20/09/2014, aged up to 9 years 9 months . OEM informed that this model is obsolete. End of life letter issued As per tender clause 5.3.14.2 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AKHILESH P 

*Not mandatory


#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


As per stock book equipment installed on 20/09/2014 and aged up to 9 years 9 months. Equipment is fully damaged and problem related with ECG module and spo2 module and OEM informed that this model is obsolete.

Signature of JC BM (NHM)


26/07/24
Consultant (Biomedical Engg)
NHM (Arogyakeralam), Palakkad



Date:



Deputy Director of Health Service
& Superintendent.

District Hospital, Palakkad

Superintendent/Medical Officer (I/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. :
231870

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>DH palakkad</u></p> <p>Address <u>palakkad (dt)</u></p> <p style="padding-left: 40px;"><u>Kerala</u></p> <p>Ph : <u>9074868652</u></p>	<p>Call Registration Date : <u>15.07.2024</u></p> <p>Caller ID : <u>123128</u></p> <p>Date of Visit : <u>16.07.2024</u></p> <p>Asset No. : <u>0911339</u></p> <p>EQPT Name : <u>multi para monitor</u></p> <p>Manufacture <u>philips</u> Model : <u>no way</u></p> <p>S. No. <u>CN12805622</u> Dept. <u>Cath ICU</u> <u>UT 6000A</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : ECU and SpO₂ not get

Action Taken : checked the equipment and found that ECU module and SpO₂ module faulty. need to replace the ECU and SpO₂ module for further checking.

Completed Date : 16.7.24 Time : 12:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Dileep</u>	<u>16.7.24</u>	<u>10.15 AM</u>	<u>12.00 PM</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Dileep A.</u></p> <p>Signature : <u>Dileep A</u></p> <p>Date : <u>16.07.2024</u></p> <p>Contact Number : <u>9048751999</u></p>	<p>Customer Name : <u>Vijayalee</u></p> <p>Signature : <u>Vijayalee</u></p> <p>Date : <u>16/07/24</u></p> <p>Contact Number : <u>Deputy Director of Health Services & Superintendent.</u></p> <p>Designation : <u>District Hospital, Palakkad</u></p> <p>Hospital Seal : </p>
--	---


Date: 3rd July 2024

To Whomsoever it may concern

This is to inform that Philips India Ltd have declared patient monitor model Goldway UT6000 as an end-of-life device. Hence spare parts of this model may/may not be available.

Thanking you,

Yours Faithfully


Davis George
Manager
Anamdev Engineers





REQUIRED QUOTATION FOR MULTIPARA MONITOR 0911339 # 123128 @ DH PALAKKAD, PALAKKAD

8 messages

Akhilesh P <akhileshcyrix@gmail.com>
To: anamdev.medical@gmail.com <anamdev.medical@gmail.com>
Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>

Sat, 20 Jul, 2024 at 8:38 am

Dear sir
Please share the price and stock availability of ECG MODULE , MAIN BOARD for multipara monitor @ dh palakkad. Details are furnished below.

Hospital Name : DH PALAKKAD
Equipment Name : MULTIPARA MONITOR
Make : SHENZHEN
Model : UT6000A
SN : CN12805622

Thanks & Regards
AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

Akhilesh P <akhileshcyrix@gmail.com>
To: anamdev.medical@gmail.com <anamdev.medical@gmail.com>
Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>

Mon, 22 Jul, 2024 at 3:11 pm

Dear sir
Kindly update the status

Thanks & Regards
AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

[Quoted text hidden]

anamdev engineers <anamdev.medical@gmail.com>
To: Akhilesh P <akhileshcyrix@gmail.com>

Mon, 22 Jul, 2024 at 5:33 pm

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, davis george <davis.anamdev@gmail.com>, Anamdev Engineers <mail@anamdev.com>

Dear Sir
This is to inform you that the Multipara Monitor Model UT6000 is at the end of life as of 31st December 2023.

Thanks n Regards
Jayakumar
(Anamdev Engineers)
[Quoted text hidden]

Akhilesh P <akhileshcyrix@gmail.com> Mon, 22 Jul, 2024 at 7:13 pm
To: anamdev engineers <anamdev.medical@gmail.com>
Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, davis george <davis.anamdev@gmail.com>, Anamdev Engineers <mail@anamdev.com>

Dear sir
Kindly give the eol letter in letter head with seal.

Thanks & Regards

AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

[Quoted text hidden]

Akhilesh P <akhileshcyrix@gmail.com> Wed, 24 Jul, 2024 at 11:13 am
To: anamdev engineers <anamdev.medical@gmail.com>
Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, davis george <davis.anamdev@gmail.com>, Anamdev Engineers <mail@anamdev.com>

Dear sir
Kindly update the status.

Thanks & Regards

AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

[Quoted text hidden]

Davis George <davis.anamdev@gmail.com> Wed, 24 Jul, 2024 at 12:51 pm
To: Akhilesh P <akhileshcyrix@gmail.com>
Cc: anamdev engineers <anamdev.medical@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, Anamdev Engineers <mail@anamdev.com>

PFA

Thanks and Regards,
Davis George
Anamdev Engineers
Mob:9995721150

[Quoted text hidden]

Akhilesh P <akhileshcyrix@gmail.com> Thu, 25 Jul, 2024 at 11:31 am
To: Davis George <davis.anamdev@gmail.com>
Cc: anamdev engineers <anamdev.medical@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, Anamdev Engineers <mail@anamdev.com>

Dear sir,

Is that Philips GOLDWAY UT6000 AND UT6000A Models are the same .Please Let me know

Thanks & Regards

AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

[Quoted text hidden]

Davis George <davis.anamdev@gmail.com> Thu, 25 Jul, 2024 at 11:35 am
To: Akhilesh P <akhileshcyrix@gmail.com>
Cc: anamdev engineers <anamdev.medical@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>, Anamdev Engineers <mail@anamdev.com>

Yes

Thanks and Regards,
Davis George
Anamdev Engineers
Mob:9995721150

[Quoted text hidden]

511

181

MULTIPARA MONITOR

R.A

191

B

ms

20/9/14

Recd from the State

G

G

NIL

G

Issued to use

G

NIL

G

Vayalun

Deputy Director of Health Services
& Superintendent
District Hospital, Palakkad



(M.D)

Service # 865251



SN CN12805622



REF UT6000A



DPT B35G13J01S03



SN CN12805622



2014-01



Patient Monitor

Shenzhen Goldway Industrial Inc.

Model: UT6000A

Power: 100V - 240V ~, 50Hz/60Hz 115VA



IPX4



No.2 Tiangong Road, Nanshan District, Shenzhen, P.R.China 518057

Shanghai International Holding Corp. (Lambert Finance) Effelstrasse 80, 20537 Hamburg, Germany

Tel: 0049-40-2513175 Fax: 0049-40-255229



HEALTH CARE PVT.LTD
 BEMP SERVICE PROVIDER
 PREVENTIVE MAINTENANCE SERVICE
 PMS DONE ON: 25/03/2014
 NEXT PMS DUE: 22/03/2015
 PERFORMED BY: 10641


CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)
 TOLL FREE NO: 1800 - 425-7669
 BAR CODE - (8004-890615225) 0911339



CYRIX HEALTHCARE PVT.LTD
 S.N: CN12805622
 CN: DHP090
 PRO: Multipara Monitor
 ID: 0911339
 CAL ON: 30/10/2023
 29/10/2024

GOLDWAY

UT6000A



Jan S W
 Deputy Director of Health Services
 & Superintendent,
 District Hospital, Palakkad

