


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	ERNAKULAM
2	Name of Hospital	PHC VALAKOM ERNAKULAM
3	Name of Equipment with Make, Model and Serial Number	Equipment : Weighing Machine Make : Pragathi Medical Systems Model : 2034 SN :Na
4	Equipment ID & Barcode	118528 & 0744761
5	Date of purchase / Year of manufacture /Installation Date	12-06-2019
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	21-06-2024 (Toll free)
9	Action taken	Checked and found mother board, power supply transformer , display board , accessories and load cell defective. Need to replace these spares for further checking and working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair.
12	Cost of spares (specify parts and cost)	Mother board – Rs.1350/- Power supply transformer – Rs.250/- Display board – Rs.400/- Sensor Load cell – Rs.1750/- Accessories – Rs.250/- Total – Rs.5900/-

13	Asset Value	Rs. 6725/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	87%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached and reference quotation attached.
16	Reasons for recommending the equipment as BER	Checked and found mother board, power supply transformer, display board, accessories and load cell defective. Machine installed on 12-06-2019 and covered up to 4+ years. The repairing cost of the equipment is 87% both criteria met so recommending the equipment for condemnation as per the tender clause 5.3.14.1.
17	Name & Signature of CYRIX Authority	Amal Sasi 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Equipment used to replace motherboard, Power supply transformer, Display board, Sensor Board Cell, Asset value is Rs. 6725/ and reported spare cost is Rs. 5900/- as per attached Quot
BER submitted after 30 days.

CONSULTANT
BIO-MEDICAL ENGINEER
National Commission (NHM)
Arroyal, Ernakulam
Amal Sasi
CONSULTANT BME
31/7/24
Signature of JC BM (NHM)

Date _____



Seal


Signature of Superintendent

സൂപ്പർവൈസിംഗ് ഓഫീസർ ഇൻ ചാർജ്
കുടുംബാരോഗ്യ വിഭാഗം, റവറേണി
മെഡിക്കൽ ഓഫീസ്
ഫോൺ : 682 316



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 216643

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Service Report

<p>Health Facility : <u>FHC</u></p> <p>Address : <u>valaikom, Ernakulam, Kerala</u></p> <p>Ph : <u>7994782562</u></p>	<p>Call Registration Date : <u>21/6/24</u></p> <p>Caller ID : <u>112528</u></p> <p>Date of Visit : <u>22/6/24</u></p> <p>Asset No. : <u>0744761</u></p> <p>EQPT Name : <u>weighing machine</u></p> <p>Manufacture <u>Pragathi</u> Model : <u>2034</u></p> <p>S. No. <u>n/a</u> Dept. <u>publi Health</u></p>
-----------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : machine not getting on

Action Taken : Checked and found mother board, power supply transformer, display board, accessories and lead cell defective need to replace these spares for further checking and working condition of the equipment

Completed Date : Time : Spare Required

Description	Qty.	Part Number	PR Number	Cyrix Engineer		
				Date	Start Time	End Time
1. mother board	1 no			22/6/24	9:00am	12:00pm
2. power supply Transformer	1 no					
3. Display board	1 no					
4. sensor lead cell	1 no					

Customer Remark : _____ Completed Pending

Service Engineer Name : Amal

Signature : [Signature]

Date : 22/6/24

Contact Number : 8281015732



Customer Name : Vilasiruk.K.

Signature : [Signature]

Date : 22/6/24

Contact Number : 8547656929

Registration : PHN


Hospital Seal : _____

സി.ആർ.എസ്. ഇൻ. ചി.ടി.സി.
 ഓഫീസ് ഐ.ഐ.സി. റോഡ്,
 എ.എസ്.പി.ഒ.
 ഫീസ് : 682 316



കേരള ശാസ്ത്ര സാങ്കേതിക വിദ്യാ അക്കാദമി
കോഴിക്കോട് ജില്ല, കോഴിക്കോട്
ഫോൺ : 682 316







BAR CODE: 18004-8906152251
0744761

TOLL FREE NO: 1800 - 425-7668


CYRIX MEDICAL EQUIPMENT MAINTENANCE
PROGRAMME GROUP

TOLL FREE NO: 1800-425-7668



Body
Electronic weighing scale






PRAGATHI MEDICAL SYSTEMS



Baby
Electronic weighing Scale



kg



ON
OFF

MODEL: 2014
MAX: 150kg
MIN: 0.01kg
DATE: 00/00/00

PRAGATHI MEDICAL SYSTEMS