


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THRISSUR
2	Name of Hospital	PHC NALUKETTU
3	Name of Equipment with Make, Model and Serial Number	Bp Apparatus Make - DIAMOND DELUX Model - Delux SN - 9910208
4	Equipment ID/ Barcode	0845892 #123122
5	Date of purchase/ Year of manufacture/Installation Date	Ticket master installation date – NA Actual installation date -14/02/2019 (stock book attached for reference)
6	Warranty details	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown/ Date of registration of complaint	15/07/2024
9	Action taken	Checked the equipment and found mercury tank and glass tube broken, need to replace glass tube, mercury tank and need to refill mercury.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Details of service required (Recommendations for repair)	Not recommending
12	Cost of spares (specify parts and cost)	Mercury and tank - 810/- Glass tube - 110/- Total - 920/-


13	Asset Value	1,323/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	69.54%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX.	Cyrix Service report, quotation attached
16	Reasons for recommending the equipment as BER	Checked the equipment and found mercury tank and glass tube broken, need to replace glass tube, mercury tank and need to refill mercury. Equipment installed on 14/02/2019 and covered up to 5 years and 5 months, Spare cost is 69.54% of asset value both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Signature of CYRIX Authority	BIJO T JOY 

*Not mandatory #Based on the period of life and value as per the BER guidelines


* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Spare cost is high as the broken glass tube, mercury to be refilled


Signature of JC BM (NHM)

Date



Signature of 
Superintendent/Medical Officer (S)

Medical Officer in Charge
Family Health Centre
Nalukettu, Pin 680 308

Nalukettu



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. :
224669

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>phe</u></p> <p>Address <u>Nalukettu</u> <u>Thrisur, Kerala</u></p> <p>Ph : <u>8590640067</u></p>	<p>Call Registration Date : <u>15/7/24</u></p> <p>Caller ID : <u>123122</u></p> <p>Date of Visit : <u>16/7/24</u></p> <p>Asset No. : <u>0845892</u></p> <p>EQPT Name : <u>BP apparatus</u></p> <p>Manufacture <u>Diamond Delux</u> Model : <u>delux</u></p> <p>S. No. <u>9910208</u> Dept. <u>Subcenter</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : pressure not rising

Action Taken : checked the equipment and found Mercury tank and glass tube broken, need to replace glass tube, Mercury tank and need to re-fill mercury

Completed Date : 16/7/24 Time : 12:30 PM Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1. <u>glass tube</u>	1		
2. <u>Mercury tank</u>	1		
3.			


Cyrix Engineer	Date	Start Time	End Time
<u>Jinto Joy</u>	<u>16/7/24</u>	<u>11:30 AM</u>	<u>12:30 PM</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Jinto Joy</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>16/7/24</u></p> <p>Contact Number : <u>7593847125</u></p>	<p>Customer Name : <u>MERCY</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>16/7/24</u></p> <p>Contact Number : <u>9995510132</u></p> <p>Designation : <u>J.P.H.R</u></p> <p>Hospital Seal :</p>
--	---



Medical Officer in Charge
 Family Health Centre
 Nalukettu, Pin: 680 300



BCS Healthcare Pvt.Ltd
3136, 1st door, Mathewsons square
Metro Pillar No: 464 Near Changapuzha park
Cochin, Kerala - 682024,
Email : info@bcshealthcare.in
web: www.bcshealthcare.in



GST NO: 32AAKCB2766M1Z

DATE: 16/08/2024

Ref: BCS/115/24-25

QUOTATION

TO,
CYRIX HEALTHCARE PVT LTD

SL.NO	PRODUCT NAME	QTY	UNIT RATE	TAX 18%	TOTAL
01	BP Apparatus Make : Diamond delux Model : Delux Serial no : 9910208				
	Mercury and tank	1	686.44	123.56	810.00
	Glass tube	1	93.22	16.78	110.00
Grand Total					920.00

Terms & Conditions

- Delivery Within 8 Days After Confirmation Of Purchase Order
- Payment 50% Advance Balance 50% After Delivery Time



For, BCS HEALTH CARE PRIVATE LIMITED