

Date:

Contact Number:

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME **UNDER** NATIONAL HEALTH MISSION



SERVICE PROVIDER

No.:

Tender No. WO-37/2021-2022/698	KI		1697	17	
ISO 13485 : 2012 & ISO 9001-2008 CERTI	FIED COMPANY		ervice Agency		
Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com E-mail : bemp.kl@cyrix.in					
		ation Date :		24	
Health Facility Wech ALAPPUZHA		ation Date:			
		t:8181			
Address			•	1 1	
DIST ALAPPUZHA	Asset No.: 0412116				
Ph: 9074079517		0		CN-01WA	
		92.1375.130			
			ept 🗀 🖽 🗸	107.175	
Service Classification : Breakdown Call $\sqrt{}$	PMS _	Calibration	n Cust.	Training 🗌	
Problem Identified:	menosing	7			
Action Taken : Check the was	him onc	Land	thour the	2	
compressor motor with	plston	is de	fective		
	•••••	•••••••			
Completed Date:& & 2.24 Time:	Completed Date: 8/8/24. Time: 5:00PM Spare Required				
Spare Replaced Requested					
Description	Qty.	Part Nur	nber	PR Number	
1.					
2. 3.					
Cyrix Engineer					
O 1 0		Date	Start Time	End Time	
M) John aj. K		8(8124	4:30Pm	5:00pm	
Customer Remark Completed			Pendi	ng .	
I MO BOOK					
Customer Remark Completed Pending Pending Service Engineer Name: Customer Name: Deepu Xaver Service Pending					
Service Engineer Name: Micharda Ro, Gustomer Name: Deepu Xaver					
Signature: Signature:					
	and the second second		1 1 11 1	A RY / 16	

Contact Number :

Designation:

Hospital Seal :

10000 Jours

818124

9072522056

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI.	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	W&C HOSPITAL ALAPPUZHA
3	Name of Equipment with Make, Model and Serial Number	NEBULIZER MAKE :- COMFOCARE MODEL :- CN-02MC SN:- C 9021
4	Equipment ID & Barcode	127652 & 0412116
5	Date of purchase / Year of manufacture /Installation Date	26/02/2019
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	06/08/2024
9	Action taken	CHECK THE MACHINE AND FOUND THAT THE COMPRESSOR MOTOR WITH PISTON IS DEFECTIVE.
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDED FOR REPAIR
12	Cost of spares (specify parts and cost)	NA `

13	Asset Value	RS:- 1353/-	
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA	
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT ATTACHED	
16	Reasons for recommending the equipment as BER	CHECK THE MACHINE AND FOUND THAT THE COMPRESSOR MOTOR WITH PISTON IS DEFECTIVE. THIS MACHINE WAS INSTALLED ON 26/02/2019 AGED UP TO 5+ YEARS. QUOTATION IS NOT SUBMITTED SINCE SPARE IS NOT AVAILABLE IN THE MARKET. SO WE RECOMMENDING THE EQUIPMENT AS BER.	
17	Name & Signature of CYRIX Authority	MIDHUN RAJ R	


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommendation (Biomed









SUPERINTENDENT WAY A CHOSPITAL ALAPPUSHE

Br bom 98 & Nebalizer Empsk 7, 10 Jun par 17 1 d retail polonce Condemned as por order up C 2048/16/suprdit

able 15/18/16 and Auchoned of per order 100

C 2048/16 dated 10/8/17 and No-108

Condemned 2 3 546. 2/3/17 Sung Cal requipment Co-lock:
Received from store 1. * 4 sty Condemned as per the order NO B 920 (2)/17 sign and themptal magginera. 2 2 146 Condenved privil STORE SUPERINTENDER 1 3 Jh 26/2/19 12d from Store. POSENO 395 & Acre Redde) RS 1362. (My wate No 53-795 de 28/2/9 Fr Karunya Communty Mannay Count Hopel Dby) 8/3/19 Tood to pendapre 1 2 show 32/10/19 Remod from store

(4. low primus suctions)

(Store pros no - 116)

(4 - 5550/-1 M-5550/-10/3/3) nel from Store (Pound) Comst) 2 6 Thout to pase not: 144.159.