


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	PHC ERAMAM KUTTUR
3	Name of Equipment with Make, Model and Serial Number	WEIGHING MACHINE Make : SAMSO Model: NA SN:NA
4	Equipment ID/ Barcode	1340579 #127327
5	Date of purchase/ Year of manufacture/Installation Date	13-09-2019 (Actual installation date is 28.08.2019 Stock book copy attached for reference)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free- 04-08-2024
9	Action taken	Checked the machine and found that Machine is not switching on, Found mainboard, Load cells damaged. Need to replace these spares for further checking.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	715 /-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Service report attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that machine is not switching ON. Found that main board and load cells damaged. In software Equipment installed on 13-09-2019. As per the stock book installation date is 28.08.2019 aged up to 04 years 11 months. Quotation not submitted since spares are not available in the market. So we recommending for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


\*Not mandatory

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that the machine not switching ON. Aged up to 4 years & above. Its service cost economically not feasible. So recommended for BER as per BER protocol.


  
19/08/2024

Signature of JC BM (NHM)  
CONSULTANT BIOMEDICAL  
NATIONAL HEALTH COMMISSION  
KANNUR - 670002

Jessy. T. J

Jessy  
Nursing officer UOI

Date: 23/08/2024

  
Signature of Superintendent/Medical Officer (UOI)  
Dr. Samudra

Medical Officer  
Primary Health Centre  
P. O. Kuttur  
Kannur (Dist) 670 306

PRIMARY HEALTH CENTRE  
P. O. KUTTUR  
Date.....  
ER NAM-KUTTUR





# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

## CYRIX

HEALTHCARE PVT LTD

**No. :** 227588

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>PHC Eravamam Kuttur</u></p> <p>Address <u>Kannur</u> <u>Kerala</u></p> <p>Ph : <u>8606526534</u></p>	<p>Call Registration Date : <u>04-08-2024</u></p> <p>Caller ID : <u>127327</u></p> <p>Date of Visit : <u>05-08-2024</u></p> <p>Asset No. : <u>1340579</u></p> <p>EQPT Name : <u>weighing Machine</u></p> <p>Manufacture <u>Samsa</u> Model : <u>NA</u></p> <p>S. No. <u>NA</u> Dept. <u>OP</u></p>
--	--

**Service Classification :** Breakdown Call  PMS  Calibration  Cust.Training

**Problem Identified :** found that machine is not switching ON

**Action Taken :** Checked the machine and found that machine is not switching ON, found mainboard loadcells damaged. Need to replace these spares for further checking.

Completed  Date : 05-08-2024 Time : 11:00AM Spare Required



Spare Replaced  Requested

No.	Description	Qty.	Part Number	PR Number
1.	NA	NA	NA	NA
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Nitheesh P</u>	<u>05-08-2024</u>	<u>10:00AM</u>	<u>11:00AM</u>

**Customer Remark**  Completed  Pending

<p><b>Service Engineer Name :</b> <u>Nitheesh P</u></p> <p><b>Signature :</b> <u>[Signature]</u></p> <p><b>Date :</b> <u>05-08-2024</u></p> <p><b>Contact Number :</b> <u>8301871531</u></p>	<p><b>Customer Name :</b> <u>Jess</u></p> <p><b>Signature :</b> <u>[Signature]</u></p> <p><b>Date :</b> <u>5/8/24</u></p> <p><b>Contact Number :</b> <u>8606526534</u></p> <p><b>Designation :</b> <u>nursing officer</u></p> <p><b>Hospital Seal :</b> <u>[Seal]</u></p>
--	---





**CYRIX™**  
HEALTH CARE PVT LTD

**BIOMEDICAL EQUIPMENT MAINTENANCE  
PROGRAMME (BEMP)**



**KMSCL**  
KARNATAKA MEDICAL SERVICES CORPORATION LIMITED

**TOLL FREE NO: 1800 - 425-7669**

**BAR CODE - (8004-890615225)  
1340579**



**CYRIX™ BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)**  
**TOLL FREE NO: 1800 - 425-7669**  
BAR CODE - (8004-890615225)  
1340579



SAMSUNG



*[Handwritten Signature]*  
MEDICAL OFFICER  
PRIMARY HEALTH CENTRE  
ERAMAM-KUTTUR  
P. O. KUTTUR  
KANNUR (DIST) - 670 306

