


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**


**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

| Sl. No | Particulars  | Details   |
|--------|--|---|
| 1      | Name of District   | KANNUR  |
| 2      | Name of Hospital   | FHC MUNDERI   |
| 3      | Name of Equipment with Make, Model and Serial Number                           | UPS<br>Make: APC BY SCHNEIDER<br>ELECTRIC<br>Model: BX600IN<br>SN: B21750019431   |
| 4      | Equipment ID/ Barcode  | 1340041 #125294   |
| 5      | Date of purchase/ Year of manufacture/Installation Date                        | 08.08.2018<br>As per the stock book Installation Date Is 17.10.2018 (stock book copy attached for reference)                      |
| 6      | Warranty details (Yes/No)  | No warranty   |
| 7      | *AMC/ CAMC Period agreed at the time of Purchase                               | No AMC/CAMC   |
| 8      | Date of breakdown (Date of registration of complaint through email/ Toll free) | Toll free 24.07.2024.   |
| 9      | Action taken   | Checked the Equipment found Equipment is not switching ON, found that Mother board, Battery are defective. Enquired for quotation |
| 10     | Present status of the equipment (Fully damaged / partially damaged)            | Fully damaged   |
| 11     | Recommendations for repair (required service details)                          | No recommendations  |
|        | Cost of spares (specify parts and cost)  | Ups Battery-950/-<br>Main Board -2050/-<br><b>Total-3,000/-</b>   |



**MEDICAL OFFICER**  
**PRIMARY HEALTH CENTRE**  
**MUNDERI - 670 591**

|    |  |  |
|----|--|--|
| 13 | Asset Value  | 4,500/-  |
| 14 | * Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value               | 66.6 %   |
| 15 | Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not) | Cyrix Service report & quotation attached  |
| 16 | Reasons for recommending the equipment as BER  | Checked the Equipment found Equipment is not switching ON, found that Mother board, Battery are defective. Enquired for quotation. In Software Equipment installed on 08-08-2018. As per stock book installation date is 17.10.2018. Aged up to 5 years 9 months. Repairing cost is 66.6 % both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation. |
| 17 | Name & Signature of CYRIX Authority  | AVINASH T<br>   |


\*Not mandatory

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that machine not working main board, Battery are defective. The machine aged up to 5 years & above. its service cost economically not feasible as per guidelines. So recommended for BER as per BER protocol.

  
Signature of JC BM (NHM)  
16/8/24

Date: 19-8-24

Signature of  
Superintendent/Medical Officer (i/c)

  
MEDICAL OFFICER  
PRIMARY HEALTH CENTRE  
MUNDRI - 670 591

CONSULTANT BIOMEDICAL  
NATIONAL HEALTH MISSION  
MUNDRI - 670 591



**BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAMME  
UNDER  
NATIONAL HEALTH MISSION**



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

**CYRIX**  
HEALTHCARE PVT LTD

**No. :**  
229694

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report** 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

|  |   |
|--|---|
| Health Facility ..... <i>phe munderi</i> | Call Registration Date : ..... <i>24-7-24</i>                 |
| Address ..... <i>Kannur</i>              | Caller ID : ..... <i>125294</i>                               |
| ..... <i>Kerala</i>                      | Date of Visit : ..... <i>25-7-24</i>                          |
| Ph : ..... <i>9746146849</i>             | Asset No. : ..... <i>1340041</i>                              |
|  | EQPT Name : ..... <i>UPS</i>                                  |
|  | Manufacture <i>APC BY SCHNEIDER</i> Model : <i>BX 600 L M</i> |
|  | S. No. <i>B21750019431</i> Dept. <i>Laboratory</i>            |

**Service Classification :** Breakdown Call  PMS  Calibration  Cust.Training

**Problem Identified :** ..... *Mother board, battery defective*

**Action Taken :** *checked the equipment found equipment is not working on. Found that mother board, battery are defective. Engaged for replacement.*


Completed  Date : *25-7-24* Time : *11:00 am* Spare Required

Spare Replaced  Requested

| Description | Qty. | Part Number | PR Number |
|-------------|------|-------------|-----------|
| 1.          |      |             |           |
| 2.          |      |             |           |
| 3.          |      |             |           |

| Cyrix Engineer       | Date           | Start Time      | End Time        |
|----------------------|----------------|-----------------|-----------------|
| <i>Shyamkrishnan</i> | <i>25-7-24</i> | <i>10:00 am</i> | <i>11:00 am</i> |

**Customer Remark** Completed  Pending




**Service Engineer Name :** *Shyamkrishnan*  
**Signature :** *[Signature]*  
**Date :** *25-7-24*  
**Contact Number :** *8281188514*

**Customer Name :** *MECHANA PD*  
**Signature :** *[Signature]*  
**Date :** *25-7-24*  
**Contact Number :** *9746148849*  
**Designation :** *LAB TECHNICIAN*  
**Hospital Seal :** *9746148849*


**MEDICAL OFFICER**  
**PRIMARY HEALTH CENTRE**  
**MUNDARI - 670 591**

Self Declaration -  
Conforming to  
IS 16242 (Part 1) : 2014,  
R-83000450

MADE IN INDIA (UTTARAKHAND)



BX600C-IN



B21750019431

 **WARN**

00-690

80132950

QR/2D MATRIX






**CYRIX** BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)


TOLL FREE NO: 1800 - 425-7669

BAR CODE - (8004-890615225)

1340041




  
MEDICAL OFFICER  
PRIMARY HEALTH CENTRE  
KANNUR - 670 591

MEHAR P. D  
LABORATORY TECHNICIAN  


# UPS (MISPA VIVA)

U

| DATE       | FROM WHERE IT RECEIVED   | RECEIPT | ISSUE | BALANCE | SIGN<br>LT | SIGN<br>MO |
|------------|--|---------|-------|---------|------------|------------|
| 17/10/2018 | Received from pharmacy Store<br><div style="border: 1px solid black; padding: 5px; width: fit-content;">                     FSN: 8504. Lot: B21750019231<br/>                     Invoice: 201819-006090, RS. 2/08/2018<br/>                     BX 600C IN. SCHWEIDGER ELECTRIC                 </div> | 1       |       | 1       |            |            |
| 28/1/19    | used   |         |       |         |            |            |



MEDICAL OFFICER  
 PRIMARY HEALTH CENTRE  
 MUNDERI - 670 592

MCHNDR P.D  
 LAB TECHNICIAN



# SUPERCHIP TECHNOLOGIES

Room No. 459, 1st Floor, Casa Marina Complex, Near AKG Hospital, Talap, Kannur- 4.

Phone : 0497 2712559, Website : [www.superchiplaptoptraining.com](http://www.superchiplaptoptraining.com)

Ref. No. ....5515.....

Date..03/8/24.....

Quotation

To

Cynix health Care (P) Ltd.  
30/641B, Pella Ponnithuse  
Ernakulam (Dt) - Kerala .

|             |        |
|-------------|--------|
| ups battery | 950 .  |
| main board  | 2050 . |
| Total       | 3000 . |

**SUPERCHIP TECHNOLOGIES**  
ROOM No.459, 1<sup>st</sup> Floor  
Casa Marina Complex,  
Talap, Kannur - 670 004  
Ph: 04972712559, 9847401589