





**PROFORMA**  
**RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)**  
 BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Name of Hospital: PHC KEEZHPALLY	Name of District: KANNUR
Name of Equipment: BP APPARATUS	Equipment ID & Barcode: #131911 -1343427
Make: OMRON	Model: HBP 1300
Serial Number: N/A	Warranty details: NO Warranty
Date of purchase/Year of manufacture/Installation Date: 02-02-2018 (As per stock book Installation date is 09.03.2020 Stock book copy attached for reference)	Present status of the equipment: Fully damaged
Date of breakdown: 28.08.2024 Date of registration of complaint through email/ Toll free: Toll free	*AMC/CAMC Period agreed at the time of purchase: NO AMC/ CAMC
Action taken: Checked the Equipment found Equipment is not switching ON, found that Main Board, Pressure sensor and Display Defective. Need to replace these spares for further checking.	
Recommendations for repair (required service details): No recommendations	
Cost of spares (specify parts and cost): N/A	
# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: N/A	Asset Value: 2200/-
Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Service report attached	
Reasons for recommending the equipment as BER: Checked the Equipment found Equipment is not switching ON, found that Main Board, Pressure sensor and Display Defective. In software Equipment installed on 02.02.2018. As per the stock book installation date is 09.03.2020 aged up to 4 years 5 months. Quotation not submitted since spares are not available in the market. So we recommending for condemnation.	
AVINASH. T  06/9/24 Name & Signature of CYRIX Authority with date	
Remarks of Junior Consultant (Biomedical) NHM: <i>checked &amp; identified that machine not working, due to the main board, pressure sensor &amp; display are defective. its spare cost economically not feasible. Aged up to 4 years. So recommended for BER as per BER Protocol.</i>	
Recommended for BER (Yes/ No):	 06/09/24. Signature of JC BM (NHM)
Date: 06/09/24.	
Myisha. K-B MII Senior NURSING OFFICER Seal	 9/9/2024. Signature of Superintendent / Medical Officer (ii/c) CHC, KEEZHPALLY KANNUR DT. - 670704
Date: 9/9/2024 #Based on the period of life and value as per the BER guidelines. Attach Photograph	





# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

## CYRIX

HEALTHCARE PVT LTD

**No. :** 232039

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report** 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>PHC KEEZHPALLY</u></p> <p>Address <u>keezhpally</u> <u>KANNUR</u></p> <p>Ph : <u>9847 557 332</u></p>	<p>Call Registration Date : <u>28/08/2024</u></p> <p>Caller ID : <u>131911</u></p> <p>Date of Visit : <u>29/08/2024</u></p> <p>Asset No. : <u>1343 427</u></p> <p>EQPT Name : <u>Bp apparatus</u></p> <p>Manufacture <u>OMRON</u> Model : <u>HBP1300</u></p> <p>S. No. <u>04010265LF</u> Dept. <u>OP</u></p>
---	--

**Service Classification :** Breakdown Call  PMS  Calibration  Cust.Training

**Problem Identified :**  
Mainboard, Pressure sensor and display are defective.

**Action Taken :** checked the equipment and found equipment is not switching on. found that mainboard, Pressure sensor and display are defective. Need to replace these spares for further checking.

Completed  Date : 29/8/2024 Time : 11.30 AM Spare Required

Spare Replaced  Requested

1.	Description	Qty.	Part Number	PR Number
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Sayanth</u>	<u>29/8/2024</u>	<u>10.30 AM</u>	<u>11.30 AM</u>

**Customer Remark** Completed  Pending

**Service Engineer Name :** Sayanth  
**Signature :** [Signature]  
**Date :** 29/8/2024  
**Contact Number :** 86063 45195

**Customer Name :** AYISHA K.S  
**Signature :** [Signature]  
**Date :** 29/8/24  
**Contact Number :** 9847557332  
**Designation :** SNO  
**Hospital Seal :**

MEDICAL OFFICER  
CHC, KEEZHPALLY  
KANNUR DT. 670704





**OMRON**  
**HBP-1300 (HBP-1300-AP)**

RATING 6V  $\approx$  1.6A  
 AC ADAPTER 60220H1040SW-E  
 BATTERY HXA-BAT-2000

**SN 04010265LF**

OMRON HEALTHCARE Co., Ltd.  
 Kyoto, JAPAN

OMRON HEALTHCARE EUROPE B.V.  
 Scorpius 33, 2132 LR Hoofddorp  
 THE NETHERLANDS

Asia Pacific HQ:  
 OMRON HEALTHCARE SINGAPORE PTE LTD.

**CE 0197**

MADE IN CHINA



MEDICAL OFFICER  
 CHC, KEEZHPALLY  
 KANNUR DT. - 670704

9/9/2024  
 Dr. Praveen S. Chandran