


24/08/24
J.Thu

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	IDUKKI
2	Name of Hospital	THQH ADIMALY
3	Name of Equipment with Make, Model and Serial Number	Equipment name: Oto Acoustic Emission Screener (OAE) Make: Interacoustics Model: Titan Serial number: 915777
4	Equipment ID & Barcode	ID: 113545 Barcode: 0620030
5	Date of purchase / Year of manufacture /Installation Date	25/3/2014
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	27-05-2024 (Toll-free)
9	Action taken	Check and find that the display, mainboard, and probe are defective. Need to be replace this spares for further checking and working condition of the equipment. Enquired spare with OEM
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair
12	Cost of spares (specify parts and cost)	1. CLINICAL EXTENSION CABLE -71,500/- 2. Display for Titan -29,500/- 3. Main Board -1,10,000/- Total -2,48,980/-

13	Asset Value	279360
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	89%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	The Cyrix service report and OEM quotation attached
16	Reasons for recommending the equipment as BER	Check and find that the display, mainboard, and probe are defective. The equipment was installed on 25/3/2014 and covered up to 10+ years. Repairing cost of the equipment is 89%, both criteria met. So recommending the equipment for condemnation as per the tender clause 5.3.14.1.
17	Name & Signature of CYRIX Authority	Jithu Abraham 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


• Original supplier is ALPS.

The estimate attached with this Report is from vt Healthcare systems with the authorization letter provided by Interacoustics and Otac Hearing solutions. Due to the delay of to get estimate RBER report received on 24/08/2024.

Rajitha
27/08/2024
Consultant Biomedical
National Health
Authority

Signature of JC BM (NHM)

Date


Signature of
Superintendent / Medical Officer (i/c)
Tamil Nadu State Health Services Commission
Chennai



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 178476

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>THCCH</u></p> <p>Address : <u>Adimaly</u> <u>Idukki</u></p> <p>Ph : <u>9526657262</u></p>	<p>Call Registration Date : <u>27-5-24</u></p> <p>Caller ID : <u>113545</u></p> <p>Date of Visit : <u>28-5-24</u></p> <p>Asset No. : <u>0620090</u></p> <p>EQPT Name : <u>OAE Machine</u></p> <p>Manufacture <u>Interacoustics</u> Model : <u>Titan</u></p> <p>S. No. <u>0915777</u> Dept. <u>Labour Room</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not Working

Action Taken : We checked the machine and found problems with the display, mainboard and probe. we are taking it for further testing and evaluation.

Completed Date : 28-5-24 Time : 12:00 PM Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1. <u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
2. <u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
3. <u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>

Cyrux Engineer	Date	Start Time	End Time
<u>Emmanuel</u>	<u>28-5-24</u>	<u>10:00 AM</u>	<u>12:00 PM</u>

Customer Remark Completed Pending

Service Engineer Name : Emmanuel
Signature : [Signature]
Date : 28-5-24
Contact Number : 2593847174

Customer Name : Thakara
Signature : [Signature]
Date : 28-5-24
Contact Number : [Number]
Designation : SIN
Hospital Seal : [Seal]



Handwritten notes and signatures:
Superintendent
Taha (K...)
Adul...
Kochi District P...-685501



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 178477

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>THQH</u></p> <p>Address <u>Adimaly</u> <u>Idukki</u></p> <p>Ph : <u>9526657262</u></p>	<p>Call Registration Date : <u>27-5-24</u></p> <p>Caller ID : <u>113545</u></p> <p>Date of Visit : <u>28-5-24</u></p> <p>Asset No. : <u>0620030</u></p> <p>EQPT Name : <u>OAE machine</u></p> <p>Manufacture <u>Inteacoustics</u> Model : <u>Titan</u></p> <p>S. No. <u>0915777</u> Dept. <u>Labour Room</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : not working

Action Taken : After inspecting the machine we've determined that the display mainboard and probe are defective and need to be replaced. These replacements are necessary for further testing and to ensure the equipment is in proper working condition. Enquired spare with OEM

Completed Date : 17-8-24 Time : 1:10 pm Spare Required

Spare Replaced Requested


No.	Description	Qty.	Part Number	PR Number
1.	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
2.				
3.				

Cyrux Engineer	Date	Start Time	End Time
<u>Emmanuel</u>	<u>17-8-24</u>	<u>12:00 pm</u>	<u>1:10 pm</u>

Customer Remark Completed Pending

Service Engineer Name : Emmanuel
Signature : [Signature]
Date : 17-8-24
Contact Number : 7593897124

Customer Name : [Signature]
Signature : [Signature]
Date : 17/8/24
Contact Number : [Number]
Designation : SIN
Hospital Seal :





jithu abraham <jithuabrahamcyrix@gmail.com>

Enquiry for TITAN OAE Serial Number 915777

2 messages

Anjitha T L <purchasecyrix2@gmail.com>

Wed, Aug 14, 2024 at 11:01 AM

To: VK Healthcare <vkhealthcaresystem@gmail.com>

Cc: "Cyrix Purchase Mgr." <purchasemgr@cyrix.in>, jithu abraham <jithuabrahamcyrix@gmail.com>, DM Abijith-KLBEMP <dm2.klbemp@cyrix.in>

Dear Sir,

Please share the quotation for the below attached spare.

- 1 CLINICAL EXTENSION CABLE
- 2 Display for Titan
- 3 Main Board

Machine details are below

make: Titan

model: type2

sn..SN0915777

Hospital name: THQH Adimaly

Please do the needful at the earliest.

--

Thanks & Regards

Anjitha T L

Sr. Purchase Executive

PH:- 9947719111

purchasecyrix2@gmail.comwww.cyrixhealthcare.com**Cyrix Healthcare Pvt Ltd**

| 30/641 B | Pettah Jn | Poonithura | Cochin -38 | Kerala | India

KERALA || KARNATAKA || TAMIL NADU || UTTAR PRADESH

VK Healthcare <vkhealthcaresystem@gmail.com>

Wed, Aug 14, 2024 at 5:39 PM

To: Anjitha T L <purchasecyrix2@gmail.com>

Cc: "Cyrix Purchase Mgr." <purchasemgr@cyrix.in>, jithu abraham <jithuabrahamcyrix@gmail.com>, DM Abijith-KLBEMP <dm2.klbemp@cyrix.in>, Vikash Rana <ranavikash87@gmail.com>



V K HEALTHCARE SYSTEM

SHOP NO-01, GROUND FLOOR, KRISHNA COMPLEX,
NEAR PNB BANK, KUND ROAD
BEHROR Rajasthan 301701
India
Phone 7678531115
Email- vkhealthcaresystem@gmail.com
Website-www.vkhealthcaresystem.com
GSTIN 08AZFPV9472M1ZB

Quotation

: VK/EST/24-25/95 Place Of Supply : Kerala (32)
Estimate Date : 14/08/2024
Expiry Date : 13/09/2024

Bill To

CYRIX Healthcare Private Limited (Kerala)
1st Floor,30/641B
Kochi Dhanushkodi Road
Ernakulam
682038 Kerala
India
GSTIN 32AAFCC2499H2ZM

Ship To

1st Floor,30/641B
Kochi Dhanushkodi Road
Ernakulam
682038 Kerala
India

Subject:

Regarding Titan SN0915777

#	Item & Description	HSN/SAC	Qty	Rate	IGST		Amount
					%	Amt	
1	CLINICAL EXTENSION CABLE	90330000	1.00	71,500.00	18%	12,870.00	71,500.00
2	Display For Titan	9033	1.00	29,500.00	18%	5,310.00	29,500.00
3	Main Board	9033	1.00	1,10,000.00	18%	19,800.00	1,10,000.00

Total In Words
Indian Rupee Two Lakh Forty-Eight Thousand Nine Hundred Eighty Only

Sub Total 2,11,000.00
IGST18 (18%) 37,980.00
Total ₹2,48,980.00

Notes

Looking forward for your business.

Company's Bank Details: V K Healthcare System
Bank Name: State Bank of India
A/C No: 40255396231
IFSC and Branch: SBIN0005945, ADB, Behror

Terms & Conditions

- Prices are FOR Destination.
- GST @ Extra. In case of any changes in the tax structure/levies, the same shall be applicable at the time of invoicing and shall be borne by you.
- Delivery : 4 weeks from the date of receipt of your commercially and technically clear order.
- Payment : 100% advance by Demand Draft/Cheque/NEFT/RTGS.
- Other Taxes/Duties/Levies: Any local taxes or duties that are not applicable now but become leviable from the date of supply/bill shall be charged extra as applicable.
- Subject to Behror jurisdiction.
- Offer is subject to Force Majeure Clause.
- For Calibration- Need to send complete equipment through courier at our Head office.
- For Calibration- We need approximate 7 day in our office for complete process.



Authorized Signature

Authorization Letter

We M/s Otic Hearing Solutions Pvt. Ltd., an authorized distributors of Interacoustics Denmark, here by authorized M/s V K Healthcare System, Shop No.- 1, Ground Floor, Krishna Complex, Near PNB Bank, Kund Road, Behror-301701 (India) as an authorized exclusive Dealer for our brand of our Products and all Audiology Equipment's i.e. Audiometer, Tympanometer, OAE, ABR (BERA), Vertigo System and Hearing Aid Analyser System of Interacoustis, Denmark.

V K Healthcare System is authorized to quote commercially in GEM and Govt. Tender & Pvt. Sector and for INTERACOUSTICS, Denmark on behalf of M/s Otic Hearing Solutions Pvt. Ltd.

V K Healthcare System is also authorized to Sale, Service, Repair and maintenance of all our Products and Audiology Equipment's.

Note: This Authorization Valid for Three Years (From 1st April, 2024 to 31st March, 2027).

For Otic Hearing Solutions Pvt. Ltd.,

Ashish





Authorized Signatory



Titan

Test: Out of e
DP-1 - 6kHz



0123 2014

Automatic Equipment
MP-Type1, ABR-Type 2

DAE-Type 2
Contains Transmitter Module

FCC ID: QDQWT12

DAE Type: NP120-37V-L-000



Manufactured by
Interacoustics AS
DK-5610 Assens



MP Titan

8128122

50281577



0820074

Interacoustics
Headset
Model: NP120-37V-L-000


0820053

STOCK BOOK OF T.H.Q.H. ADIMALI

Old Acoustic Emission SCREEPER.

Name of article

Date	No. & Date of Voucher or invoice	From whom received or to whom issued	Receipt	Issued	Balance after each transaction	Initials of receiver	Batch No.	Date of Expiry	Price	Manufacturer Name
		B/F Page No.								
25/3/14		Received from store								
		Invoice NO 70072 dt 12/3/14					AKPS			
		International cobaltabad (UP)								
		Supply Order no: 015/2014/513								
		RS 2,79,360 warranty 3 years.								
		model 71191 clinical OAC.								
		Serial no 0915777.								
		Phone no: 65266729.								
		Email sales @ alph. in.								INDIA



[Handwritten Signature]
 Superintendant
 T.H.Q.H. Hospital
 Adimali, District
 [Handwritten Address]