

**PROFORMA
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

Name of Hospital: THQH MANNARKKAD	Name of District: PALAKKAD
Name of Equipment: STERILIZER	Equipment ID & Barcode: #133398 - 0920599
Make: GETIDY	Model: JY23
Serial Number: 201207119	Warranty details: No Warranty
Date of purchase/Year of manufacture/ Installation Date: 17/10/2012	Present status of the equipment: Fully damage
Date of breakdown: 04/09/2024 Date of registration of complaint through email/ Toll free): Toll Free	*AMC/ CAMC Period agreed at the time of purchase: No AMC/CAMC

Action taken: Checked the flash autoclave found steamer and control boards including the transformer damaged. Need to replace these spare for further checking.

Recommendations for repair (required service details): No recommendations

Cost of spares (specify parts and cost): N/A

# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: N/A	Asset Value: 82467/-
---	----------------------

Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Service report and OEM EOL letter attached

Reasons for recommending the equipment as BER: Checked the flash autoclave found steamer and control boards including the transformer damaged. Need to replace these spare for further checking. Equipment installed on 17/10/2012 and aged up to 11 years 10 months. OEM informed that spare parts are not available this model is obsolete, letter issued. As per tender clause 5.3.14.2 we recommending the equipment for condemnation.

AKHILESH P
[Signature]
Name & Signature of CYRIX Authority with date 23/09/24

Remarks of Junior Consultant (Biomedical) NHM:
Equipment installed on 17/10/2012 and aged up to 11 years OEM informed that spare parts are not available and the model is obsolete. Both criteria of RBER met. Hence recommended for BER.

Recommended for BER (Yes/ No): Yes	Consultant (Biomedical) NHM (Arogyakeralam), Palakkad <i>[Signature]</i> Signature of JC BM (NHM) Consultant (Biomedical Engg) NHM (Arogyakeralam), Palakkad
Date:	

Date: 26/9/24 Seal Signature of Superintendent / Medical Officer (i/c)

*Not mandatory #Based on the period of validity as per the BER guidelines *Attach Photograph



[Signature]
സൂപ്രണ്ട്
താലൂക്ക് ആസ്ഥാന ആശുപത്രി
മണ്ണാർക്കാട്



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 173677

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>THPH Mannarkkad</u></p> <p>Address <u>Palakkad</u></p> <p>Ph : <u>9495132421</u></p>	<p>Call Registration Date : <u>04/09/2024</u></p> <p>Caller ID : <u>133398</u></p> <p>Date of Visit : <u>05/09/2024</u></p> <p>Asset No. : <u>0920599</u></p> <p>EQPT Name : <u>Flash autoclave / Sterilizer</u></p> <p>Manufacture <u>Credity</u> Model : <u>JY23</u></p> <p>S. No. <u>201207119</u> Dept. <u>Dental</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Leakage problem

Action Taken : checked the equipment. Found leakage problem with steamers and control board. Faulty. Need to Replace these spare part further checking.


Completed Date : 05/09/24 Time : 10:00 am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Akhilesh P</u>	<u>05/09/24</u>	<u>10:00 am</u>	<u>12:00 pm</u>

Customer Remark Completed Pending



<p>Service Engineer Name : <u>Akhilesh P</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>05/09/24</u></p> <p>Contact Number : <u>7593847154</u></p>	<p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>5/09/24</u></p> <p>Contact Number : <u>9495132421</u></p> <p>Designation : <u>Dental Surgeon</u></p> <p>Hospital Seal :</p>
--	--

JAIGURU SALES & SERVICES

The Team For Sterilization

XIII/385, N.Paravur, Ernakulam, Kerala-683519

Ph: 8089960227

Mob: 09447043821

To

Cyrix Health care Pvt. Ltd,Ernakulam

Ref: Qtn. /92/2024-25 Dated 19-09-2024

Sir,

Sub: Flash Autoclave Repair at Govt. Hospital Mannarkad, Palakkad Dist.

After inspecting your GETIDY machine (Serial No. 201207119), we found that the steamer and control boards, including the transformer, need replacement.

However, these parts are no longer available due to an update in the machine's design, making the model obsolete. The new parts are only compatible with the latest version, which does not fit your older model.

We recommend discarding the equipment and considering an upgrade to the latest version for continued support.

So please do the needful,

Expecting your valued co operation,

For **Jaiguru Sales & Service**

Proprietor
Remesh Kumar





REQUIRED QUOTATION FOR AUTOCLAVE 0951874 # KL 921 @ DH PALAKKAD , PALAKKAD

2 messages

Akhilesh P <akhileshcyrix@gmail.com>

Thu, 19 Sept, 2024 at 11:51 pm

To: Jaiguru Sales & Service Kerala <Jssindiaster@gmail.com>

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>

Dear sir

Please share the price and stock availability of

1. Pressure Guage
2. Safty valve
3. Relief valve
4. Silicon gasket
5. Heating coil
6. Inner chamber
7. Temperature controller

@ DH PALAKKAD , PALAKKAD DISTRICT

Thanks & Regards

AKHILESH P
DISTRICT INCHARGE - PALAKKAD
Bemp-Kerala
Mobile : +91 7593847154
Email : akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B, Petta, Punithura
Ernakulam- 682038
www.cyrixhealthcare.com

Jaiguru Sales & Service Kerala <jssindiaster@gmail.com>

Fri, 20 Sept, 2024 at 8:22 pm

To: Akhilesh P <akhileshcyrix@gmail.com>


[Quoted text hidden]

For Jaiguru Sales & Service
Remesh Kumar
Proprietor
Jaiguru Sales & Service
N.Paravur, Ernakulam, Kerala-India
Ph: 8089960227 Mob: 09447043821



Handwritten signature in green ink.

സുപ്രസ
താലൂക്ക് ആസ്ഥാന ആശുപത്രി
മണ്ണാർക്കാട്



HEALTH CARE PVT.LTD
SIP SERVICE PROVIDER
ACTIVE MAINTENANCE SERVICE
DOMS ON, KOLLONDA
TIRUNELVELI, KERALA
CONTACT NO: 0471 271134

CYRIX
TOLL FREE NO: 1800 - 425-7669
BAR CODE - (8004-80813225)
09205596

Genigy CE
220V-230V, 50Hz, 1500W
Model: JY-23
2012-07 ECREP
S.N.: 201207119

Warning Symbol: **A** (Warning of electric shock)
Manufacturer: Jiyangang Systems
18 Wanchang Dasha, Puzhuozhong
Wanchang MES (GAD)
浙江奥普子行器械有限公司
JIYANG GLTIDY M.L.C.C.
ADD: TONGQIN INDUSTRIAL ZONE, WUYI ZHESHANG, CHINA