



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

No : 1005001

CYRIX[®]

HEALTH CARE PVT LTD

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi- 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | Email : bemp.kl@cyrix.in

Health Facility..... <u>THQH</u>	Call Registration Date : <u>5/7/2024</u>
Address..... <u>Cheruthala</u>	Caller ID : <u>121342</u>
..... <u>Alappuzha</u>	Date of Visit : <u>6/7/24</u>
Ph : <u>9281069322</u>	Asset No : <u>0420079</u>
	EQPT Name : <u>Suction Apparatus</u>
	Manufacture. <u>Supreme</u> Model : <u>NA</u>
	S. No..... <u>NA</u> Dept. <u>WARD - 5</u>

Service Classification : Breakdown call PMS Calibration Cust. Training

Problem Identified : Suction Apparatus is not getting ON

Action Taken : checked the machine and found that the suction bottles are broken and motor is defective suction metallic body is Rusted and need to replace these spars and further checking and working condition of Equipment.

Completed Date : 6/7/24 Time : 11:00 am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Nasut</u>	<u>6/7/24</u>	<u>10:00am</u>	<u>11:00am</u>

Customer Remark	Completed	Pending
<u>Not working.</u>		
Service Engineer Name : <u>Nasut</u>	Customer Name : <u>SHYLI AS.</u>	
Signature: <u>Nasut</u>	Signature: <u>[Signature]</u>	
Date: <u>6/7/24</u>	Date: <u>6/7/24</u>	
Contact Number: <u>9526749524</u>	Contact Number: <u>9847189787</u>	
	Designation : <u>SNO</u>	
	Hospital Seal	



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

No : 1005011



ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi- 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | Email : bemp.kl@cyrix.in

Health Facility..... <u>THQH</u>	Call Registration Date : <u>5/7/24</u>
Address..... <u>Cherthala</u>	Caller ID : <u>121342</u>
..... <u>Alappuzha</u>	Date of Visit : <u>6/7/24</u>
Ph : <u>8281069322</u>	Asset No : <u>0420079</u>
	EQPT Name : <u>Suction Apparatus</u>
	Manufacture <u>Supreme</u> Model : <u>NA</u>
	S. No..... <u>NA</u> Dept..... <u>wards</u>

Service Classification : Breakdown call PMS Calibration Cust. Training

Problem Identified : Suction Apparatus is not getting on.....

Action Taken : checked the machine and found that the suction bottles are broken and motor is defective suction metallic body is rusted Enquired spare with the vendor.....

Completed Date : 23/8/24 Time : 11:00 am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrux Engineer	Date	Start Time	End Time
<u>Nasef</u>	<u>23/8/24</u>	<u>11:00 am</u>	<u>11:00 am</u>

Customer Remark letter 7 letter solo Completed Pending not working

Service Engineer Name : Nasef
Signature: [Signature]
Date: 23/8/24
Contact Number: 952677952



Customer Name :
Signature:
Date:
Contact Number:
Designation :
Hospital Seal

[Signature]
SUPERINTENDENT
ALUK HEAD QUARTERS HOSPITAL
CERTHALA

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	THQH CHERTHALA
3	Name of Equipment with Make, Model and Serial Number	SUCTION APPARATUS MAKE:- SUPREME ENTERPRISES MODEL :- NA SN:- NA
4	Equipment ID & Barcode	121342 & 0420079
5	Date of purchase / Year of manufacture /Installation Date	11/01/2010
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	05/07/2024
9	Action taken	CHECKED THE MACHINE AND FOUND THAT THE SUCTION BOTTLES ARE BROKEN AND MOTOR IS DEFECTIVE. SUCTION METALLIC BODY IS RUSTED, ENQUIRED SPARE WITH THE VENDOR
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDED FOR REPAIR.
12	Cost of spares (specify parts and cost)	SUCTUION MOTOR = 5650 <u>SUCTION BOTTLES (2) =2500</u> <u>TOTAL = 8150</u> (without tax amount)

13	Asset Value	RS:- 10200/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	79%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT AND SPARE QUOTATION ATTACHED
16	Reasons for recommending the equipment as BER	CHECKED THE MACHINE AND FOUND THAT THE SUCTION MOTOR AND SUCTION BOTTLES ARE DEFECTIVE. THE EQUIPMENT WAS INSTALLED ON 11/01/2010 AGED UP TO 14+ YEARS. COST OF SPARE IS 79% AND ECONOMICALLY NOT VIABLE. MET BOTH CRITERIA AS PER THE TENDER CLAUSE 5.3.14.1 SO WE RECOMMENDING THE EQUIPMENT AS BER.
17	Name & Signature of CYRIX Authority	NASEEF K N <i>Naseef</i>

*Not mandatory **#Based on the period of life and value as per the BER guidelines**

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for BER

Jyothish Thomas
21/08/24
JYOTHISH THOMAS
Consultant (Biomedical Engineering)
NHM ALAPPUZHA
Signature of JC BM (NHM)

For consideration

Date



[Signature]
23/8
Signature of
Superintendent Medical Officer (i/c)
SUPERINTENDENT
BALUK HEAD QUARTERS HONNAYUR
CHERTHALA

*Letter T
Letter
SWS*

Stock Register

97

Name..... Suction APPARATUS

Remarks	Date	Received from or Issued to	Inv. No. or Issue	Rate Rs. Ps.	Receipts	Issues	Bal :	Remarks
	21/3/05	Recd from store (Cost - 12000/- Car)	store pass no 331		4		4	8
Medics H/A -	21/4/05	Tr out to hd: vi	(stock register page-239)			2	2	8
	11/1/10	Tr in for old stock and from store 15/1/2002	Page - 250			1	3	
		Tr out to magd. a.i.				1	2	300
	21/3/05	9						
	21/3/05	Tr. out to conservable register	page no 10			1	1	
	24/4/17	Conservable register						
	3/6/2023	Tr in from conserved register page no.			2	-	3	
	15/1/2024	Recd Tr in from W.I.V (Page no 165. Stock register)			1		4	
		Conservable register						(2)



Letto
 Sano
 RA
 POK
 23/8
 SUPERINTENDENT
 SUKH HEAD QUARTERS HOSPITAL
 CHERTHALA



9744473043, 9744473243

cloud99biotech@gmail.com

1 KMC/XIII-1333
Room No: 22,
CSI Golden Jubilee Complex
Baker Hill
Shastri Road
Kottayam

CLOUD99 BIOTECH

GSTIN: 32AMWPT5633Q1Z0

MSME NO: : UDYAM-KL-07--0030714

State: 32 - Kerala

DL NO: : KL/KTM/MD42/2023/000015

Estimate

Estimate For:

ABHILASH A

CYRIX HEALTHCARE PRIVATE LIMITED
1 ST FLOOR, 30/641B,
KOCHI DHANUSHKODI ROAD, POONITHURA,
ERNAKULAM 682038

Contact No.: 8157068890

GSTIN Number: 32AAFCC2499H2ZM

State: 32-Kerala

Estimate No.: C99B-QTN-51

Date: 22/08/2024

Place of Supply: 32-Kerala

#	Item name	HSN/ SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	SUCTION JAR (SUCTION BOTTLES)	90189099	2	Nos	₹ 1,250.00	₹ 300.00 (12%)	₹ 2,800.00
2	SUCTION MOTOR (MOTOR FOR HOSPITAL SUCTION)	9018	1	-	₹ 5,650.00	₹ 1,017.00 (18%)	₹ 6,667.00
Total			3			₹ 1,317.00	₹ 9,467.00

Pay To:

Bank Name : UNION BANK OF INDIA, KOTTAYAM

Bank Account No. : 361201010035646

Bank IFSC code : UBIN0536121

Account holder's name : CLOUD99 BIOTECH

Sub Total	₹ 8,150.00
SGST@6%	₹ 150.00
CGST@6%	₹ 150.00
SGST@9%	₹ 508.50
CGST@9%	₹ 508.50
Total	₹ 9,467.00

Description

EQUIPMENT: HOSPITAL SUCTION APPARATUS
BAR CODE: 0420079
TICKET ID: 121342

Estimate Amount In Words

Nine Thousand Four Hundred Sixty Seven Rupees only

Terms And Conditions

Thanks for doing business with us!

For : CLOUD99 BIOTECH



Authorized Signatory



Abhilash A <abhilashacyrix@gmail.com>

SUCTION APPARATUS Estimate invoice details

1 message


cloud99biotech@gmail.com <cloud99biotech@gmail.com>
To: ABHILASHACYRIX@gmail.com

Thu, Aug 22, 2024 at 5:43 PM

Dear ABHILASH A,
Thanks for doing business with us. Below are your invoice details.
Also attached are the PDF of invoice for your convenience.
Estimate:

Amount: 9467

Thanks & Regards

 **vyapar_print_22_08_2024_17_38_44.pdf**
184K