



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 203487

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Service Report

<p>Health Facility : <u>THRH</u></p> <p>Address : <u>Parassak</u> <u>Tarvandrum</u></p> <p>Ph :</p>	<p>Call Registration Date : <u>4/4/24</u></p> <p>Caller ID : <u>104720</u></p> <p>Date of Visit : <u>5/4/24</u></p> <p>Asset No. : <u>0120438</u></p> <p>EQPT Name : <u>Stetliper</u></p> <p>Manufacture : <u>NA</u> Model : <u>NA</u></p> <p>S. No. : <u>NA</u> Dept. : <u>Dental op</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not beating, Door band
gasket defective

Action Taken : Checked and found door band
gasket and motor coil defective. Need to
replace the spare for further
checking and working condition of the
equipment. Enquired spare with OEM.

Completed Date : 5/4/24 Time : 11am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Asith</u>	<u>5/4/24</u>	<u>10.30am</u>	<u>11am</u>

Customer Remark : [Signature]

Completed Pending


<p>Service Engineer Name : <u>Asith</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>5/4/24</u></p> <p>Contact Number : <u>9593847111</u></p>	<p>Customer Name : <u>Dr. Asith</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>5/4/24</u></p> <p>Contact Number : <u>9447961215</u></p> <p>Designation : <u>Dentist / Surgeon</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
---	--


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

531

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	THQH PARASSALA
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : STERILIZER Manufacturer : Local Model : NA Sl: NA
4	Equipment ID/ Barcode	104720/0120438
5	Date of purchase/ Year of manufacture/Installation Date	17/09/2019
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	05/04/2024 (Toll free)
9	Action taken	Checked the found autoclave door bend, gasket and heater coil defective. Need to replace these for further checking
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not recommending for Repair
12	Cost of spares (specify parts and cost)	 <ul style="list-style-type: none"> 1. Door - 4574.86/- 2. Gauge - 902.7/- 3. Coil - 1770/- 4. Power code - 643.1/- 5. Safety valve - 920.4/- 6. Gasket - 784.7/- <p>TOTAL = 9595.76</p>

13	Asset Value	Rs . 15000/-
14	Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	63.97%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached and Quotation from vendor attached.
16	Reasons for recommending the equipment RBER	Checked and found autoclave door bend, door gasket and heater coil defective. The unit was installed on 17/09/2019 and covered upto 5+ years. The repairing cost is 63.97%, As per the tender clause 5.3.14.1 both criteria met. So recommending the unit for condemnation.
17	Name & Signature of CYRIX Authority	Kasyep PV 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Door bend , Door gasket and heater coil defective . So can be RBER as per tender conditions


MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram



10.7.2024
Signature of JC BM (NHM)


Date:



Signature of Superintendent Medical Officer (S.M.O.)







CLOUD99 BIOTECH

Office : 97444 7304

Service : 97444 7324

Sales and service of all kinds of medical equipments
Room No: 22, First Floor, CSI Golden Jubilee Complex,
Behind Shastri Road Waiting Shed, Kottayam-686001
Email: cloud99biotech@gmail.com

QUOTATION

Ref No: C99B/0150/2023-24

Date: 17/04/2024

To,

THQH, PARASSALA

TRIVANDRUM

Dear Sir

We are pleased to submit a quotation for **THQH, PARASSALA, TRIVANDRUM** for Autoclave.
Barcode is **0120438, Ticket ID- 104720.**

SL No	ITEM NAME	PRICE PER UNIT	GST	PRICE INCLUDING GST
1	DOOR	3877	18%	4574.86
2	GAUGE	765	18%	902.7
3	COIL	1500	18%	1770
4	POWER CODE	545	18%	643.1
5	SAFETY VALVE	780	18%	920.4
6	GASKET	665	18%	784.7
	TOTAL			9595.76

Terms & Conditions

1. Taxes: GST @ 18 % inclusive
2. Payment Terms: 100% advance payment
3. Quotation validity: 15 days from date of quotation


We hope you will find our rates are competitive and wait for your valued order.

Thanking you,

Yours Faithfully

FOR CLOUD99 BIOTECH


മുഖ്യമന്ത്രി
മുഖ്യമന്ത്രിയുടെ സെക്രട്ടേറിയം
കൊച്ചി





AUTHORIZED SIGNATORY

we deal with sales and service of all kinds of hospital equipments, neonatal equipments, laboratory equipments, dental equipments, suction, hospital furniture, radiology equipments, physiotherapy equipments, all type of autoclaves, ICU equipments, etc.

deal with sales and service of all kinds of Hospital equipments, Neonatal equipments, Laboratory equipments, dental equipments, Hospital furniture, Radiology equipments, Physiotherapy equipments, all type of Autoclaves, equipments etc.



Handwritten signature or text, possibly a name, located at the bottom right of the page.



Handwritten signature

ഡുപണ്ട്
സാജുക്ക് ആന്ധ്രൻ ആശുപത്രി
കൊല്ലം

