

### BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

# CYRIX

No.:

231301

HEALTHCAREPVTLTD

ISO 13485 : 2012 & ISO 9001-2008 CEF	TIFIED COMPANY	AERB Approved S	service Agency			
Service Report 30/64 1 B, Petta Junction Ph: 98472 99500 Website: w	ww.cyrix.com	E-mail : bemp.kk	@cyrix.in			
	Call Regist	ration Date :	20/6/	2.0.24		
Health FacilityH.Q.H.	Caller ID :	1142=	14			
Address	Date of Visit: 21/6/2024					
	Asset No. :	0420	258			
Alappusta			u cot			
Ph: 9074001252	· Manufactui	e Janal	K Model : A	CP.EX. 600		
	S. No. X.L.	840020.F1.2.A	Dept. Diale	sis unit		
Service Classification : Breakdown Call	PMS [	Calibratio	on Cust.	Training 🗌		
Problem Identified: \	C. D. A. 1.S	+a.~	getting			
Completed Date: 21.16.204time	ad wo	aring.	.cocd.it	Required		
Spare Replaced Requested						
Description	Qty.	Part Nu	ımber	PR Number		
1.						
2.						
3.						
Cyrix Engineer		Date	Start Time	End Time		
Nascet		216/24	9:30 am	12:00 Pm		
Customer Remark  Not working	Completed		Pendi	ng		
Service Engineer Name : Naset			AMPIL Y.	THE REAL PROPERTY.		
Signature : Nort	Signatu Date :	ire:	21/6/24			
Date: 01/6/24	Confac	Number: 9	21111			
	Design	ation:	96140 984			



## BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

No.:

231311

	CAREPVT			
ISO 13485 : 2012 & ISO 9001-2008 CER  Service Report 30/64 1 B, Petta Junction Ph. 98472 99500 Website : w	Poonithura, Koch	i - 682 038, Ker	ala	
Service Report Ph: 98472 99500 Website: w				20.24
Harlet Facility TUON			14	
Health FacilityH.Q.H.	Data of Visit		,124	
Address			255	
Alappusha			U cot	
Ph: 9074001852				ACP EX 6000
Manne of Equipment on an				Hide Die
		Calibration		Training 🗌
Service Classification : Breakdown Call	PMS 🗌	Calibration	n Cust.	
Problem Identified : TCU C	ot is	rot 3	ethog	oN
	0			
Action Taken :	a tour	sol co	MXO!	Chailten and T
box is defective. Ex	zwid sol	3. Pads		F. K.L (3. L (9)
Completed Date : 24 7 24 Time :	· 12:0020		Spare	Required
Spare Replaced Requested Requested	· mannaman,			
Description	Qty.	Part Nur	mber	PR Number
1.				
2.				
3.				
Cyrix Engineer		Date	Start Time	End Time
Nasert		24/7/24	9:30 am	12:0000
Customer Remark				
	Completed		Pendin	ia.
0. 00'.0	Completed	- Aureland	Pendin	9
Bridges. Not working. AHP	Arek On nuonna	13.00	Pendin	g
Browns Not working AMP  Browns Not working AMP  Service Engineer Name: Nasual	And Carlone	r Name :		g
Service Engineer Name: Nasual Signature: Nau	Custome Signature Date	r Name:	Morre	
Service Engineer Name : Nasua	Custome Signature	r Name:	1 Nogra	

# REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

### Recommendations for Beyond Economic Repair (BER)

### **PROFORMA**

SI. No	Particulars	Details				
1	Name of District	ALAPPUZHA				
2	Name of Hospital	THQH CHERTHALA  ICU COT MAKE :-JANAK HEALTHCARE (P) .LTD MODEL :- ACP EX 6000 SN :- X6A317050068				
3	Name of Equipment with Make, Model and Serial Number					
4	Equipment ID & Barcode	118274 & 0420258				
5	Date of purchase / Year of manufacture /Installation Date	22/04/2017				
6	Warranty details (Yes/No)	NO WARRANTY				
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC				
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	20/06/2024				
9	Action taken	On checking found Control Junction box is defective. Enquired spare with the OEM				
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged				
11	Recommendations for repair (required service details)	Not Recommended For Repair				
12	Cost of spares (specify parts and cost)	NA (Obsolete Model)				

13	Asset Value	RS :- 101772 /-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service Report and OEM EOL letter attached
16	Reasons for recommending the equipment as BER	On checking found Control Junction box is defective. Enquired spare with the OEM. This model is obsolete and Spare is not available. The machine was installed on 22/04/2017 and aged up to 7+ years. The OEM declared end of life in this model. So we are recommending the equipment for condemnation as per the tender clause 5.3.14.2
17	Name & Signature of CYRIX Authority	NASEEF K N

\*Not mandatory #Based on the period of life and value as per the BER guidelines

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

The world is 7+ Years old, Octor discontinued spares of models more than 10 years. Other who recome add to yograde the with to Linax to And System.

Signature of JC BM (NHM)

Date Signature of Superintendent / Medical Cherthal

Consultant (Biomedical Engineering)
NHM ALAPPUZHA

<sup>\*</sup> Attach Photograph








AMPILY.T

Buduroof: S.

010161-688°

SUPERINTENDENT SUPERINTENDENT SALUK HEAD QUARTERS HOSPITAL CHERTHALA

1			REGIS	TER	1.18	3	
	IRON COT		(0)	an antonima nem			
1	Received from	Inv. No.	Rate	Receipts	Issues	Balance	Remarks
pate	issued to	Issue	Rs. P	S.	The second	La	
خالياه	Edom Kusel -	2112-1		-0		02	
-	thataga Wodel	THE RESERVE OF THE PARTY OF THE	213423 -	- 08	1	1000	
	Ex Case Plas Pulls				1		<b>建筑</b>
The second second	watars ex samply				1		
	Woke fourt			7365			
The state of the s	Healthcorr. ONF.					371.46	
BE SEAL OF THE PARTY OF THE PAR	Rocerd and make			444	- N	1	
The second second second second	U3/0/6/ 002 /4/12		•	19.58	1	200	
-	18800 FO CO.	Wall to	Have	1 8/11-	- 0	3 00	7
E14172	Maysom for	and some of	1.85	M.UKR	1	10/	
	contificate als	00	The read	(22)	Reco	Miles -	A8 41 118
-	1880g	The second control of				15 48	
	18800	Section 1997 Section 1997	To the second se				
1	Figure 12 Avenue	MATERIAL MATERIAL AND	10/0	to po	geNo	-137	-
	F.	o with A	elet R	gister	Vo	· <u></u>	2 13
	<del></del>	VII					
7		1					
							-
							1
	4						
				1	11		
			-	6			



Abhilash A <abhilashacyrix@gmail.com>

## Quotation for the Midmark Janak service spares / Cyrix

2 messages

Amicis Medica <amicismedicatcr@gmail.com>
To: Abhilash A <abhilashacyrix@gmail.com>

Thu, Jul 4, 2024 at 3:33 PM

Dear Sir,

Please refer to the attached quotation and kindly issue the po along with the advance payment for the supply of spares.

With Regards,

#### Reenu Xavier

Service Coordinator 9495830122

Email: amicismedicatcr@gmail.com Web: www.amicismedica.com

#### **Amicis Medica**

Capital Tower, 1st Floor, VIII 568 A/7, Kuttanellur, Thrissur, Kerala 680014



Quote Ref. 070012024 Cyrix Spare1.pdf 145K

Amicis Medica <amicismedicatcr@gmail.com>
To: Abhilash A <abhilashacyrix@gmail.com>
Cc: Rejithlal Syamlal <rsyamlal@midmark.com>

Tue, Jul 9, 2024 at 12:43 PM

Dear Sir.

We have received your request for Control junction box of EX6000 ICU Cot. This is to inform you that, old model bed spares more than 10 years are discontinued and the only possible way is to upgrade to the new model LINAK system.


As this is a special case, we are offering discounted rates for upgrading the electronic spare parts to updated technology by replacing the combo of control box, remote and wiring kits.

Please refer to the attached quotation and kindly issue the po along with the advance payment for the supply of spare parts and service.

With Regards,

Reenu Xavier Service Coordinator 9495830122 Email: amicismedicator@gmail.com Web: www.amicismedica.com

Amicis Medica Capital Tower, 1st Floor, VIII 568 A/7, Kuttanellur, Thrissur, Kerala 680014



### Abhilash A <abhilashacyrix@gmail.com>

## Quotation for the Midmark Janak service spares / Cyrix

Amicis Medica <amicismedicatcr@gmail.com>
To: Abhilash A <abhilashacyrix@gmail.com>
Cc: Rejithlal Syamlal <rsyamlal@midmark.com>

Fri, Aug 16, 2024 at 3:51 PM

Dear Sir.

We have received your request for a Control box for EX6000 ICU Cot.

This is to inform you that, as part of upgrading, the LINAK control system has changed their entire system to the most modern technology. So the old model bed's controls system has been discontinued and the only possible way is to upgrade to the new model LINAK system. It shall be compatible with future connectivity systems.

As a special case, we are offering 50% discounted rates to upgrade the old technology by replacing the combo of control box, remote and wiring kits with advanced technology as recommended by LINAK .

Please refer to the attached quotation and kindly issue the po along with the advance payment for the supply of spare parts and service.

With Regards,

Reenu Xavier

Service Coordinator 9495830122

Email: amicismedicator@gmail.com Web: www.amicismedica.com

Amicis Medica

Capital Tower, 1st Floor, VIII 568 A/7, Kuttanellur, Thrissur, Kerala 680014

[Quoted text hidden]

Quote Ref. 070012024 Cyrix Spare1.pdf



To

CYRIX HEALTHCARE PVT. LTD., FIRST FLOOR, PETTA JUNCTION 30/641B POONITHURA, ERNAKULAM-682038, INDIA, sales.kl2@cyrix.in, abhilashacyrix@gmail.com GST No.: 32AAFCC2499H2ZM

Kind Attn: Mr. Abhilash

Subject: Quotation for the Midmark Janak Service Spares

Dear Sir/Madam

This refers to the service and spare request at your hospital and accordingly we enclose our offer for spare.

SI. No.	Product	Item Code	Spares Description	List unit Price	QTY	Amount	GST	Total Price
1	ICU Cot	MI7721043	Upgradation Kit for EX6005/EX5500 series (for service)	19,897.00	01	19,897.00	18%	23,478.00

COST OF Service: Service charges for one product will be Rs.1,500.00/- (Exclusive of 18% GST)

VALIDITY OF CONTRACT: This contract shall be force for a period of ONE YEAR commencing from 1st January 2024

#### REPLACEMENT OF PARTS:

A) Item codes are subjected to change according to the spare up-gradation.

B) Company reserves the right to discontinue any spare part considering the discontinuation of a manufacturing process or products or products parts.

C) There will be no warranty on spares (as per standard practice prevailing in the industry. However, any inherent defects due to poor material and workmanship brought to our notice immediately after carrying out the job will be considered suitably.

A. Prevailing GST Tax Structure additional on unit rate. 18% on Spare parts.

- B. Offered prices include packing and installation and exclude any prevailing local entry/statutory tax which are in the customer's scope.
- C. Offered prices Excluded freight charges.
- D. Offered prices Excluded unloading charges.
- E. In an event of an introduction of any new duty and levy by Government or any change in the statutory levies during the tenure of the contract/delivery of material or in the forthcoming budget, the same shall be apply to this offer which will be in customer's scope. Taxes applicable as actual at the time of Invoicing.
- F. In case, where the unloading is in Midmark (India)'s scope, the material will be unloaded at a single designated location at the consignee address. Any relocation thereafter will be in customer's scope and Midmark (India) can provide supervision.
- PAYMENT: 100% Advance for spare part and for service after invoicing.
- 3. DELIVERY: Within 6-8 weeks from the date of purchase order & receipt of payment along with the product colour confirmation, wherever applicable. In case of any change in delivery terms, the same should be agreed by both the parties.
- 4. PRICE VALIDITY: 30 days from date of quotation/proforma invoice. Any extension to the validity is subject to a prior written confirmation by Midmark (India).

We hope that the above offer is in line with your requirement and kindly award us with your valuable order.

Yours Truly, Ms. Reenu Xavier +91 9495830122

Service Coordinator Amicis Medica

Account Name: Amicis Medica Bank Name: Catholic Syrian Bank Bank A/C: 005503974955195001 Bank IFSC: CSBK0000055

1st Floor, VIII/568 A/7 Capital Tower, Kuttanellur - 680014 Thrissur, Kerala, India Ouote Ref. 07/001/2024

Date: 04.07.2024