

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



DDOVIDED

No. :

Tender No. WO-37/2021-2022/698	CAREPVI	LTD	232337	
ISO 13485 : 2012 & ISO 9001-2008 CERT 30/64 1 B, Petta Junction, Ph : 98472 99500 Website : ww	IFIED COMPANY	AERB Approved Se	rvice Agency ala cyrix.in	
Health Facility PHC Uzhamalakkal Address TaiVandhum Keaala Ph: 98472 99500 Website: www	Call Regist Caller ID: Date of Vis Asset No.: EQPT Nam Manufactur	ration Date:	2024 Sippette Model:	na.
Service Classification : Breakdown Call	PMS 🗌	Calibratio	n Cust.	Training 🗌
Problem Identified:	et ruostii	1g		
Action Taken: Checked and It is ones solating identifie soloting humbes sing, need to seplace the Checking and westing Completed Date: 25,07,124. Time:	el Ind rotaling hese condition	the gears Sparts	octating are don los hi he equi	key, naged
Spare Replaced Requested				· _ & .
Description	Qty.	Part Nur	nber	PR Number
	The second second			
3.			200	
Cyrix Engineer		Date	Start Time	End Time
midhun. BM		25 97/24	9.30Am	10 100 AM
Customer Remark	Completed		Pendin	g

Service Engineer Name:

midlun. BM

Customer Name:

in Dupany

Signature:

25/07/24

Contact Number:

9074167987

ज्ञानिश्व 1326976 wit

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

<u>PROFORMA</u>

SI. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	PHC UZHAMALAKKAL
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : Microippette Make : Dr.Pette Model : NA Serial No : NA
4	Equipment ID/ Barcode	124040/0145025
5	Date of purchase/ Year of manufacture/Installation Date	30/04/2019
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No CAMC/AMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	19/07/2024
9	Action taken	Checked and found that the number barrel is over rotating. Identified that the rotating key, rotating number ring, rotating gears are
		damaged.Need to replace these sparts for further checking and working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDING FOR REPAIR
12	Cost of spares (specify parts and cost)	NOT AVAILABLE

13	Asset Value	662.7/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
10	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT AND CALIBRATION REPORT ATTACHED
16	Reasons for recommending the equipment as BER	Checked and found that the number barrel is over rotating, Identified that the rotating key, rotating number ring, rotating gears are damaged. The pipette was installed on 30/04/2019 and covered up to 5+ years. Since the spares are not available in the market. Recommending the unit for condemnation
17	Name & Signature of CYRIX Authority	MIDHUN BM

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Number læssel is over sotating per tender conditions this c

RBER.

MANEESHA MOHAN W.R. Junior Consultant (Biomedical) National Health Mission Thiruvananthapuram

23-08-2024 Signature of JC BM (NHM)

്റ്റഡിക്കൽ ആഫീസർ ഇൻചാർജ്ജ് കുടുംബാരോഗ്വ കേന്ദ്രം ୭ଜଅଗଲ ୍ଞ

Signature of Superintendent/Medical Officer (i/c)

Date:



CERTIFICATE OF CALIBRATION



TUV-SUD ISO 9001:2015/Intertek ISO 13485:2016

CUSTOMER NAME	FAMILY HEALTH CENTRE UZHAMALAKKAL		
ADDRESS	UZHAMALAKKAL, THIRUVANANTHAPURAM, KERALA 695542	DATE OF CALIBRATION	31/07/2024
CERTIFICATE NO:	NA	VALID UP TO	NA
	Service Control of the Control of th	DATE OF ISSUE	31/07/2024

San July 18	INS	INSTRUMENT DETAILS		
Instrument Name	MICRO PIPETTE	S.No.	NA	
Make / Model No.	MICO	Visual Inspection	OK	
LOCATION:	LAB	RANGE	5 - 50 µL	
	BA	AR CODE: 0145025	· · · · · · · · · · · · · · · · · · ·	

PROBLEM IDENTIFIED: NUMBER BARREL NOT PROPER

ACTION TAKEN:

The pipette is gone recalibration and it is found that the volume is not achieving properly. Even after adjusting the spring tension the volume not achieving correctly. It was found that the numbered barrel is over rotating. Because of this rotating key, rotating number ring, rotating gears are damaged. This part is not available in the market. So the above mentioned pipette is non-serviceable. Therefore, we recommend to decommission this Pipette.

The same of the sa	Business Consult and Property Consultation		proprietable services Englished Control Services	
CALIBRATION STATUS	PASS		FAIL	J
	And the first the world of the same for a supple from a first of	the state of the state of		in the second se

REMARKS:-

- This result of calibration refers to only to the particular items submitted for calibration.
- The above result is valid at the time of and under the stated conditions measurement.
- Calibration certificate issued for weight & measure parameters like mass, weighting balance, volumetric equipment, measuring scales/tapes etc. Are scientific purpose only and should not used for commercial.

Calibrated By

(CALIBRATION ENGINEER)



Cyrix Healthcare Pvt Ltd, 30/641B, Petta Junction, Poonithura, Ernakulam-682038 +91 974445552

calibration@cyrix.in

www.cyrixhealthcare.com

Approved By (TECHNICAL MANAGER)

മെസിക്കൽ ആഫീസർ ഇൻചാർജ് കുടുംബാരോത്വ കേന്ദ്രം ഉഴമലയ് ക്കൽ

			T	כ
	Micro pipette 10 Micro lilem	((iscad) &	8/w	
Lyvoia No .335		- Receipt	Frim) clean
	P			-
30 4 19	Record Jum Caenze Modicin			
	-deport KSWC building 11/61	Y		
	Cloudi, Shuri, Frualeeude			
	(cp sp. 6 c 2. 7/-/			
	12p. Dale. 12/2028. MRP. 2050			
	Balch 11. Pact 662.71-/-			
	hust 662.71-/-	1		1/
	UMW4 662. F-1-1-			1
			AME	
			9	
_(6 7 19	Freed to Leb batuicion			
	A			
4.	(Til -) no p. 30 0 Sheltele P	m.	1	
	-Character Land			
	Born Sty.		Andread State of the second	
	of the Oly	·		E 72
,			_	
			<u> </u>	
1000			A	
			_	
	ALTHCE			_
	THE COURT OF THE PARTY OF THE P			-
	(1)	1	and all algorithms	
	(BASS) 188	1000 S	ALIB.	Me El
	The same and the s	மாத்திர தாக்கும் இது	00	
	- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10	6,820 Bar age	- 10 mg/m	
(2) y				
4.36	Company of the Compan	3,112	***************************************	
Land State (





കുടും പ്രാവി കേരും പര്യാവി കേവ്രം