



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 234338

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

| | |
|--|--|
| <p>Health Facility <u>CHC</u></p> <p>Address <u>CHC Pathanapuram</u> <u>Kallam</u></p> <p>Ph : <u>7306404017</u></p> | <p>Call Registration Date : <u>29-07-24</u></p> <p>Caller ID : <u>126299</u></p> <p>Date of Visit : <u>30-07-24</u></p> <p>Asset No. : <u>0230514</u></p> <p>EQPT Name : <u>Stelizer</u></p> <p>Manufacture <u>Atlas</u> Model : <u>Vertical</u></p> <p>S. No. <u>HSN 9018</u> Dept. <u>Autoclave Room</u></p> |
|--|--|

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not heating, Door damaged

Action Taken : Checked and found that the stelizer while operating
blacked and door totally damaged the autoclave
chamber locknut and coil damaged, the stelizer
is unsafely to use in its maintainable condition, totally damaged
its installation done on 23-06-15, outlived 9 years. Month as per Mfg. date

Completed Date : 30-7-24 Time : 11:00 AM Spare Required


Spare Replaced Requested

| Description | Qty. | Part Number | PR Number |
|-------------|------|-------------|-----------|
| 1. | | | |
| 2. | | | |
| 3. | | | |

| | | | |
|--------------------|----------------|----------------|-----------------|
| Cyrux Engineer | Date | Start Time | End Time |
| <u>Sudhiraj. S</u> | <u>30-7-24</u> | <u>9:00 AM</u> | <u>11:00 AM</u> |

Customer Remark Completed Pending

| | |
|--|--|
| <p>Service Engineer Name : <u>Sudhiraj. S</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>30-7-24</u></p> <p>Contact Number : <u>9447621489</u></p> | <p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>30/7/24</u></p> <p>Contact Number : <u>7306404017</u></p> <p>Designation : <u>NO</u></p> <p>Hospital Seal :</p> |
|--|--|




Handwritten notes and signatures:
 Jax
 Thadeep
 MEDICAL OFFICER IN CHARGE
 HEALTH CARE QUARTERS
 PATHANAPURAM
 NO 7306404017


REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)


Recommendations for Beyond Economic Repair (BER)

PROFORMA

| Sl. No | Particulars | Details |
|--------|--|--|
| 1 | Name of District | KOLLAM |
| 2 | Name of Hospital | CHC PATHANAPURAM |
| 3 | Name of Equipment with Make, Model and Serial Number | Equipment : STERLIZER (vertical autoclave) Make: ATLAS SURGICALS Model: VERTICAL SN : HSN 9018 |
| 4 | Equipment ID & Barcode | Ticket id: 126299 / Barcode : 0230514 |
| 5 | Date of purchase / Year of manufacture / Installation Date | 23-06-2015 |
| 6 | Warranty details (Yes/No) | No warranty |
| 7 | *AMC/ CAMC Period agreed at the time of purchase | No AMC/CMC |
| 8 | Date of breakdown (Date of registration of complaint through email/ Toll free) | 29-07-2024 |
| 9 | Action taken | Checked and found that the sterilizer while operating blasted and door totally damaged the autoclave, chamber lock nuts & coil damaged |
| 10 | Present status of the equipment (Fully damaged / partially damaged) | Fully damaged |
| 11 | Recommendations for repair (required service details) | Not recommending for repair. |
| 12 | Cost of spares (specify parts and cost) | NA |




 MEDICAL OFFICER IN CHARGE
 HEAD QUARTERS HOSPITAL
 PATHANAPURAM


| | | |
|----|--|--|
| 13 | Asset Value | Rs .49491 |
| 14 | # Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value | NA |
| 15 | Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not) | Cyrix service report & images attached. |
| 16 | Reasons for recommending the equipment as BER | Checked and found that the sterilizer while operating blasted and door totally damaged the autoclave chamber lock nuts & coil damaged, the sterilizer is unsafety to use it's not in repairable condition totally damaged. Its installed on 23-06-2015 outlived 9 year 1+ month .so recommending to condemnation |
| 17 | Name & Signature of CYRIX Authority | SUDHIRAJ  |

*Not mandatory #Based on the period of life and value as per the BER guidelines


* Attach Photograph


Remarks and Recommendations of Consultant (Biomedical) NHM:

Autoclave fully damaged and old one.
Recommended for Beyond economic repair


23/08/24
Signature of JCBM (NHM)
NHM, KOLLAM

Date _____



Signature of 
Superintendent / Medical Officer (t/c)
MEDICAL OFFICER IN-CHARGE
TALUK HEAD QUARTERS HOSP.
PATHANAPURAM

Brought forward from *Agri Register Volume I*
Page NO: 1

53

Date
22/6/15




Stems
Sterilizer

| Ret | Balance | Total |
|-----|---------|-------|
| 1 | 2 | 3 |





vivo Y33s · Faja Faya Falz <3

MEDICAL
TALUK HEAD OFFICE
PATHANAMTHALAM HOSPITAL



[Signature]
MEDICAL OFFICER IN CHARGE
TALUK HEAD QUARTERS HOSPITAL
PATHANAPURAM




MEDICAL OFFICER IN-CHARGE
TALUK HEAD QUARTERS HOSPITAL
PATHANAMPARAM