



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 229926

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>DH Calankki</u></p> <p>Address <u>Cheruthoni</u> <u>Calankki</u></p> <p>Ph : <u>9447466081</u></p>	<p>Call Registration Date : <u>17/8/24</u></p> <p>Caller ID : <u>129963</u></p> <p>Date of Visit : <u>18/8/24</u></p> <p>Asset No. : <u>0610566</u></p> <p>EQPT Name : <u>Fetal doppler</u></p> <p>Manufacture <u>Bpi</u> Model : <u>0123</u></p> <p>S. No. <u>A27A6A5228</u> Dept. <u>L.R</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust. Training

Problem Identified :
Not working

Action Taken : Checked the Machine Found that the Main board and Probe defective. Need to replace the Spare for further checking working. Contacted of the Equipment. Enquired Spare with OEM.

Completed Date : 18/8/24 Time : 2:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Murali</u>	<u>18/8/24</u>	<u>1:00pm</u>	<u>2:00pm</u>

Customer Remark Completed Pending

Service Engineer Name : Muralikrishna ID

Signature : [Signature]

Date : 18/8/24

Contact Number : 9847798098

Customer Name : [Signature]


Signature : [Signature]

Date : 18/8/24

Contact Number : 9447466031

Designation : Nsg. officer GRI

Hospital Seal : [Seal]



PROFORMA
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Name of Hospital: DH IDUKKI	Name of District: IDUKKI
Name of Equipment: Fetal Doppler	Equipment ID & Barcode: id:129963 barcode:0610566
Make: BPL	Model:0123
Serial Number: AZTA8A5228	Warranty details: No Warranty
Date of purchase/ Year of manufacture/ Installation Date: 6/3/2014	Present status of the equipment: Fully damaged
Date of breakdown: 17-08-2024 (toll-free) (Date of registration of complaint through email/ Toll free)	*AMC/ CAMC Period agreed at the time of purchase: No CAMC/AMC

Action taken: Check and find that the mainboard, and probe are defective. Need to be replace this spares for further checking and working condition of the equipment. Enquired spare with OEM


Recommendations for repair (required service details) Not recommending for repair

Cost of spares (specify parts and cost): main board:2500/-
 Probe:1500/-
 Total:4000/-


Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: 72% Asset Value:5525/-

Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)
 The Cyrix service report and OEM quotation attached

Reasons for recommending the equipment as BER: Check and find that the mainboard, and probe are defective. The equipment was installed on 6/3/2014 and covered up to 10 + years. The repair cost of the equipment is 72%, and both criteria are met. So recommending the equipment for condemnation as per the tender clause 5.3.14.1.

Vijitha Arora 
 30/8/24
 Name & Signature of CYRIX Authority with date


Remarks of Junior Consultant (Biomedical) NHM:
*Repair cost of the machine is 72%
 Total working years 10.*


Consultant Biomedical Engineer
 National Health Mission
 Arogyakeralam
 Idukki, KS 103

 Signature of JCBM (NHM)

Recommended for BER (Yes/ No): *yes*

Date: *31/08/2024*

Date: _____
 Medical Officer (i/c)



Signature of Superintendent /

 SUPERINTENDENT
 DIST. HOSPITAL
 IDUKKI

REPAIRING COST FOR BPL FETAL DOPPLER

1 message

cloud99biotech@gmail.com <cloud99biotech@gmail.com>
To: JITHUABRAHAMCYRIX@gmail.com


Wed, Aug 26, 2024 at 11:50 AM

Dear Sir,

Please find the attached document below.

Thank you for doing business with us.

Thanks and regards.

 vyapar_print_28_08_2024_11_44_28.pdf
184K



9744473043 9744473243

cloud99biotech@gmail.com

T.K.M.C./XII-1353
Room No: 22
CS Golden Jubilee Complex
Baker Hill
Shastri Road
Kottayam

CLOUD99 BIOTECH

GSTIN: 32AMWPT5633Q1Z0
State: 32 - Kerala

MSME NO.: UDYAM-KL-07-0030714
DL NO.: KL/KTM/MD42/2023/000015

Estimate

Estimate For:

JITHU ABRAHAM

1ST FLOOR 30/641B CYRIX HEALTHCARE PVT LTD
KOCHI DHANUSHKODI ROAD POONITHURA

Contact No.: 6238655106

GSTIN Number: 32AAFCC2499H2ZM

State: 32-Kerala

Estimate No.: C99B-QTN-53

Date: 28/08/2024

Place of Supply: 32-Kerala

#	Item name	H5N/ SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	MAIN BOARD (MAIN BOARD)	8423	1	Nos	₹ 2,500.00	₹ 0.00 (0%)	₹ 2,500.00
2	PROBE FOR FETAL DOPPLER (PROBE FOR FETAL DOPPLER)	90189099	1	Nos	₹ 1,339.29	₹ 160.71 (12%)	₹ 1,500.00
Total			2			₹ 160.71	₹ 4,000.00

Pay To

Bank Name : UNION BANK OF INDIA, KOTTAYAM
Bank Account No. : 361201010035646
Bank IFSC code : UBIN0536121
Account holder's name : CLOUD99 BIOTECH

Sub Total	₹ 3,839.29
SGST@0%	₹ 0.00
CGST@0%	₹ 0.00
SGST@6%	₹ 80.36
CGST@6%	₹ 80.36
Total	₹ 4,000.00

Description

DISTRICT HOSPITAL, IDUKKI
EQUIPMENT: FETAL DOPPLER
MAKE: BPL
MODEL: 0123
SNO: AZT8A5228

Estimate Amount In Words

Four Thousand Rupees only



Terms And Conditions

Thanks for doing business with us!

For : CLOUD99 BIOTECH



Authorized Signatory



FOETAL HEART MONITOR (Doppler) (NIDDK)

193

	Recd	Issu	Tr to n/s	Balac	Sug.
23/1/04	Rd from store (Dopler) (Main Stock Reg Page No 91 & WINSI Vol I) RS/19800/	1		1	
	Tr in from Sub-stock Regd: Vol - 1 Page No - 109		Tr to Unsound-Book 39 (1) NIL		
6/3/14	Rd from store RS/-5525/- (Foetal Doppler) (BPL)	1		1	
					Conclorment as per Or No 01/225/2021-GRU MCDH) Supt dated 11/1/2022 - NIL
10/9/20	Received from store Main Stock Registers page (Nautabha) No: 125 vol - IV model No: 9018 (Kernel supply) 5824 RS/- -cube Advanced technologies.	1		2	(ke)
4/12/22	Transferred out to OT Sub-stock Reg. Vol II Page no. 109 (Nautabha)	1		1	



SUPERINTENDING
 DIST HOSPITAL
 CHIKMAGALUR