

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER

Tender No. WO-37/2021-2022/698



No: 1015898

100 40405 - 0040 8 ICO 0004 2008 CEI	PTIEIED CON	ADANY I AEDR Approved So	price Agency
ISO 13485 : 2012 & ISO 9001-2008 CEI Service Report 30/64 1 B, Petta Juncti Ph : 98472 99500 Website :	ion, Poonith	ura, Kochi- 682 038, Kerala om Email : bemp.kl@cyrix	
Health Facility. Guneral hospital Address. Mirmanan thapus Kecala Ph: 8590512545	Can Da As EC	all Registration Date: aller ID: /3 8 ate of Visit: 0 /1 0 6 8 QPT Name: Furnigation Date: anufacture Soley No. // A	116 110/24 110/24 3 ator Model: AD-51
Service Classification : Breakdown cal		AS Calibration	Cust. Training
Problem Identified: Found	that d su	the equip	ment is
ActionTaken: Cheeked completed: Cheeked construction of the equipment of the expectation of the expecta	gging r fuethe ment	setch. Not pain housing e cheeking and	e equipment cooling cooling Spare Required
Spare Replaced Requested	S1 84		
Description 1	Qty.	Part Number	PR Number
2 3.	- T	-	
Cyrix Engineer Southerpoor.	ENERAL HO	Date Start T	
Customer Remark	impleted [*)	Pending Continuence
Signature: 4 10 14	heapillin	Signature: Date:	u 10 24
Contact Number: \$90740 6244		Contact Number: Designation: Designation:	al limil 80 gen

PROFORMA RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER) BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP) Name of Hospital: GH THIRUVANANTHAPURAM Name of District: Thiruvananthapuram Name of Equipment: FUMIGATOR Equipment ID & Barcode: 138716 & 0110683 Make: AEROSOL Model: AD-5L

purchase: No AMC/CAMC (Date of registration of complaint through email/ Toll free) Action taken: Checked and found unit is not getting on. Identified that the Vaccum motor and fogging main housing defective. Needs to replace these spares for further checking and working condition of the equipment. Enquired spare from vendor.

Recommendations for repair (required service details): Not recommending for repair.

Cost of spares (specify parts and cost):

Serial Number: NA

Date of purchase/

- 1. Vaccum Motor 7048.49/-
- 2. Fogger Main Housing 3890.81/-Total = 10939.3/-

Year of manufacture/Installation Date: 24/03/2021

Date of breakdown: 04/10/2024 (Toll free)

Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: 113.8%

Asset Value: 9610.99/-

Warranty details: No Warranty

Present status of the equipment: Fully Damaged

*AMC/ CAMC Period agreed at the time of

Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Cyrix service report and vendor quotation attached.

Reasons for recommending the equipment as BER: Checked and found that the vaccum motor and fogger main housing defective. The equipment was installed on 24/03/2021 and aged up to 3+ years. The repair cost is 113.8%. As per the tender clause 5.3.14.1 both criteria met. So recommending the unit for condemnation.

> Kasyep.pv Name & Signature of CYRIX Authority with date

		0		
Remarks of Junior Consultant (Biomedical) NHM: Vaccum motor and Jegger main tender condition can be RBER	housing	défecture.	So as	per
Recommended for BER (Yes/No):			Λ	

Date: 16-10-2024

Junior Consultant National Health Missic Junior Colland Health In National Health Mational Health In National H

Date:

Date	Voucher No.	Receipts	Issucs	Balance	Initials of affectives :	
		Quantity	Quantity	Quantity	Initi	
Jul 21 2 1	Furugator.		: :/ -	1 1 1		
11421	Acrosol Disinger	, 1		and the suppression of the suppr	3.	
-	5 hif (35x40x82	(m)	, , , ,			- and
.,	5 Tag (3) 1000					
	I - 9610.99) National Ora	1 600	ALC MADO	panine !	cheme	(NHM
	National Ora	- we				4
		The second secon				
		-				
		and a second			. 1	
			1960	- 53.		
				April 1 in the particular of t		
	,		and the second second second second			
				and the second second second second second		-
·			* - 4:			
	• • • • • • • • • • • • • • • • • • • •	A hora management of the				
			The state of the s	and the same of th		
-	The second secon		and the second of the second o		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	out decisions have					
			and the second distribution and the second			
,			a second	and the second of the second of the second		
,						
	Angular to the contraction of the second second second to the second second second second second second second		, con entegrals interessed Accounts	,	Property of the Control	
	and the state of t					
			A STATE OF THE PARTY OF THE PAR	- promote de la companya de la compa		-1- 7
				The second secon		1)1
			GOVT, GENERA		1	YX
GPT.25/1	773/99/150x200/J.		Col	1000	Sup	erintender eral Hospit







REF: BEC/DHM/ 01/07-2024 16-07-2024

M/s. District Hospital Mavelikkara

Pricing details of accessories for ULV fogger

S.No	Description	Qty	Pricing INR (exc.GST)	GST	Total Price (inc.GST)
1	Fogger main housing	1.00	3297.30	18.00	3890.81
2	Vaccum motor	1.00	5973.30	18.00	7048.49
3	Tank	1.00	1898.10	18.00	2239.76
4	Spring wound timer	1.00	1979.30	18.00	2335.57

TERMS & CONDITIONS

Taxes: As shown above

Payment: 50% advance with PO, balance COD/bank transfer against delivery

Warranty: NOT APPLICABLE

Delivery: 6-8 weeks from date of submitted quote

With Regards

Authorized Signatory

Biomedical Engineering Company (BEC)

Bank details:

M/s. Biomedical Engineering Company


HDFC Bank, Kadavanthara Branch ,IFSC code HDFC0000295

A/c: 99999388878006



Superintendent General Hospital Thirmyananthapuram.

KERALA: 39/878 A2,YMJ Stadium Link Road,Opp.JN Stadium ,Palarivattom,Cochin-682025, Email: mail@bechealthcare.com.,Tel:04842887200 GST :32AAGFB1151K1ZV









Superintendent
General Hospital
Thruvananthapuram.