

**PROFORMA  
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)  
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

Name of Hospital: PHC ANDATHODE	Name of District: Thrissur
Name of Equipment: Oxygen Concentrator	Equipment ID & Barcode: #140624- 0840650
Make: Owgels oxy-med	Model: OM-501 (5 Lpm)
Serial Number: W20181102-229	Warranty details: No Warranty
Date of purchase/Year of manufacture/ Installation Date: Ticket master installation date Nil, As per Stock book installation date 26-12-2018	Present status of the equipment: Fully damaged
Date of breakdown: 15-10-2024	*AMC/ CAMC Period agreed
Date of registration of complaint through email/Toll free): Toll free	at the time of purchase: No AMC/CAMC

Action taken: Upon inspecting the machine, it was discovered that the compressor, sieve bed, pressure regulator and solenoid valve are faulty. Need to replace these spares for further checking of working condition of equipment.


Recommendations for repair (required service details): Not Recommending

Cost of spares (specify parts and cost): NA

#Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: NA	Asset Value: 26500/-
---	----------------------

Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Cyrix report and EOL letter attached.

Reasons for recommending the equipment as BER: Upon inspecting the machine, it was discovered that the compressor, sieve bed, pressure regulator and solenoid valve are faulty. Installation date as per hospital stock equipment received on 26-12-2018 and aged up to 5 years and 9 months. OEM informed that its an discontinued model repair and spare parts are no longer available, Obsolete letter issued. So As per tender clause 5.3.14.2 We recommending the equipment for condemnation.

  
**BIJO T JOY**  
 Name & Signature of CYRIX Authority with date

Remarks of Junior Consultant (Biomedical) NHM:  
*Machine fully damaged.*

Recommended for BER (Yes/ No): *Yes*


Date: *23/10/2024*

Date: *23/10/2024*

Seal

Signature of Superintendent / Medical Officer  


\*Not mandatory // Based on the period of life and value as per the BER guidelines

Signature of J.C. BM (NHM)  
 Jr. Consultant (Biomedical)  
 NHM, Thrissur  
  
**MEDICAL OFFICER**  
**F.H.C. ANDATHODE**  
**THRASSUR**



# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

No : 1017864

# CYRIX<sup>®</sup>

HEALTH CARE PVT LTD

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

## Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi- 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | Email : bemp.kl@cyrix.in

Health Facility..... <u>Phe</u>	Call Registration Date : <u>15/10/24</u>
Address..... <u>Andanode</u>	Caller ID : <u>140624</u>
<u>Thrikkur</u>	Date of Visit : <u>17/10/24</u>
Ph : <u>9846165538</u>	Asset No : <u>0840650</u>
	EQPT Name : <u>Oxygen Concentrator</u>
	Manufacture..... <u>N/A</u> Model : <u>N/A</u>
	S. No..... <u>N/A</u> Dept..... <u>Painy palliative</u>

Service Classification : Breakdown call  PMS  Calibration  Cust. Training

Problem Identified : equipment not going on

Action Taken : Upon inspecting the machine. It was discovered that the compressor, servo bed pressure regulators and solenoid valve are faulty. Need to replace these spares for further checking of working condition of equipment

Completed  Date : 17/10/24 Time : 4:00pm Spare Required

Spare Replaced  Requested


Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Christy</u>	<u>17/10/24</u>	<u>3:00pm</u>	<u>4:00pm</u>


Customer Remark Completed  Pending 1

Service Engineer Name : Christy  
 Signature: [Signature]  
 Date: 17/10/24  
 Contact Number: 628844347

Customer Name : Jul Jini Havan kuth.  
 Signature: [Signature]  
 Date: 17-10-24  
 Contact Number: 9846165538  
 Designation : Pharmacist LSGA



**MEDICAL OFFICER**  
**F.H.C. ANDATHODE**  
**THRISSUR**



**Obsolete Letter for Oxy-med Owgels Model (3 Lpm / 5 Lpm)**

**Dear valued customers,**

Medequip has discontinued support for the OXY-MED OWGELS 3Lpm and 5Lpm models, repair parts are no longer available for these models.



Please contact our OXY-MED Support staff or our Service team.

If you wish to exchange your old product with new updated Oxymed -Mini Product, Please contact our OXY-MED support staff or our service team. Should you have any commercial or product related questions please contact Mr. Jayakumar for Further Information

Thanks & Regards

Jayakumar  
Service Manager- India  
Mobile- +918795660006  
[Email-jayakumar@medequip.co.in](mailto:jayakumar@medequip.co.in)



