


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KASARGOD
2	Name of Hospital	TH PANATHADY
3	Name of Equipment with Make, Model and Serial Number	Name: - UPS Make: - APC Model: -SRC200 SN:- NA
4	Equipment ID & Barcode	95698, 1420471
5	Date of purchase / Year of manufacture /Installation Date	08/02/2017
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC
8	Date of breakdown(Date of registrationof complaint through email/ Toll free)	13/02/2024 (Toll free)
9	Action taken	Checked the machine and found that main board is defective. Enquired OEM for quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No Recommendation
12	Cost of spares (specify parts and cost)	Repair or replace of complaint APC ups with working factory refurbished PCB- ₹ 20060


13	Asset Value	₹ 11000
14	"Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	182.36%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report and OEM quotation attached.
16	Reasons for recommending the equipment as BER	Checked the machine, found machine main board defective. Machine installed on 08-02-2017 and aged up to 7+ years. Repairing cost of equipment is 182.36% with respect to asset value. Both criteria for RBER met. Considering the tender clause 5.3.14.1, We recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	VISHNU P 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked the machine and found problem with main board. Machine installed on 08/02/2017. Repair cost is 182.36% of asset value. OEM quotation attached. so recommending the equipment for BER as per BER guidelines.


 JUNIOR CONSULTANT
 Signature of IC Biomedical Engineering
 Kanyakulam (NHM)
 Kanyakulam

Date 16/3/24




MEDICAL OFFICER
 Kanyakulam Health Centre
 Superintendent / Medical Officer (i/c)
 Kanyakulam 671532



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 185939

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrilx.com | E-mail : bemp.kl@cyrilx.in

<p>Health Facility ... <u>Taluk Hospital</u></p> <p>Address ... <u>Panathady</u></p> <p style="padding-left: 40px;"><u>Kasaragod</u></p> <p>Ph : ... <u>7907176669</u></p>	<p>Call Registration Date : <u>13.02.2024</u></p> <p>Caller ID : ... <u>95698</u></p> <p>Date of Visit : ... <u>14.02.2024</u></p> <p>Asset No. : ... <u>1420471</u></p> <p>EQPT Name : <u>UPS</u></p> <p>Manufacture ... <u>APC</u></p> <p style="padding-left: 100px;">Model : <u>SRL300</u></p> <p>S. No. ... <u>NA</u></p> <p style="padding-left: 100px;">Dept. <u>Laboratory</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : No output voltage

Action Taken : Checked the machine and found that machine mainboard defective. need to replace the main board for further checking of the equipment.


Completed Date : 14.02.24 Time : 12.00pm

Spare Replaced Requested Spare Required

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrilx Engineer	Date	Start Time	End Time
<u>Abhinav. D</u>	<u>14.02.24</u>	<u>11.00AM</u>	<u>12.00PM</u>

Customer Remark Completed Pending



<p>Service Engineer Name : <u>Abhinav</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>14.02.2024</u></p> <p>Contact Number : <u>8948392989</u></p>	<p>Customer Name : <u>Abhishale</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>14/2/2024</u></p> <p>Contact Number : <u>8086392803</u></p> <p>Designation : <u>Lab technician</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
---	--

APC

YEMYEM Enterprises

1st Floor, Vinayaka Plaza, Nanthancode,
Trivandrum Ph: 2316669, 9447001118

Authorized Dealer and Service Provider for **American Power Conversion**

23-02-2024

To,

M/s CYRIX HEALTHCARE PVT LTD

UPS Location: Taluk Hospital, Panathady, Kasargod

Subject: Out Of Warranty Replacement offer for APC SRC2KUXI UPS.

Dear Sir,

We thank you for the confidence shown on us to provide power protection solutions for your new requirement.

We are the **High Power Partners & Authorized Service Providers** of APC (American Power Conversion).

Based on our discussions, please find our offer.

Commercial offer:-

Sl. No	Description	Rate	Qty	GST (18%)	Total
01	Repair or Replacement of Complaint APC SRC2KUXI UPS with working Factory Refurbished PCB (Eleven month warranty) Model : SRC2KUXI Sl. No : B21452000339 (Without Battery)	17,000	1	3,060	20,060/-
Total Amount (Including all GST)					20,060/-

Defective/Replaced product will be taken back to APC Stores

Terms and Conditions

Payment Terms : Full payment in Advance

Freight & Forwarding charges: Nil

Installation and Commissioning charges: Nil

Delivery : Minimum 30 Days from date of formal PO & Advance Payment from customer.

Warranty: As mentioned above

Validity : The Quoted prices are valid till 20-03-2024

Thanking you in anticipation of your valuable order

Assuring you our best services at all times



Contact Person


DEEPU

(9387546669/04712316669)

**Yours Faithfully
For YemYem Enterprises**







2
MEDICAL OFFICER
Community Health Centre
Panathady
PO Rajapuram-671532

FULLY AUTOMATIC BIOCHEMISTRY ANALYSER

Date	From whom received / To whom issued	Received	Issued	Balance	Rate	Sign
03/3/17	Received from Steno Fully Automated Random Access clinical chemistry Analyser Make : Transasia Model : LM 360 SL No : 60644 Service Eng. ph no. 9895001160. Installed on. 8/2/2017	01	-	01	10,00,810	118 Jee
	Water Treatment Plant (RO+MB Hybrid plant with 15,20 LPH + Disposable mixed bed Cartridge) Make : Aquakem. Model : ACI/RO+MB/359. SL No :	01		01		Jee
	Refrigerator. Voltas make : Voltas / Model: 320LSD Voltas. SL No : PUV 320K5002B	01		01		Jee
	UPS - 2KVA Make : APC Models SRC2KVXI SL No : B 21452000339 : Service ph no 9476203569. Battery 12V/20AH x 6 Nos. - 2 battery damaged & replaced make & Sunata / Amtron. Retail 150924 on 15/4/18 Stabilizer 4KVA V Guard Make : V Guard Model: VMB 400. SL no: Capacity 12A Input voltage - 230 V Single phase A.C 50/1/3	01		01	2,600/-	Jee
	2 nos Warranty					
	2 nos Status					

Fund - Ksd Package.

User ID - Guest
PW - Guest



Grant Total - 11,15,000/-
[defaulted batteries 2 nos are replaced & new one is provided in individual lab like]

MEDICAL OFFICER
Community Health Centre
Panathary
871533



Jayesh Krishnan <jayeshcyrix@gmail.com>

OOW Replacement offer for APC UPS

yemyenterprices apc <yemyemapc@gmail.com>
To: "jayeshcyrix@gmail.com" <jayeshcyrix@gmail.com>

Fri, Feb 23, 2024 at 12:47 PM

Sir,
Please find the attached OOW replacement offer for APC SRC2KUXI 2KVA UPS & Kindly do the needful...

With
thanks & regards,

Yem Yem Enterprises

Authorised Sales & Service Partner of APC by Schneider Electric

1st Floor, Vinayaka Plaza, Nanthancode, Kowdiar P.O., Trivandrum

Contact no.:- 0471-2316669, 9447001118

2 attachments

 **OOW Replacement offer for SRC2KUXI Cyrix (1).pdf**
304K

 **YemYem-Bank Details MAIN.pdf**
1080K