PROFORM RECOMMENDATION FOR BEYOND	ECONOMIC REPAIR (RBER)				
BIOMEDICAL EQUIPMENT MAINTE	` '				
Name of Hospital: CHC MUTTOM	Name of District: IDUKKI				
Name of Equipment: Micro Pipette	Equipment ID & Barcode: ID: 146765 Barcode: 0630670				
Make: LABOPEPPETE	Model: Na				
Serial Number: Na	Warranty details: No Warranty				
Date of purchase/ Year of manufacture/ Installation Date: 15/2/2008	Present status of the equipment: Fully damaged				
Date of breakdown: 14-11-2024 (toll-free) Date of registration of complaint through email/ Toll free)	*AMC/ CAMC Period agreed at the time of purchase: No CAMC/AMC				
Action taken: Checked and found that the piston was defective. In and the working condition of the equipment.	This spare needs to be replaced for further checking				
Recommendations for repair (required service details) Not recon	nmended for repair				
Cost of spares (specify parts and cost): Na					
Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: Na	Asset Value: 2500/-				
Abstract of Service Report provided by the OEM/ Authorized Se The Cyrix service report and calibration report are attached	rvice Provider/ CYRIX (Attached or Not)				
Reasons for recommending the equipment as BER: Checked and to be replaced for further checking and the working condition of 15/2/2008 and covered up to 16 + years. The quotation was not so, recommending for RBER	the equipment. The equipment was installed on				
	Name & Signature of CYRIX Authority with date				
Remarks of Junior Consultant (Biomedical) NHM: * Spane	and and the aut attacked				
Remarks of Junior Consultant (Biomedical) NHM: # Spare Installation date as stock rege & year of working and % of spare a	stagles well RBER conteres Consultant Biomedical English				
Recommended for BER (Yes/No): yes	National Health Mission Arogyakeralam				
Date: 29/11/24.	Signature of JC BM (NHM)				
Date: Seal Officer (i/c)	Signature of Superintendent / Medical				



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



മെഡിക്കൽ ആഫീസ്റ്റ് നൻ ചാമം സാമുഹിക ആരോഗ്യക്യേദ് മുട്ടം, തൊടുപുഴ

SERVICE PROVIDER

Tender No. WO-37/2021-2022/698



No: 1018624

C . D			proved Service Ag	ono,
Service Report 30/64 1 B, Petta Ph : 98472 99500 W	a Junction, Poonithu ebsite :www.cyrix.c	ıra, Kochi- 682 03 om Email : bem	88, Kerala p.kl@cyrix.in	Editor and
Health Facility	Ca	ller ID:te of Visit:/	0ate: 15/11/0 146765 5/11/2025 0630670	2 *************************************
Ph: 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4	/ <i>7070</i> Ma		N. O. O. P.	PHE NIII LAY
Service Classification : Breakdov	wn call PN	IS Calibra	ation Cust.	Training
Problem Identified :	notwo	OCHING	n se slovenski - 15	
Completed Date: 5/11/00	13/	114 -0	and the second section of the second section and the second of	
Completed Date :.!\(\omega.\lambda \lambda \lambda \lambda \lambda \text{Date} \)	<u>9.7</u> Time :	11am	Spare	Required 🗌
Spare Replaced Requested	of Journal of the same	es i esperimento de la composição de la	ti mentingan da dipiti da	HE PROSE THIS
Spare Replaced Requested Description	Qty.	Part Nu	mber	PR Number
Spare Replaced Requested	of Journal of the same	es i esperimento de la composição de la	ti mentingan da dipiti da	PR Number
Spare Replaced Requested Description	of Journal of the same	es i esperimento de la composição de la	mber	PR Number
Spare Replaced Requested Description	Qty.	Part Nu	mber Start Time	PR Number
Spare Replaced Requested Description Cyrix Engineer Customer Remark	Completed Completed	Date Date Customer Na Signature: Date: Contact Num	Start Time	PR Numbe End Time // CM) ng Le. KS. 4



An ISO/IEC- 17025:2017 / ACCREDITED BY NABL/ AERB CERTIFIED QA AGENCY/TUY-SUD ISO 9001:2015



CERTIFICATE OF CALIBRATION

CUSTOMER NAME	COMMUNITY HEALTH CENTRE MUTTOM				
ADDRESS	MUTTOM, IDUKKI, KERALA 685587	DATE OF CALIBRATION	20/11/2024		
CERTIFICATE NO:	NA	VALID UP TO	NA		
		DATE OF ISSUE	21/11/2024		

PIPETTE S.No.	21 - 30480
	Z1 - 3U4XU
PETTE Visual Inspection	OK
AB RANGE	10 – 100 μL
	Visual Inspection

PROBLEM IDENTIFIED: VOLUME VARIATION

ACTION TAKEN:

The pipette is gone recalibration and it is found that the volume is not achieving properly. Even after adjusting the spring tension the volume not achieving correctly. It was found that the piston is damaged due to wear and tear. This part is not available in the market. So above mentioned pipette is currently non serviceable

CALIBRATION STATUS PASS	FAIL J
-------------------------	---------------

REMARKS:-

- This result of calibration refers to only to the particular items submitted for calibration.
- The above result is valid at the time of and under the stated conditions measurement.
- Calibration certificate issued for weight & measure parameters like mass, weighting balance, volumetric equipment, measuring scales/tapes etc. Are scientific purpose only and should not used for commercial.

Calibrated By

(CALIBRATION ENGINEER)

Approved By

(TECHNICAL MANAGER)
PREJITH T B



Cyrix Healthcare Pvt Ltd, 30/641B, Petta Junction, Poonithura, Ernakulam-682038

+91 97445 55622

calibrationcyrix@gmail.com

www.cyrixhealthcare.com



Stock Register

146 Name MICRO PIPETTE 10 MM

Date	Received from or Issued to	Inv. No. or Issue	Rato . Rs.	Ps.	Receipts	Issues	Bal:	Remarks
			14.4				i marin	
15/2/0	· MICROPIPETTE	2604	2000 -	بن.	<u> </u>		1	
	Plemics Chemical	**					<u>.</u>	
			٠.					2.1
	3							mers
	4.			420	modern	d to	Æq.	inprient
			e Page		11 '			P5-12-39
						٥	on 1/2	15
				-				
						*		
	200 - 40 1				- 40	10°1	e is the succession	
	MICRO PIPETTE	J.	भारति		Muma	THE TO SE		
····· <u>·</u>					a Provide a suga		, A .	
	teansferred	from 6	Tock	300	k I	Paye	NO E	5
5 No							01	
	Change to	100 N. P	xed	عالم	ma		10.	
				1	* . 1	tan	servic	261
		Chen	100 Ja	Py	ed y	ומליים ול	3-1)	
	teans	errich of	RAN	2	mert	8700	c Re	Fil
			γ	1		α		וארניי
				1.		امردا	w 4. 4	
					- 7	80)W	··/
				1,2,1,11			TC	
						11 1	OF	1022
				-0520		/J.y		
				المون	18/10	(D).		Talling Fr
			200		Maria de la companya della companya	**************************************	Confluence A	Dulantas
			* 100			ନିଥିଲେ ସୁଲେ	HUNO GOG	234738
				છો હત્વ	03	(10)	Ø130.	29 1778 9 20 18 20 18 18 18 18 18 18 18 18 18 18 18 18 18
į.		•••••••••••••••••••••••••••••••••••••••		·••••		••••••		The state of
		•••••••••••••••••••••••••••••••	***************************************		•••••	*****************	<mark>.</mark>	
	Complete the second of the sec		A 5		20 EV EV		- s.	·