

**PROFORMA  
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)  
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

Name of Hospital: PHC PATTITHARA	Name of District: PALAKKAD
Name of Equipment: STERILIZER	Equipment ID & Barcode: #148823-0943471
Make: NA	Model: NA
Serial Number: NA	Warranty details: No Warranty
Date of purchase/Year of manufacture/ Installation Date: In ticket master installation date - NIL, As per sock 07/05/2016 (stock book attached for reference)	Present status of the equipment: Fully damaged
Date of breakdown: 25/11/2024 Date of registration of complaint through email/Toll free: Toll free	*AMC/ CAMC Period agreed at the time of purchase: No AMC/CAMC
Action taken: Checked the machine and found sterilization test is not passing while checking of signo lock. Problem with silicon gasket, pressure gauge, relief valve and weak coil condition. So need to be replace these spare for further checking working condition of machine.	


Recommendations for repair (required service details): No recommendations

<b>Cost of spares (specify parts and cost):</b> Pressure gauge = 1800/- Door lock knobs = 800/- Door gasket silicon = 2800/- Safety valve = 1300/-	Heater coil element = 1900/- Relief valve = 1100/- <b>Total = 9700/-</b>
--	--


#Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: 64.66%	Asset Value: 15000/-
---	----------------------



Abstract of Service Report provided by the OEM/Authorized Service Provider/CYRIX (Attached or Not): Cyrix Service report attached and quotation attached.

Reasons for recommending the equipment as BER: Checked the machine and found sterilization test is not passing while checking of signo lock. Problem with silicon gasket, pressure gauge, relief valve and weak coil condition. So need to be replace these spare for further checking working condition of machine. As per stock book Equipment installed on 07/05/2016 aged up to 8 years 6 months. Repairing cost is 64.66% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending for condemnation.

AKHILESH P.   
Name & Signature of CYRIX Authority with date

Remarks of Junior Consultant (Biomedical) NHM:  
 Machine installed on 7/05/2016 and aged up to 8 years 6 months. Repairing cost is 64.66% of asset value. Both criteria of RBER met.

Recommended for BER (Yes/ No): <i>Yes</i>	 Signature of JCBM (NHM) Palakkad NHM (Arogyakeralam), Palakkad
Date: <i>11/12/24</i>	

 Date: _____ Seal	 Signature of Superintendent/Medical Officer (i/c)
---	--





# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

No : 132704

# CYRIX<sup>®</sup>

HEALTH CARE PVT LTD

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi- 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | Email : bemp.kl@cyrix.in

Health Facility..... <u>PHE Pottithura</u> Address..... <u>Palakkad.</u> Ph:..... <u>9946300204</u>	Call Registration Date : <u>25/11/24</u> Caller ID : <u>148823</u> Date of Visit : <u>26/11/24</u> Asset No : <u>0943471</u> EQPT Name : <u>Steriliser</u> Manufacture : <u>Na</u> Model : <u>Na</u> S.No..... <u>Na</u> Dept..... <u>OP</u>
---	--

Service Classification : Breakdown call  PMS  Calibration  Cust. Training

Problem Identified : Not working

Action Taken : checked the Equipment found that Sterilisation test is not passing while checking of Signo lock. Problem with Silicon gasket, Pressure gauge relief Valve and wear & tear coil condition. So need to be Replace these Spares for further checking working condition of machine

Completed  Date : 26/11/24 Time : 11:00AM Spare Required


Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			


Cyrix Engineer	Date	Start Time	End Time
<u>Teyas</u>	<u>26/11/24</u>	<u>10:00AM</u>	<u>11:00AM</u>

Customer Remark  Completed  Pending

Service Engineer Name : Teyas  
 Signature: Teyasath  
 Date: 26/11/24  
 Contact Number: 8848098422



Customer Name : Dr. Hanja. m.  
 Signature: [Signature]  
 Date: 26/11/2024  
 Contact Number: 9946300204  
 Designation : Medical officer I/C.  
 Hospital Seal





# **JAIGURU SALES & SERVICES**

The Team For Sterilization  
XIII/385, N.Paravur, Ernakulam, Kerala-683519

Ph: 8089960227  
Mob: 09447043821

To

Cyrix Health care Pvt. Ltd,Ernakulam

Ref: Qtn. /106/2024-25 Dated 04-12-2024

Sir,

**Sub: Vertical Autoclave Repair.**

We have inspected the vertical Autoclave and found that the chamber, gauges and electrical parts to be replaced and the cost of those spares are as follows.

1. Pressure Gauge @ 1,800/-
2. Door Lock Knobs @ 800/-
3. Door Gasket Silicon @ 2,800/-
4. Safety Valves @ 1,300/-
5. Heater Coil Elements @ 1,900/-
6. Relief Valve @ 1,100/-

**Total Rs. 9700/-**

Please go through the above rates and do the needful...

For Jaiguru Sales & Service

Proprietor  
Remesh Kumar



MEDICAL OFFICER  
HEALTH CENTRE  
KAD-679534

CSSD CONSULTANTS DESIGNERS EQUIPMENTS AND CONSUMABLE SUPPLIERS & SERVICE PROVIDERS FOR CSSD EQUIPMENTS  
STAINLESS STEEL PIPELINE, FURNITURE & SPECIAL PURPOSE MACHINERY FABRICATORS



---

**REQUIRED QUOTATION FOR AUTOCLAVE 0943471 # 148823 @ PHC PATTITHARA , PALAKKAD**

4 messages

---

**Akhilesh P** <akhileshcyrix@gmail.com>

Sat, 30 Nov, 2024 at 10:58 am

To: Jaiguru Sales & Service Kerala <Jssindiaster@gmail.com>

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>

Dear sir

Please share the price and stock availability of

1. Pressure Guage
2. Safty valve
3. Relief valve
4. Silicon gasket
5. Heating coil
6. Door lock kobe 8 nos

Deatils are furnished below

Hospital Name : PHC PATTITHARA

Equipment Name : AUTOCLAVE

Barcode : 0943471

Ticket Number : 148823

Thanks & Regards

AKHILESH P  
DISTRICT INCHARGE - PALAKKAD  
Bemp-Kerala  
Mobile : +91 7593847154  
Email : [akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)

CYRIX HEALTHCARE (P) LTD  
30/641B, Petta, Punithura  
Ernakulam- 682038  
[www.cyrixhealthcare.com](http://www.cyrixhealthcare.com)

---

**Akhilesh P** <akhileshcyrix@gmail.com>

Tue, 3 Dec, 2024 at 8:40 am

To: Jaiguru Sales & Service Kerala <Jssindiaster@gmail.com>

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Blesson Jose <Zm2.klbemp@cyrix.in>

Dear sir  
Please update.

Thanks & Regards

AKHILESH P  
DISTRICT INCHARGE - PALAKKAD  
Bemp-Kerala  
Mobile : +91 7593847154  
Email : [akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)

CYRIX HEALTHCARE (P) LTD  
30/641B, Petta, Punithura  
Ernakulam- 682038  
[www.cyrixhealthcare.com](http://www.cyrixhealthcare.com)

[Quoted text hidden]

---

**Akhilesh P** <[akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)>  
To: Jaiguru Sales & Service Kerala <[Jssindiaster@gmail.com](mailto:Jssindiaster@gmail.com)>  
Cc: DM Sarang-KLBEMP <[dm1.klbemp@cyrix.in](mailto:dm1.klbemp@cyrix.in)>, Blesson Jose <[Zm2.klbemp@cyrix.in](mailto:Zm2.klbemp@cyrix.in)>

Wed, 4 Dec, 2024 at 9:46 am

Dear sir  
Please update.

Thanks & Regards

AKHILESH P  
DISTRICT INCHARGE - PALAKKAD  
Bemp-Kerala  
Mobile : +91 7593847154  
Email : [akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)

CYRIX HEALTHCARE (P) LTD  
30/641B, Petta, Punithura  
Ernakulam- 682038  
[www.cyrixhealthcare.com](http://www.cyrixhealthcare.com)

[Quoted text hidden]

---

**Jaiguru Sales & Service Kerala** <[jssindiaster@gmail.com](mailto:jssindiaster@gmail.com)>  
To: Akhilesh P <[akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)>

Wed, 4 Dec, 2024 at 9:47 am

[Quoted text hidden]

--  
For Jaiguru Sales & Service  
Remesh Kumar  
Proprietor  
Jaiguru Sales & Service  
N.Paravur, Ernakulam, Kerala-India  
Ph: 8089960227 Mob: 09447043821







