

**PROFORMA
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

Name of Hospital: GH THRISSUR	Name of District: Thrissur
Name of Equipment: Defibrillator	Equipment ID & Barcode: #148997- 0850452
Make: SCHILLER	Model: CARDIO PLUS
Serial Number: A08A048	Warranty details: No Warranty
Date of purchase/Year of manufacture/ Installation Date: Ticket master installation date – 18-06-2008 As per the Stock book installation date-08-06-2008	Present status of the equipment: Fully damaged
Date of breakdown:26-11-2024 Date of registration of complaint through email/Toll free): Toll free	*AMC/ CAMC Period agreed at the time of purchase: No AMC/CAMC
Action taken: Upon inspecting the machine, it was discovered that the Main board, capacitor and SMPS board are faulty. Need to replace these spares for further checking working condition of equipment.	


Recommendations for repair (required service details): Not Recommending

Cost of spares (specify parts and cost): NA


#Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: NA	Asset Value: 100700/-
---	-----------------------


Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Cyrix report and EOL letter attached.

Reasons for recommending the equipment as BER: Upon inspecting the machine, it was discovered that the Main board, Capacitor and SMPS board are faulty. In Ticket master installation date is 16-06-2008, but As per the stock book, Installation date is 08-06-2008 (stock book attached for reference), Equipment aged up to 16 years and 5months. OEM schiller issued obsolete letter for the said machine and informed spares for replacement are not available. So in adherence to tender clause 5.3.14.2 We recommending the equipment for condemnation.


BIJO T JOY
 Name & Signature of CYRIX Authority with date

Remarks of Junior Consultant (Biomedical) NHM:
obsolete model, spares not available


 Jr. Consultant (Biomedical)
 NHM, Thrissur

Recommended for BER (Yes/ No): <i>yes</i>	 Signature of JC BM (NHM)
Date:	

Date:	 Seal GENERAL HOSPITAL THRISSUR - PIN: 680 001	 Signature of Superintendent / Medical Officer (i/c)
-------	--	---

*Not mandatory Based on the period of life and value as per the BER guidelines * Attach Photograph

15/12/24
SUPERINTENDENT (Dy. DHS)
GENERAL HOSPITAL
THRISSUR - PIN: 680 001



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

No : 1006933

CYRIX[®]

HEALTH CARE PVT LTD

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi- 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | Email : bemp.kl@cyrix.in

Health Facility..... <i>GH</i> Address..... <i>THRISSUR</i> Ph:..... <i>88995124</i>	Call Registration Date : <i>26/11/2024</i> Caller ID : <i>148997</i> Date of Visit : <i>27/11/2024</i> Asset No : <i>0850452</i> EQPT Name : <i>Defibrillator</i> Manufacture..... <i>Schiller</i> Model : <i>cardio plus</i> S. No..... <i>A09A044</i> Dept..... <i>or</i>
--	---

Service Classification : Breakdown call PMS Calibration Cust. Training

Problem Identified : *No. switching on*

Action Taken : *Machine checked and found main board, capacitor and smps board are defective. Need to replace these spares for further serv.*


Completed Date : Time : Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<i>Byo</i>	<i>27/11/2024</i>	<i>10:00am</i>	<i>11:00am</i>

Customer Remark Completed Pending

Service Engineer Name : <i>Byo</i> Signature: <i>[Signature]</i> Date: <i>27/11/2024</i> Contact Number: <i>9892187000</i>	 Customer Name : Signature: <i>[Signature]</i> Date: Contact Number: Designation : Hospital Seal
---	--

**SUPERINTENDENT (Dy.DHS)
GENERAL HOSPITAL
THRISSUR - PIN: 680 001**



Bijo T Joy <bijocyrix@gmail.com>

price enquiry - GH THRISSUR - 0850452 - 148997

6 messages

Bijo T Joy <bijocyrix@gmail.com>

4 December 2024 at 07:33

To: "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasecyrix2@gmail.com>

Dear sir,

There is a complaint reported from GH THRISSUR, Thrissur, Kerala, Regarding the complaint with Defibrillator ,Please share the price and availability of the **below mentioned spare** as soon as possible.

Equipment - Defibrillator

Make : Schiller

Model: CARDIO PLUS

Serial No: A08A048

quotation for -

1. Main board
2. Capasitor
- 3 . SMPS Board

Hospital- GH Thrissur

District - Thrissur

Barcode - 0850452

Caller id - 148997

With Regards,

BIJO T JOY**DISTRICT INCHARGE THRISSUR,
CYRIX HEATHCARE PRIVATE LIMITED**

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

Bijo T Joy <bijocyrix@gmail.com>

5 December 2024 at 07:09

To: "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasecyrix2@gmail.com>

reminder

With Regards,

BIJO T JOY**DISTRICT INCHARGE THRISSUR,
CYRIX HEATHCARE PRIVATE LIMITED**

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

[Quoted text hidden]

Kishore Kumar M.V. <kishorekumar@schillerindia.com>

5 December 2024 at 09:48

To: Bijo T Joy <bijocyrix@gmail.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasecyrix2@gmail.com>, "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Dear Mr.Bijo,

Please clarify is this blue colour cabinet or white colour cabinet;

Unit installed in 2009.

Please clarify so that only we can able to quote . If nay clarification please feel free to call

Regards,

M. V. Kishore Kumar

Asst.General Manager – CS (South)



Schiller Healthcare India Pvt. Ltd.

37/1013,II floor, Unidec house ,

Fathima church road,

Elamkulam, cochin.

9349257488 /9037835243

kishorekumar@schillerindia.com

<https://www.schillerindia.com/>

[Quoted text hidden]

Bijo T Joy <bijocyrix@gmail.com>

5 December 2024 at 11:46

To: "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasocyrix2@gmail.com>, "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

With Regards,


BIJO T JOY

DISTRICT INCHARGE THRISSUR,

CYRIX HEATHCARE PRIVATE LIMITED

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

[Quoted text hidden]



DEFIB.jpg
770K

Kishore Kumar M.V. <kishorekumar@schillerindia.com>

5 December 2024 at 14:21

To: Bijo T Joy <bijocyrix@gmail.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasocyrix2@gmail.com>, "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Dear Mr.Bijo,

This is more than 14 years old unit . currently the enquired spares are not available .

Its better go for Upgrading to new unit

Regards,

kishore

[Quoted text hidden]

Bijo T Joy <bijocyrix@gmail.com>

13 January 2025 at 15:56

To: "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Cc: Blesson Jose <zm2.klbemp@cyrix.in>, Anjitha T L <purchasecyrix2@gmail.com>, "Kishore Kumar M.V." <kishorekumar@schillerindia.com>

Dear sir,

kindly provide the end-of-life letter for this machine.

With Regards,

BIJO T JOY

DISTRICT INCHARGE THRISSUR,

CYRIX HEATHCARE PRIVATE LIMITED

30/641 B, Petta Junction | Poonithura | Kochi | Kerala-682038 Branches: Kerala | Karnataka || Tamil Nadu || Uttar Pradesh | Kuwait | Saudi Arabia M:-8921870010 | E:- bijocyrix@gmail.com | W:- www.cyrixhealthcare.com | "

[Quoted text hidden]

8/6/2008 Ed from stone (Volume 1.9. Main Page: 87)

classmate
Date _____
Page 9

0850452 DEFEBRILATOR

Ref Balance Sign

3/8/16 Trn from ICU

1 1

Received date 8/6/2008 (from ICU)

RS-100700

Schuller health care

SK 9-08 10098

(not responsible)

TR 4430 unscrupulous return

Page No. 2

8/9/2007 Trn from MICU


1 2

Philips start XL

Put in use


SI NO 00578715

28/01/2010



[Signature]

[Faint handwritten notes]



MU00AU040

MODEL	<input type="checkbox"/> E <input type="checkbox"/> ES <input type="checkbox"/> ER <input type="checkbox"/> ESN <input type="checkbox"/> ESNR
RATING	220-240-50Hz 200VA, Fuse 250V 2A fast blow
VER	AA

SCHILLER

HEALTHCARE INDIA PVT. LTD.,
NO 17, PONDY - VILLUPURAM ROAD,
BALAJI NAGAR, OULGARET,
PUDUCHERRY - 605 010.
TEL:0413-2291160 TELEFAX:0413-2292940

CYRIX
MEDICAL EQUIPMENT MAINTENANCE
PROGRAMME (BEMP)
MAR CODE: (8004-800415225)
08 50452

RBER
Ticket No: 102347
RBER approved on: 10/04/2019
Condemn on: 10/04/2019
Remark: 10/04/2019

CYRIX
HEALTHCARE INDIA PVT. LTD.
Puducherry

SL.NO	A08A048
MODEL	<input type="checkbox"/> E <input type="checkbox"/> ES <input type="checkbox"/> ER <input type="checkbox"/> ESN <input type="checkbox"/> ESNR
RATING	220-240-50Hz 200VA, Fuse 250V 2A fast blow
VER	AA

SCHILLER

HEALTHCARE INDIA PVT. LTD.,
NO 17, PONDY - VILLUPURAM ROAD,
BALAJI NAGAR, OULGARET,
PUDUCHERRY - 605 010.
TEL:0413-2291160 TELEFAX:0413-2292940

MEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)
CYRIX

GENERAL HOSPITAL
THRISSUR - PIN: 686001
20/11/2019